ARVAL
BNP PARIBAS GROUP

1XKV281

INSPECTION REPORT

End of contract


GENERAL INFO

File	322688
License plate	1XKV281
Vehicle identification number	WV2ZZZ7HZKH163274
Dossier	2019 148 131
Make	Volkswagen Multi.2.0TDi 150 Hi
Mileage	73160
First registration	28/01/2020
client availability date	25/09/2026
inspectionDate	29/09/2026










CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	




B
1-XKV-281

DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
41	Windshield // Replace	Y
72	Side View Mirror Left // Painting	Y
80	Door Front Left // Smart Repair Small	Y
113	Wing Rear Left // Painting	N
124	Light / Rear left / Replace	N
157	Rear Bonnet / Trim / Replace	N
161	Roof // Smart Repair Medium	N
166	Roof / Antenna / Replace	N
174	Light / Rear Right / Replace	N
214	Door Front Right // Repair & Painting	Y
321	Wheel Alloy Rear Left // Repair	Y
341	Wheel Alloy Front Right // Repair	N
532	Trunk Compartment / Side Cover Left / Replace	N
549	Interior / Headliner/ Replace	N
618	Front Left Door Interior Coating / Door Handle / Replace	Y
801	See External Expertise	Y
860	Interior Cleaning // Small	N
883	Key Price Range 2 //	N

Damage Pictures



Wheel Alloy Front Right // Repair-scratch




Bumper Front // Painting-scratch





Side View Mirror Left // Painting-scratch







Wheel Alloy Rear Left // Repair-scratch




Front Left Door Interior Coating / Door Handle / Replace-scratch

Roof // Smart Repair Medium-dent




Door Front Left // Smart Repair Small-dent




Rear Bonnet / Trim / Replace-scratch + dent





Door Front Right // Repair & Painting-scratch + dent




Wing Rear Left // Painting-bad repair






Light / Rear left / Replace-cracked






Light / Rear Right / Replace-cracked




Windshield // Replace-glass damage




Trunk Compartment / Side Cover Left / Replace-missing




Interior Cleaning // Small-stain




Roof / Antenna / Replace-worn




Interior / Headliner/ Replace-hole








See External Expertise-N comf / out of order