
· 1.0 TSI 95pk Comfortline · 21 October 2026



Specifications


Manufacturer	VOLKSWAGEN
Model	Polo
Model Versions	1.0 TSI 95pk Comfortline
Body Type	5 door hatchback
Color	Silver
Paint Type	Metallic
Production Year	2022
KW	70
Fuel Type	Gasoline
VIN	WVWZZZAWZNU046963

Cylinder Capacity	999 cm3
Transmission Type	Handmatig geschakelde transmissie5
MOT	22-06-2028
First Admission	22-06-2022
First Registration	22-06-2022
License Plate 1a Avilable	
VAT/Marge	BTW
Odometer	155.507 Km
Numer Of Keys	2
Interior	Darkgrey - Cloth
Number Headrests	5

Images

























Olieservice nodi
km/h

Accessories

ABS	Electric rear windows
Airbags	Electric windows front
Alloy wheels	Electrically adjustable & heated exterior mirrors
ASR	ESP
Audio System	Fog lights
Automatic air conditioning	Front & rear parking sensors
Bluetooth car kit	Leather steering wheel
Central door locking	Navigation system
Centre armrest	Rear view camera
Cruise control	Roller cover / parcel shelf
Dimming interior mirror	Steering wheel multifunction

Condition

Condition exterior	Adequate	Maintenance Remarks	De onderhouds indicator is actief
Condition interior	Adequate	Last maintenance odometer	123.380
Last Maintenance	03-03-2026	Previous Repairs	Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	7 mm	Vredestein	195 mm	55 mm	16 inch	All Season
Rear Left	7 mm	Vredestein	195 mm	55 mm	16 inch	All Season
Front Right	7 mm	Vredestein	195 mm	55 mm	16 inch	All Season
Rear Right	7 mm	Vredestein	195 mm	55 mm	16 inch	All Season
Spare Tire Type	Compressor					

Damages




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Interior	Damaged	Dakhemel gaatje	Cloth Repair	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Mirror - leftside	Dent(s)	Spiegelhuis vervormd	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Right	Small dent(s)	Acceptable	Yes




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Mirror - Rightside	Dent(s)	Spiegelkap & spiegelhuis vervormd	Replace	No




Damage Part	Damage Type	Repair Type	Acceptable
Alloy – Right Front	Small scratch(es)	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Front	Small scratch(es)	Acceptable	Yes