TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

# Expertise

Protocol number: 48205355
Order No. / Reference: 27053759
Inspection date: 19 Oct 2026

| Manufacturer: Audi | Model: A3 40 TFSI Sportback quattro S tronic S line |
|---|---|
| VIN: WAUZZZGY8PA143843 | |







## Vehicle details

| | |
|---|---|
| **Manufacturer / Type / Model / Equipment** | |
| Audi A3 40 TFSI Sportback quattro S tronic S line | |
| **Vehicle Identification number** | WAUZZZGY8PA143843 |
| **Mileage** (Read) | 60,420 km |
| **First registration** | 3 Jul 2023 |
| **Number of holders** | 1 |
| **Fuel type** | Petrol |
| **Engine displacement / Cylinder** | 1,984 ccm / 4 |
| **Power** | 140 kW |
| **Gearbox / Number of gears** | Automatic / 7 |
| **Type of drive** | All-wheel drive |
| **Type of vehicle** | Car hatchback |
| **Colour / colour code** | Mythosschwarz Metallic |
| **Doors / Seats** | 5 / 5 |
| **Upholstery type** | Cloth / leather combination |
| **Colour of upholstery** | Grey-Anthracite |

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

## Vehicle details

| | | | |
|---|---|---|---|
| **Maintenance booklet / proof** | digital proof / complete | **Next maintenance in** | 28,600 km |
| **Last service on / at** | 07/2026 at 59,350 km | | |
| **Key is / should be** | 2 / 2 | **FZG documents** | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
| | | **Letter No.** | GV241755 |
| **Previous damage / Accident** | Detectable | **Repainting** | Detectable |
| **Inspection conditions** | sufficient | **Lifting equipment / pit** | yes |
| **Test drive** | Not performed | **Engine function test** | Performed |
| **Manufacturer key number/ type code number** | 0588 / BXZ 00251 | | |
| **Emission standard** | EURO6 | **fine dust sticker** | |
| **Permitted total weight** | 2,000 kg | **Empty weight** | |

## Tyres

### Mounted tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 235/35 R19 91Y | Summer tyres on Light alloy | Continental | 5mm / 5mm |
| 2) | 235/35 R19 91Y | Summer tyres on Light alloy | Continental | 5mm / 5mm |

### Additional tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 205/50 R17 93H | Winter tyres on Light alloy | Goodyear | 6mm / 6mm |
| 2) | 205/50 R17 93H | Winter tyres on Light alloy | Goodyear | 6mm / 6mm |

### Replacement

| Typ | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| | Tirefit | Expiration date 04/2027 | | |

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**

## Equipment

### Standard equipment

- Airbag for driver and front passenger
- All-wheel drive "quattro"
- Anti-lock braking system (ABS)
- Audi connect emergency call & service m.connect remote & control
- Exterior mirror housings in body color
- Headliner in steel grey fabric
- Digital instrument cluster - fully digital instrument cluster in 10.25 inches
- Door sill trims with aluminum inlay at the front, illuminated, with S lettering
- Electronic Differential Lock (EDS)
- Chassis: Sport chassis
- Remote key (without Safe-Lock)
- Removable luggage compartment cover
- Transmission: S tronic 7-speed
- Interior lighting
- i-Size child seat attachment and top tether for the outer rear seats
- Front headrests
- Light and rain sensor
- Non-smoking version
- Wheel: Alloy wheels - 17 inch - 5-spoke
- Tire pressure monitoring system
- Headlight
- 3-point automatic seat belts
- Seats: Standard front seats
- Lane Departure Warning
- 12-volt power outlet in the rear
- Daytime running light
- Electronic immobilizer
- Airbag: Front side airbags with head airbag system and front interaction airbag
- Traction control ASR
- Audi pre sense front
- Electrically adjustable and heated exterior mirrors
- third brake light
- Roof edge spoiler S
- Tachometer
- Rear parking sensors
- Electric auxiliary air heater
- Electromechanical parking brake
- Electronic Stability Control (ESC)
- Electric windows front and rear
- front and rear floor mats
- Speed limiter
- rear window wiper
- Electrically operated child safety lock
- Manual air conditioning
- Rear headrests (3)
- Steering wheel: Leather steering wheel in 3-spoke design with multifunction and paddle shifters
- Otto particulate filter
- Radio: MMI Radio plus
- Tire repair kit
- Electromechanical power steering
- Seat covers in fabric
- Seats: Rear seat backrest foldable
- Start-stop system
- 12V socket
- Glazing: Green tinted thermal insulation glazing

## Extra equipment

- Electrically adjustable, heated and folding exterior mirrors, automatically dimming on both sides (with integrated LED turn signal and curb view function for the passenger-side exterior mirror - mirror glass left aspherical, right convex - including heated windshield washer nozzles)
- High-beam assist (within the system's limitations, it automatically detects oncoming headlights, taillights of other road users, and light sources in built-up areas. Depending on the traffic situation, the high beams are automatically switched on or off. The system thus improves the driver's visibility and increases comfort.)
- Interior mirror, automatically dimming, frameless
- Camera-based traffic sign recognition (Supports the driver by displaying traffic signs detected within the system's limits, such as speed limits, no-overtaking zones, and temporary speed restrictions, which are within the detection range of the front camera. The traffic sign recognition is displayed automatically in the digital instrument cluster or in the optional Audi virtual cockpit.)
- Steering wheel: Leather steering wheel in a 3-spoke design with multifunction plus and shift paddles (The steering wheel's height and reach are manually adjustable. For convenient operation of the extensive standard and optional infotainment features, the steering wheel is equipped with twelve multifunction buttons. Shift paddles allow manual gear changes.)
- S line interior package (S tronic) (front sport seats with manual adjustment of seat height, seat fore/aft position, seat tilt, backrest tilt and seat belt height, as well as headrests; fabric Puls/mono.pur 550-K synthetic leather; 3-spoke leather steering wheel with multifunction plus and shift paddles including leather steering wheel grips; front and rear door armrests in synthetic leather; aluminum spectrum dark decorative inlays; illuminated front door sill trims with aluminum inlays and S lettering; black fabric headliner; front center armrest; stainless steel floor mats, pedals and footrest)
- Reversing camera (captures the area behind the vehicle within the system limits. The display is adjusted according to the steering angle using dynamic display elements in the MMI touch display. The user can choose between perpendicular parking and trailer modes. Depending on the selected mode, the calculated driving lane or a guide line for coupling a trailer is displayed, also dependent on the steering angle. The reversing camera is activated by engaging reverse gear or via a button in the center console.)
- Telephone: Audi Phone Box (universal Bluetooth interface - convenient, integrated hands-free system - coupling antenna for connecting the mobile phone to the external antenna for improved reception quality - reduced radiation in the vehicle interior - LTE support - charging option via USB port or wireless charging (Qi standard) - forget-to-use warning - charging status indicator in the MMI touch display - connection of a second mobile phone)
- Glazing: Front window in acoustic glazing (heat-insulating glazing with improved acoustic insulation value of the front window)
- Deletion of model designation and performance/technology lettering
- Chassis: Sport chassis (Sport chassis with more dynamic spring and damper tuning and lowering by 15 mm, for more direct road contact and sportier handling.)
- Cruise control with preparation for adaptive cruise control (maintains the individually set speed between 20 and 250 km/h, provided the engine power allows. Operation is via a separate steering column stalk. The set speed is displayed in the digital instrument cluster. The system does not react to vehicles ahead with distance control. Includes adjustable speed limiter.)
- Paint finish: Metallic
- LED headlights and LED taillights with dynamic turn signals (daytime running lights, low beam, high beam, position lights, turn signals, cornering lights, all-weather lights (to reduce glare in poor visibility conditions), motorway lights, static cornering lights, maneuvering lights (illumination of the maneuvering area at the front and sides when reversing), automatic dynamic headlight range control, intersection lights (in conjunction with MMI Nav. plus), dynamic rear turn signals, brake lights, tail lights, rear license plate lights, reversing lights)
- Business package (USB ports with charging function in the rear - Audi connect Navigation & Infotainment plus - Audi phone box - Audi virtual cockpit plus - Smartphone interface (Android Auto and Apple CarPlay) - MMI Navigation plus with MMI touch - Cruise control)
- Black Optics Package (Includes: - black accents in the area of the Audi Singleframe grille - black accents in the area of the trim strips on the side windows - black accents in the area of the front and rear bumpers - black accents on the widened side sills (only with S line) - optional roof rails in black (only for Sportback))
- Wheel: Audi Sport light alloy wheels, 5-twin-spoke edge, anthracite black, gloss-turned (8.0 J x 19, tires 235/35 R 19)
- Seat covers in Puls fabric/mono.pur 550 synthetic leather combination with S embossing (center section of the front and both outer rear seats in Puls fabric - side bolsters, headrests, middle rear seat and front center armrest (if ordered) in mono.pur 550 synthetic leather - with rock grey contrast stitching and S embossing in the backrests of the front seats)
- Front seat heating (heats seat and backrest center section (standard seats in fabric), otherwise seat and backrest center section as well as seat side bolsters - individually adjustable in 3 stages for driver and front passenger via direct selection button on the climate control unit)
- Phone: LTE support for Audi phone box

- Glazing: Sun protection glazing, tinted (rear window, rear door and side windows tinted)
- Telephone: Smartphone interface in conjunction with MMI Navigation plus with MMI touch (The smartphone interface (Android Auto and Apple CarPlay) connects your smartphone to your Audi and seamlessly displays your smartphone content directly on the MMI display. Navigation, telephony, music, and selected third-party apps can be conveniently controlled via the MMI touch display and voice control. The connection can be established either using a suitable USB cable or wirelessly.)

## Brief expert findings

| | |
|---|---|
| Documents submitted | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection. |
| Inspection | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle. |
| Test drive | No test drive/shunting maneuver was carried out during the inspection of the vehicle. |
| Engine function test | An engine test run was performed. |

## Value reducing factors

| No. | Component group | Description |
|---|---|---|
| 1 | Front bumper | Air-inlet grille (Rechts, blende) - Paint defect - Replace |
| 2 | Side panel - rear left side | Sill - Scratch(es) - Smart repair |
| 3 | Door - rear left side | Door (Delle Geht über die Kante) - dent(s) - Paint |
| 4 | Front bumper | Front bumper - Scratched - Paint |

## Wear and tear

| No. | Component group | Description |
|---|---|---|
| 1 | Misc. | Main inspection - No evidence - No deduction |
| 2 | Bonnet | Bonnet - Stone chips - No deduction |
| 3 | Boot lid / rear door | Boot lid - dent(s) - No deduction |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Previous damages

| No. | Previous damage | Extent of damage (Net) |
|---|---|---|
| 1 | Rear, Side right, Provided by user / customer, from 25 Feb 2025 | 5.694,64 € |

## Repainting

| No. | Repainting |
|---|---|
| 1 | Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent |
| 2 | Door - rear right side, Professionally carried out, Invoice of repair done Non-existent |

## Paint coat thickness measurement

| | | | |
|---|---|---|---|
| Side panel - rear right side | 928 µm | Door - rear right side | 189 µm |

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  *(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  *(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

## Comments

- Der beiliegende Winterradsatz ist kein Bestandteil des
Auslieferungsumfangs.




**Figure 1:** Diagonal front (left)




**Figure 2:** Diagonal front (right)




**Figure 3:** Diagonal rear (left)




**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear




**Figure 7:** Instrument cluster



**Figure 8:** Instrument panel

**Figure 9:** Interior 360° view (Online Link)



**Figure 10:** Cargo area





**Figure 11:** VIN



**Figure 12:** Mounted tyres




**Figure 13:** Documents



**Figure 14:** Additional tyres





**Figure 15:** Navigation





**Figure 16:** Misc.




**Figure 17:** Misc.




**Figure 18:** Misc.



**Figure 19:** Misc.




**Figure 20:** Misc.



**Figure 21:** Misc.




**Figure 22:** Misc.




**Figure 23:** Misc.




**Figure 24:** Misc.



**Figure 25:** Misc.




**Figure 26:** Misc.




**Damage 1:** Front bumper: Air-inlet grille (Rechts, blende) - Paint defect - Replace




**Damage 1:** Front bumper: Air-inlet grille (Rechts, blende) - Paint defect - Replace




**Damage 2:** Side panel - rear left side: Sill - Scratch(es) - Smart repair




**Damage 2:** Side panel - rear left side: Sill - Scratch(es) - Smart repair



**Damage 3:** Door - rear left side: Door (Delle Geht über die Kante) - dent(s) - Paint




**Damage 3:** Door - rear left side: Door (Delle Geht über die Kante) - dent(s) - Paint




**Damage 4:** Front bumper: Front bumper - Scratched - Paint




**Damage 4:** Front bumper: Front bumper - Scratched - Paint



**Damage 4:** Front bumper: Front bumper - Scratched - Paint



**Damage 4:** Front bumper: Front bumper - Scratched - Paint



**Damage 4:** Front bumper: Front bumper - Scratched - Paint



**Damage 4:** Front bumper: Front bumper - Scratched - Paint




**Repainting 1:** Side panel - rear right side




**Repainting 2:** Door - rear right side