DEKRA

DEKRA Automotive Solutions


Condition Report

Vehicle details

VIN	WAUZZZGY3 TA042378	Mileage	19 381 km	Engine (Fuel) Type	Hybrid petrol
Licence Plate	2HTS141	Registration date	05/11/2025	Engine size	1498
Brand	AUDI	Fuel level	-	Transmission	Automatic
Model	A3Lim-8YS-2020	Car type	PC	Gears	-
Body Type	SUV CrossOver	Number of seats	-	Condition of the car	Unknown
Doors	5	Exterior Color	Gris		

Inspection Details

Inspection date	28/10/2026	Inspection loc.	AVIS Own Risk - Parc AVIS	Fleet owner	AVIS Own Risk Belgique




Other technical information

Refill emergency kit	✔
Rear parcel shelf	✔
Emergency compressor kit	✖

Tyres

Falken 225/45/17 Y Summer 6.0 mm

Falken 225/45/17 Y Summer 7.0 mm



Falken 225/45/17 Y Summer 6.0 mm



Falken 225/45/17 Y Summer 7.0 mm

Damages

1



Part	Alloy wheel 17"
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	165.00€

2



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	90.00€

3



Part	Alloy wheel 17"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	165.00€

4



Part	Tailgate / Boot door
Position	Back
Damages	Dented
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	49.00€

5



Part	Emergency compressor kit
Position	-
Damages	Missing
Severity	-
Repair mode	Replace
Net cost (Excluding VAT)	74.58€

6



Part	Alloy wheel 17"
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	165.00€

7



Part	Fabric seat
Position	Front left
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning
Net cost (Excluding VAT)	-

Summary Inspection

Net Price (Exclusing VAT)	708.58€