TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48414978
Order No. / Reference: 27170956
Inspection date: 21 Oct 2026

Manufacturer: Ford	Model: Transit Custom 320 L2H1 LKW VA Trend Kasten
VIN: WF0YXXTTGYNT02657	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Transit Custom 320 L2H1 LKW VA Trend Kasten	
Vehicle Identification number	WF0YXXTTGYNT02657
Mileage (Read)	50,849 km
First registration	26 Jul 2022
Number of holders	1
Next periodical technical inspection	11/2026
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,995 ccm / 4
Power	77 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Black Metallic
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite
Re-import	no
readiness to drive	Roadworthy

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Vehicle details

Maintenance booklet / proof	Non-existent	**Next maintenance in**	21 Tag(e)
Last service on / at	03/2026 at 43,212 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GK815733
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	8566 / BMT 03130		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,300 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 109T	All-season tyres on Steel rim with wheel cover	Goodyear	5mm / 5mm
2)	215/65 R16 109T	All-season tyres on Steel rim with wheel cover	Goodyear	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	215/65 R16 109T	All-season tyres on Steel	Goodyear	8 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 1 battery
- Anti-lock braking system with electronic brake force distribution (EBD)
- roof, flat
- Headliner in driver's cab - up to the partition wall to the cargo area
- Tachometer
- Third brake light
- Front electric windows - with quick-down/quick-up function for driver's side
- Ford Easy Fuel - Comfort fuel cap and misfuelling protection
- Warranty: 2-year Ford new car warranty including Ford Assistance mobility guarantee
- Generator, 240 A
- Cruise control system including imitation leather steering wheel with adjustable speed limiter
- Transmission: 6-speed transmission
- Interior lighting with delay function and front reading lights
- Fuel tank 70 l
- Cargo area lighting with activatable switch-off delay - after 30 minutes
- Emergency brake assist including emergency brake light
- Front and rear parking pilot system including fog lights
- Particulate filter: diesel particulate filter
- Wheel trims
- Wheels/Tires: Spare wheel, steel wheel
- Wheels: Steel wheels 6.5 J x 16 with 215/65 R 16 R tires - 6.5 J x 16 with 215/65 R 16 R tires
- Headlights: Halogen projector headlights with LED daytime running lights and fog lights with static cornering lights
- Mud flaps front and rear
- Half-height side wall cladding
- Seat belts - Front seat belt tensioners and force limiters - Warning system for unfastened driver's seat belt
- Lashing eyes 8
- Heat-insulating glazing, lightly tinted
- Auxiliary heater, electric
- Driver's side airbag
- Exterior mirrors, electrically adjustable and heated
- On-board computer with fuel consumption and mileage information (e.g. remaining range) and outside temperature display.
- Double-leaf rear door with 180° opening angle (without window)
- Electronic Stability Program (ESP) with Traction Control System (TCS) - Hill Start Assist - Crosswind Assist - Emergency Brake Assist - Rollover Protection
- FordPass Connect including live traffic information: Information about the current status or location of the vehicle, as well as control of selected vehicle functions via smartphone with the FordPass app. Real-time traffic information (in conjunction with audio systems 24 and 25). Further information about FordPass Connect can be found at https://www.ford.de/fordpass-connect.
- Lockable glove compartment with lid
- Front air conditioning including dust and pollen filter
- Paint finish: Solid color paint
- Cargo area floor: Vinyl floor covering, sealed, "Easy Clean"
- Steering column, adjustable in height and reach
- Package: Style Color Package - Front and rear bumpers and exterior mirror caps painted in body color
- Radio: Audio system 13 additionally with DAB/DAB+ - Radio (FM/AM) - Four speakers, antenna - Audio remote control on the steering wheel - Bluetooth, USB port and hands-free system - MyFord Dock - additionally with digital radio reception DAB/DAB+ (Digital Audio Broadcasting)
- Sliding door entry light automatically illuminates when the door is opened
- Sliding door: Sliding door, right
- Side protection strips
- Power steering
- Start-stop system
- Power outlet: 12-volt connection
- Immobiliser
- Central locking with remote control

Extra equipment

- Airbag (passenger side)
- Fixed towbar, 13-pin socket - incl. trailer stability control (TSC)
- Package: Visibility Package I (Trend) - Heated windshield - Windscreen washer fluid sensor
- Roof rack - integrated and foldable - max. roof load: 100 kg
- Second key, foldable, with remote control
- Theft alarm system
- Double-wing rear doors with a 90° opening angle (with window) - with heated rear windows
- Seats: Seat Package 13 - Partition (load-through flap) with window (Custom Truck Trend) - Driver's seat, 4-way adjustable (forward/backward, backrest, seat cushion tilt, height) - Double passenger seat with storage compartment under individually foldable seat cushions - Height-adjustable headrests - Integrated tray in the double passenger seat (fold-out) - Interior armrest for driver - Manual lumbar support (driver's seat) - TREND seat upholstery: fabric - Partition (load-through flap) with window

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Wing mirror - right side	Cap - Scratch(es) - Smart repair
2	Fuel system	Tank cap - Scratch(es) - Smart repair
3	Sliding door, right	Sliding door - dent(s) - Smooth repair work
4	Body	B-pillar - right side - Scratch(es) - Smart repair
5	Body	B-pillar - left side - Scratch(es) - Smart repair
6	Side panel - rear left side	Side panel - Dent / paintcoat damage - Smooth repair work
7	Front bumper	Front bumper - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Rear bumper	Rear bumper - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Navigation



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.






Figure 26: Misc.



Damage 1: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 1: Wing mirror - right side: Cap - Scratch(es) - Smart repair




Damage 1: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 2: Fuel system: Tank cap - Scratch(es) - Smart repair



Damage 2: Fuel system: Tank cap - Scratch(es) - Smart repair




Damage 3: Sliding door, right: Sliding door - dent(s) - Smooth repair work




Damage 3: Sliding door, right: Sliding door - dent(s) - Smooth repair work




Damage 4: Body: B-pillar - right side - Scratch(es) - Smart repair




Damage 4: Body: B-pillar - right side - Scratch(es) - Smart repair



Damage 4: Body: B-pillar - right side - Scratch(es) - Smart repair




Damage 5: Body: B-pillar - left side - Scratch(es) - Smart repair



Damage 5: Body: B-pillar - left side - Scratch(es) - Smart repair




Damage 6: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smooth repair work




Damage 6: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smooth repair work



Damage 6: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smooth repair work




Damage 6: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smooth repair work



Damage 6: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smooth repair work



Damage 6: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smooth repair work




Damage 7: Front bumper: Front bumper - Broken / torn - Replace



Damage 7: Front bumper: Front bumper - Broken / torn - Replace



Damage 7: Front bumper: Front bumper - Broken / torn - Replace



Wear and tear 1: Vehicle glazing: Windscreen - Stone chips - No deduction