BMW X2

Vehicle information



Brand:	**BMW**	License plate:	**2BJS009**
Gearbox:		Body color:	
Model:	**X2**	LEVEL:	**WBAYN910505U70497**
Fuel type:		Power:	**92 kW**
Version:	**1.5iA xDrive25e PHEV OPF**	First registration	**10/12/2021**
Mileage:	**101636 km**	Number of doors:	

Summary of damages





Back	1
RIGHT	2
LEFT	1
Interior	2
Roof & other	1



Commercial photos





















Equipment corresponding to the VIN according to the manufacturer's information


Center armrest	Airbag	Alarm	Rain sensor
Distance control	Battery current	Power steering	Electrical operation of windows
GPS	Alloy wheels	Electrically adjustable mirrors	Adjustable lumbar support
Phone	Central locking	Leather steering wheel	Multifunction steering wheel
Sports steering wheel			

Options according to the inspector


GPS	**Yes**


Damages


Right rear wing
repaired.
No repairs
.




Bodywork
Damaged -
Acceptable.
Roof & other








Damaged **Interior**
- Acceptable
Interior





Alloy wheel AVG
Scratch(es)
LI - Repair and paint (complete)
Left






Rear window
with
E-mark - Replace
Rear








Right rear door
repaired.
No repairs
.



AVG Seat Upholstery
Stain
Clean
Interior



Tires

Front Left
Winter
Aluminum
225/55/17/101/V
Pirelli
4.0 mm
Front Right
Winter
Aluminum
225/55/17/101/V
Pirelli
2.0 mm
Left Back
Winter
Aluminum
225/55/17/101/V
Pirelli
5.0 mm
Rear Right
Winter
Aluminum
225/55/17/101/V
Pirelli
4.0 mm

Controls

Category	**Private vehicle**	Registration certificate - home address section	**Yes**
Vehicle registration certificate	**Yes**	Certificate of Conformity	**Yes**
Compressor	**P/A**	Vehicle inspection	**OK**
Vehicle inspection	**10/12/2027**	Jack	**P/A**
Interview	**OK**	Interview	**over 3100 km**
Galette	**P/A**	Repair kit	**P/A**
Number of charging cables (220V)	**1**	Number of charging cables (fast charging)	**1**
Total number of keys	**2**	Réinitialisation des paramètres d'usine	**Oui, le véhicule a été réinitialisé aux paramètres d'usine**
Roue de secours	**P/A**	Runflat	**P/A**
Type de carnet d'entretien	**Entretien digital**		

Détails du NIV

ABS (antiblocage des freins)	Accoudoir central arrière avec 2 porte-boissons	Accoudoir central AV
Actionnement automatique du hayon	Active Guard	Affichage de la pression de gonflage
Airbag conducteur	Airbag passager	Airbags tête avant et arrière
Antidémarrage électronique (EWS III)	Assistant de détection de somnolence	Attention Assist
Avertisseur acoustique pour piétons	Bac de rangement à gauche/droite du coffre	Batterie haute tension garantie 6 ans 100.000 km
BMW TeleServices	Boulons antivol	Bouton start/stop
Brake Energy Regeneration	Câble de charge rapide+câble standard	Calandre décorative+barreaux Schwarz hochglänz.
Caméra de recul	CBC (cornering brake control)	Climatisation à réglage électronique 2 zones
Climatiseur indépendant	Colonne de direction réglable en hauteur et en longueur	Combiné d'instruments Black Panel écran coul.2.7''
Compartiment sous le fond du coffre	Connected eDrives Services	ConnectedDrive Services (BMW Online) via SIM
Connexion USB	Control Display avec écran couleur 6.5''	Cruise Control avec fonction freinage
DAB-tuner	DBC (contrôle dynamique de freinage)	Démarrage sans clé
Désactivation airbag passager	Deux sorties échappement gauche/droite chromées	Direction assistée
Dossier arrière rabattable 40:20:40	Driving Experience Control incl. ECO PRO	DSC - Contrôle dynamique de la stabilité
DTC (Contrôle Dynamique de Traction)	Extension de garantie BMW jusqu'à 3 ans	Feux arrière en LED avec iconic design 3D
Feux stop adaptatifs	Filet au dos des sièges avant	Filet multi-usage
Filtre à particules Otto (OPF)	Fixation Isofix sièges enfants AR	Fonction Auto start/stop
Frein de stationnement électrique avec Autohold	Gicleurs de lave-glace chauffants	GPS Plus 8.8'' Head-Up alarme (si Business Pack)
Head-Up Display	iDrive avec 8 touches de raccourci programmables	iDrive Controller sur console centrale
Inserts Oxidesilber dark matt+Schwarz hochglänzend	Intelligent Emergency Call - eCall	Intérieur tissu Grid
Interrupteur de verrouillage central	JAV rayons doubles 564 7.5Jx17''+225/55	Kit mains-libres Bluetooth avec connexion USB
Kit rétroviseurs: rétros rab.élec.+cond.anti-éblo.	Kit sécurité (triangle-trousse-extincteur-veste)	LED Headlight avec fonctions étendues
Lève-vitres électriques à l'arrière	Lève-vitres électriques à l'avant	Littérature de bord en néerlandais
Logo BMW sur les montants C	Media: radio Pro.coul.6.5''+6HP+USB+AUX+Bluet.	Ordinateur de bord
Park Distance Control (PDC) à l'arrière	Park Distance Control (PDC) avant et arrière	Peinture métallisée
Peinture unie Schwarz	Performance Control	Personal Profile
Porte-boissons dans la console centrale (2)	Prise 12V dans console centrale à l'arrière	Power outlet (12V) in luggage compartment
Power outlet in the center console	Headlight reminder	Auto-dimming interior rearview mirror.
Electric and heated exterior mirrors	Electrically folding exterior mirrors	Retaining strap on the side wall of the trunk
Rain sensor and light sensor	Servotronic	Stainless steel trunk loading sill
Shift Point Display	Lumbar support for driver and passenger	Speed Limit Assist
Speed Limit Info	Alarm system with remote control	Navigation Plus system with Head-Up Display
Velvet carpeting at the front and rear	Third stop light	Central locking with remote control
German language version	Dutch language version	Heat-insulating windows tinted green
Leather steering wheel	Multifunction steering wheel	Sports steering wheel

Information on the content and scope of the inspection report:

- The evaluation is based on the sales standards specified by the client.
- Acceptable wear and tear according to sales standards is not always documented in this condition report.
- The specified repair methods and/or resulting repair times were determined taking into account modern industrial repair methods.
- The reseller must assess individual repair costs.
- The inspection was carried out without dismantling. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.