ARVAL
BNP PARIBAS GROUP

2BQJ759

INSPECTION REPORT

End of contract


GENERAL INFO

File	320161
License plate	2BQJ759
Vehicle identification number	VR3USHNSSNJ540488
Dossier	2020 353 302
Make	Peugeot 2008 1.2 96kW Active P
Mileage	66709
First registration	15/02/2022
client availability date	12/08/2026
inspectionDate	20/08/2026










CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	




B 2-BQJ-759
BELCAR

DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
19	Bumper Front / Lower Cover Not Painted / Replace	N
237	Wing Front right / Trim / Replace	N
272	Bumper Front / Trim Right / Replace	N
35	Front Bonnet // Polish	Y
38	Front Bonnet / Insulation / Replace	N
66	Wing Front Left // Polish	Y
67	Wing Front Left / Trim / Replace	N
201	Rocker Panel Right // Smart Repair Medium	Y
222	Side View Mirror Right // Painting	N
282	Bumper Rear / Trim Center / Replace	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
634	Rear Left Door Interior Coating // Replace Completely	Y
883	Key Price Range 2 //	N

Damage Pictures




Rear Left Door Interior Coating // Replace Completely-scratch




Rocker Panel Right // Smart Repair Medium-dent





Front Bonnet / Insulation / Replace-missing




Wing Front Left / Trim / Replace-Chemical reaction





Wing Front Left // Polish-Chemical reaction

Front Bonnet // Polish-Chemical reaction




Bumper Rear / Trim Center / Replace-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Side View Mirror Right // Painting-scratch




Wing Front right / Trim / Replace-scratch









Bumper Front // Painting-scratch






Bumper Front / Lower Cover Not Painted / Replace-scratch






Bumper Front / Trim Right / Replace-scratch