TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48408889
Order No. / Reference: 27216444
Inspection date: 29 Oct 2026

Manufacturer: Volkswagen	Model: Caddy Cargo 2.0 TDI BMT
VIN: WV1ZZZSKZMX014811	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Caddy Cargo 2.0 TDI BMT	
Vehicle Identification number	WV1ZZZSKZMX014811
Mileage (Read)	52,541 km
First registration	25 Mar 2021
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	75 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Candy White (B9A) Uni
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black

Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	**Next maintenance in**	-1,000 km
Last service on / at	09/2025 at 47,436 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FX486425
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / CMF 00002		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,220 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Winter tyres on Steel rim with wheel cover	Fulda	7mm / 7mm
2)	205/60 R16 96H	Winter tyres on Steel rim with wheel cover	Goodyear	7mm / 7mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments (Various shelves and storage compartments)
- Airbag for driver and front passenger (with passenger airbag deactivation)
- Reinforced battery (70 Ah/ 420 A)
- Brake booster
- Roof rail/roof rack preparation
- Three-point automatic seat belts (with front belt height adjustment and electric belt tensioners)
- Automatic headlight control with daytime running lights
- Windows: Laminated glass front pane in heat-insulating glazing
- Transmission: 6-speed transmission
- Heating system with electronic control
- Instrument cluster (km/h) (displays for speed, total/trip distance, engine speed, fuel level and time)
- Center console with 2 universal cup holders
- Fatigue detection
- eCall emergency call system
- Wheels, tires: Wheel covers
- Wheels/Tires: 205/60 R 16 96 H XL, optimized for low rolling resistance
- Gearshift lever in plastic
- Sliding door, on the right in the passenger/cargo area
- Standard side panels in the cargo area
- Speed-sensitive power steering (Servotronic)
- Seats: Left and right seats in the 1st row (including headrests)
- Start-stop system (with brake energy recuperation)
- Tire Mobility Set (12-volt compressor and tire sealant)
- Lashing points: 6 lashing points for securing cargo
- Electronic immobilizer
- Central locking with remote control and interior operation
- Storage compartments: Glove compartment open
- Towing eye front and rear, screw-in
- Exterior mirror housings and door handles in black, sliding door track in silver
- Operating voltage 12 V
- third brake light
- Three-phase generator 140 A
- Electronic parking brake including auto-hold function
- ESP Electronic Stability Program with Brake Assist (incl. Anti-lock Braking System (ABS), Traction Control System (ASR), (EDS and MSR))
- Electric windows, front
- Halogen dual headlights-H7
- Interior lighting in the cargo area (1 light)
- Steering column adjustable in height and tilt
- Headlight range control
- Multi-collision brake
- Non-smoking version
- Particulate filter: Diesel particulate filter (incl. SCR and AdBlue tank)
- Wheels/Tires: Steel wheels 6.5J x 16, in black
- taillights
- Windscreen wiper intermittent control with light sensor
- Keys for locking system: 2 remote control flip keys
- Side indicator lights
- Seats: Height adjustment for left seat, manual
- Sun visors without mirrors, with ticket pocket on the driver's side, plus airbag label on the sun visor
- Bumper in grey
- First aid kit, warning triangle and high-visibility vest
- Warning tone and light for unfastened front seat belts
- Green thermal insulation glazing

Extra equipment

- Storage compartments: Storage tray on the headliner with 2 roof grab handles in the driver's cab
- Rigid towbar (including trailer stabilization)
- Electrically adjustable and heated exterior mirrors
- Bridgestone Caddy 205/60 R16 96H winter tires
- Deletion: Lettering on the rear (excluding lettering for type/model designation - excluding promotional lettering and decals)
- Rear wing door (asymmetrically divided) with window cutout
- Interior lighting in the cargo area, 2 LEDs
- Interior lighting in the cargo area, 2 LED spotlights
- Paint finish: Solid
- Emergency braking assistant "Front Assist", evasive steering assist and turning assistant (multifunction camera - multifunction steering wheel - evasive steering assist and turning assistant - auto-dimming rearview mirror - emergency braking assistant "Front Assist" with pedestrian and cyclist detection - cruise control including speed limiter - multifunction display "Plus")
- Radio: App-Connect
- Radio accessories: Digital radio reception DAB+
- Wheels/Tires: Tire pressure monitoring system
- dimmable interior safety mirror
- Sortimo conversion
- Power outlets: 12-volt socket in the instrument panel
- Auxiliary water heater with timer and radio remote control
- Airbag, side and head airbags for driver and front passenger
- Adaptive Cruise Control (ACC) with speed limiter
- Floor coverings: Rubber floor covering in the driver's cab
- Parking assistance (rear parking distance control)
- Window: Fixed side window in the cargo/passenger compartment, front right
- Cruise control system including speed limiter
- Rear window heating and rear window wiper (heated rear window - rear window wiper/washer system with interval function)
- Air conditioning
- Fog lights including cornering lights
- Package: Driver Assistance Package - City Drive (Multifunction steering wheel - Rear parking aid - Multifunction display "Plus")
- Upholstery: Robust fabric seat covers, "Robusta" design
- Radio "Composition Audio" with 20.96 cm (8.25 inch) touch color display (2 USB interfaces (Type C) in the center console, front - 4 speakers - mobile phone interface)
- Radio: "Comfort" telephone interface with inductive charging function (hands-free system)
- Rear View reversing camera
- Seats: Manually adjustable lumbar support, left
- Auxiliary heater with radio remote control
- Partition wall (high) with windows and grilles

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Sliding door, right	Sliding door - dent(s) - Smart repair
2	Door - front left side	Door - Scratch(es) - Smart repair
3	Door - front right side	Door - dent(s) - Smart repair
4	Body	Body - Glued / labelled - De-glue / neutralise
5	Vehicle glazing	Windscreen - Stone chips - Replace

Wear and tear

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 28 Jun 2022	1.340,60 €

Repainting

No.	Repainting
1	Side panel - rear right side
2	Door - rear right side, Professionally carried out

Paint coat thickness measurement

Side panel - rear right side	412 µm	Door - rear right side	379 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Misc.




Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Damage 1: Sliding door, right: Sliding door - dent(s) - Smart repair




Damage 1: Sliding door, right: Sliding door - dent(s) - Smart repair



Damage 1: Sliding door, right: Sliding door - dent(s) - Smart repair



Damage 1: Sliding door, right: Sliding door - dent(s) - Smart repair



Damage 2: Door - front left side: Door - Scratch(es) - Smart repair



Damage 2: Door - front left side: Door - Scratch(es) - Smart repair



Damage 3: Door - front right side: Door - dent(s) - Smart repair



Damage 3: Door - front right side: Door - dent(s) - Smart repair



Damage 3: Door - front right side: Door - dent(s) - Smart repair



Damage 3: Door - front right side: Door - dent(s) - Smart repair



Damage 3: Door - front right side: Door - dent(s) - Smart repair



Damage 4: Body: Body - Glued / labelled - De-glue / neutralise



Damage 4: Body: Body - Glued / labelled - De-glue / neutralise




Damage 4: Body: Body - Glued / labelled - De-glue / neutralise




Damage 4: Body: Body - Glued / labelled - De-glue / neutralise



Damage 5: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 5: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 5: Vehicle glazing: Windscreen - Stone chips - Replace



Repainting 1: Side panel - rear right side



Repainting 1: Side panel - rear right side



Repainting 2: Door - rear right side



Repainting 2: Door - rear right side