BMW X1 - 2019


Vehicle information

Brand:	**BMW**	License plate:	**1YBE834A**
Gearbox:		Body color:	
Model:	**X1 - 2019**	LEVEL:	**WBA71AB0705R82544**
Fuel type:		Power:	**92 kW**
Version:	**1.5iA xDrive25e PHEV OPF**	First registration	**06/07/2020**
Mileage:	**162,532 km**	Number of doors:	


Summary of damages


RIGHT	2
LEFT	1
Interior	1
Roof & other	1



Commercial photos



















Made in
Germany
X1 xDrive25e
A96
BAYERISCHE MOTOREN WERKE AG
e1*2007/46*1676
WBA71AB0705R82544
2330 kg
3080 kg
1- 1110 kg
2- 1270 kg


Equipment corresponding to the VIN according to the manufacturer's information

Center armrest	Airbag	Alarm	Roof bars
Rain sensor	Distance control	Battery current	Trailer hitch
Power steering	Windscreen wipers / rear nozzles	Electrical operation of windows	GPS
Leather interior	Alloy wheels	Electrically adjustable mirrors	Heated front seats (ECS&B)
Adjustable lumbar support	Phone	Central locking	Multifunction steering wheel

Options according to the inspector

GPS	**Yes**



Damages

Bodywork
Damaged - Acceptable.
Roof & other




Damaged **Interior**
- Acceptable
Interior






Front Right Tire
Tear
E - Replace





Left Front Tire
Tear
E -
Replace





Right-hand side **mirror repeater** crack - Replace





Tires

Front Left
Summer
Aluminum
225/50/18/95/V
Michelin
3.0 mm
Front Right
Summer
Aluminum
225/50/18/95/V
Michelin
4.0 mm
Left Back
Summer
Aluminum
225/50/18/95/V
Michelin
5.0 mm
Rear Right
Summer
Aluminum
225/50/18/95/V
Michelin
5.0 mm

Controls

Category	**Private vehicle**	Registration certificate - home address section	**Yes**
Vehicle registration certificate	**Yes**	Certificate of Conformity	**Yes**
Compressor	**P/A**	Vehicle inspection	**OK**
Vehicle inspection	**06/07/2027**	Jack	**P/A**
Interview	**OK**	Interview	**over 3800 km**
Galette	**P/A**	Repair kit	**P/A**
Number of charging cables (220V)	**1**	Number of charging cables (fast charging)	**1**
Total number of keys	**2**	Factory reset	**Yes, the vehicle has been reset to factory settings.**
Spare wheel	**P/A**	Runflat	**P/A**
Type of maintenance log	**Digital interview**		

NIV Details

ABS (anti-lock braking system)	Accès confort	Accoudoir central arrière avec 2 porte-boissons
Accoudoir central AV	Actionnement automatique du hayon	Active Guard
Affichage de la pression de gonflage	Airbag conducteur	Airbag passager
Airbags latéraux avant	Airbags tête avant et arrière	Antidémarrage électronique (EWS III)
Appuie-tête AR (3)	Appuie-tête AV	ASC - X (control stabilité)
Attache remorque avec boule démontable	Avertisseur acoustique pour piétons	Bac de rangement à gauche/droite du coffre
Banquette AR régl.inclinaison et rabat.40/20/40	Batterie haute tension garantie 6 ans 100.000 km	BMW TeleServices
Boulons antivol	Bouton start/stop	Brake Energy Regeneration
Câble de charge rapide+câble standard	Caméra de recul	CBC (cornering brake control)
Ceintures à réglage manuel en hauteur	Ceintures arrière 3 points	Ceintures AV aut.+prétens.+limiteur de tension
Ceintures de sécurité AV à 3 points	Ciel de pavillon en anthracite	Climatisation à réglage électronique 2 zones
Climatiseur indépendant	Compartiment rabattable tableau bord côté cond.	Compartiment sous le fond du coffre
Connected eDrives Services	ConnectedDrive Services (BMW Online) via SIM	ConnectedDrive Services Pack
Connexions AUX-IN/USB dans la console centrale	Cruise Control avec fonction freinage	DAB-tuner
DBC (contrôle dynamique de freinage)	Désactivation airbag passager	Driving Experience Control incl. ECO PRO
DSC - Contrôle dynamique de la stabilité	DTC (Contrôle Dynamique de Traction)	Eclairage diurne
ECO PRO	Espace de rangement sous le siège conducteur	Essuie-glace AR
Extension de garantie BMW jusqu'à 3 ans	Feux arrière en LED avec iconic design 3D	Feux stop adaptatifs
Filet au dos des sièges avant	Filet de séparation du compartiment à bagages	Filet multi-usage
Filtre à particules Otto (OPF)	Fixation Isofix sièges enfants AR	Fonction Auto start/stop
Gicleurs de lave-glace chauffants	Head-Up Display	Ins.Alu Längsschliff fein+Perlgl.Ch.(si Sp./xLine)
Inserts Alu Längsschliff fein (si Model M Sport)	Inserts Oxidesilber dark matt+Schwarz hochglänzend	Intelligent Emergency Call - eCall
Intérieur cuir Dakota perforé (si Model M Sport)	Intérieur cuir Dakota perforé (si Model xLine)	Intérieur tissu Grid
Interrupteur de verrouillage central	JAV rayons doubles 564 7.5Jx17''+225/55	Kit rétroviseurs
Kit sécurité (triangle-trousse-extincteur-veste)	LED Headlights	Lève-vitres électriques à l'arrière
Littérature de bord en néerlandais	Media: radio Pro.coul.6.5''+6HP+USB+AUX+Bluet.	Miroir de courtoisie pour conducteur et passager
Naseaux contours chromés+barreaux Schwarz hochgl.	Ordinateur de bord	Park Distance Control (PDC) à l'arrière
Park Distance Control (PDC) avant et arrière	Peinture métallisée	Peinture unie Schwarz
Performance Control	Porte-boissons dans la console centrale (2)	Préparation pour Apple CarPlay
Prise 12V supplémentaire (espace jambes passager)	Prise de courant (12V) dans compartiment à bagages	Prise de courant dans la console centrale
Rails de fixation au toit noirs	Rails de toit en Shadow Line (si Model xLine)	Rangement dans la console centrale
Headlight reminder	Electric adjustment of the front seats with memory function for the driver's seat	Auto-dimming interior rearview mirror.
Heated and folding electric mirrors	Body-colored exterior mirrors	Electric and heated exterior mirrors
Retaining strap on the side wall of the trunk	Rain sensor and light sensor	Servotronic
Glossy Shadow Line (if xLine)	Heated front seats	Height-adjustable front seats
Lumbar support for driver and passenger	Alarm system with remote control	Navigation Plus system with Head-Up Display
Velvet carpeting at the front and rear	Panoramic glass sunroof	Warning triangle and first aid kit
Third stop light	Tool kit	Central locking with collision sensor
Central locking with remote control	German language version	Heat-insulating windows tinted green
Electric front windows with comfort/anti-pinch closure	Tinted rear windows	Multifunction steering wheel

Information on the content and scope of the inspection report:

- The evaluation is based on the sales standards specified by the client.
- Acceptable wear and tear according to sales standards is not always documented in this condition report.
- The specified repair methods and/or resulting repair times were determined taking into account modern industrial repair methods.
- The reseller must assess individual repair costs.
- The inspection was carried out without dismantling. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.