TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48211900
Order No. / Reference: 27104141
Inspection date: 12 Oct 2026

Manufacturer: Audi	Model: A6 Avant 40 TDI S tronic
VIN: WAUZZZF21NN066946	





Vehicle details

Manufacturer / Type / Model / Equipment	
Audi A6 Avant 40 TDI S tronic	
Vehicle Identification number	WAUZZZF21NN066946
Mileage (Read)	52,990 km
First registration	12 Oct 2022
Number of holders	1
Next periodical technical inspection	11/2027
(Report on hand)	
Fuel type	Hybrid Diesel / E
Engine displacement / Cylinder	1,968 ccm / 4
Power	150 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Goodwood green Perl.
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black
Re-import	no
readiness to drive	Roadworthy

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	7,100 km
Last service on / at	08/2026 at 52,494 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GM655350
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	0588 / BSZ 02046		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,330 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	255/40 R20 101Y	Summer tyres on Light alloy	Continental	6mm / 6mm
2)	255/40 R20 101Y	Summer tyres on Light alloy	Continental	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/45 R19 102V	Winter tyres on Light alloy	Dunlop	7mm / 7mm
2)	245/45 R19 102V	Winter tyres on Light alloy	Dunlop	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 08/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- AdBlue tank (12 liters)
- Airbag: Front side airbags and head airbag system
- Audi connect navigation & infotainment
- Audi drive select
- Audi pre sense front
- third brake light
- Roof rails in matte black
- Tachometer
- Door sills with aluminum inlay front and rear
- Driver information system with color display
- Luggage compartment lid, electrically opening and closing
- Transmission: S tronic 7-speed
- Interior mirror dimming
- Headrests (4)
- LED headlights
- front center armrest
- Non-smoking package
- Wheel: Tire pressure monitoring system
- Radio: MMI Radio plus with MMI touch response
- Seats: Standard front seats
- Sun visor on driver and passenger side
- Start-stop system
- Electronic immobilizer
- Airbag for driver and front passenger
- Anti-lock braking system (ABS)
- Audi connect emergency call & service m.connect remote & control
- Exterior mirror housings in body color
- Fabric headliner
- Diesel particulate filter (DPF) with nitrogen oxide catalyst and AdBlue tank
- Electronic Stability Control (ESC)
- key fob
- Cruise control system including speed limiter
- Interior lighting
- ISOFIX child seat attachment and Top Tether for the outer rear seats
- Steering column, manually adjustable in height and axis
- MMI navigation with MMI touch response
- Progressive steering
- Wheel: Tire repair kit
- Rail system with fixing set
- Seats: Split-folding rear seat backrest Avant
- Lane Departure Warning
- Glazing: Windscreen in heat-insulating glazing
- Central locking

Extra equipment

- Audi phone box opt-out package
- Aluminum roof rails
- Decorative inlays in natural grey-brown ash burl wood (for dashboard, door panels and center console; including aluminum-look trim)
- Parking aid plus with surround view (acoustic and visual parking aid front, side and rear to assist with parking and maneuvering by measuring with 12 ultrasonic sensors. A selective visual display shows the distance to detected objects in the upper display, depending on the current steering angle and the direction of travel. Optionally, activation occurs automatically as soon as the vehicle approaches a detected obstacle at a speed of less than 10 km/h).
- High beam assist (within the system's limits, it automatically detects oncoming headlights, taillights of other road users, and built-up areas. Depending on the traffic situation, the high beam is automatically switched on or off.)
- Paint finish: Audi exclusive individual paint finish
- Business Package (Assistance Package Tour: Adaptive Driving Assistant supports the driver with acceleration, braking, maintaining speed and distance, and lane keeping. Adaptive Cruise Control, Speed Limiter. Efficiency Assistant supports the driver with predictive driving. Parking Aid Plus, 4-zone automatic climate control, heated front seats, Audi phone box, automatically dimming interior mirror, automatically dimming exterior mirrors, adaptive windscreen wipers with integrated washer nozzles, high-beam assistant)
- Package: Storage package (2 cup holders in the rear center armrest, luggage compartment net for fixing to the lashing eyes on the luggage compartment floor)
- Wheel: Alloy wheels 5-V-spoke design, graphite grey, polished (8.5 J x 20 with tires 255/40 R 20)
- Radio accessories: Bang & Olufsen Premium Sound System with 3D sound (sound reproduction via 16 speakers including 3D sound speakers, center speaker and subwoofer, 15-channel amplifier with a total output of 705 watts; spatial sound reproduction thanks to the 3D sound feature for the front seats. This is created by additional speakers in the A-pillars, the midrange speakers and Fraunhofer Symphoria technology. The 3D sound can be played back with all sources.)
- Seat covers in leather/mono.pur 550 combination (for standard front seats without seat ventilation) (center section of the front seats and the two outer rear seats as well as the driver's side entry bolster in leather; side bolsters, headrests, inner door panel, front center armrest and middle rear seat in mono.pur 550 synthetic leather)
- Electrically adjustable, heated, and folding exterior mirrors, automatically dimming on both sides, with memory function (including curb view function for the passenger-side exterior mirror with integrated LED turn signal, including heated windshield washer nozzles, aspherical mirror glass. The curb view function tilts the passenger-side exterior mirror downwards when reverse gear is engaged, providing the driver with a better view of the curb.)
- Chassis with damper control (with electronically controlled adjustment of the dampers to different driving situations - dynamic or comfort-oriented damper basic setting, adjustable via Audi drive select - controlled shock absorbers and coil springs on the front and rear axles)
- ISOFIX child seat attachment for the front passenger seat (with deactivation switch for passenger airbag including electric child safety lock for the rear doors)
- Fuel tank (73 liters) (fuel tank for 73 liters of gasoline/diesel fuel)
- Steering wheel: Double-spoke leather steering wheel with multifunction and paddle shifters (paddle shifters allow manual changing of the driving modes.)
- S line exterior package (S-specific front and rear bumpers with S line-specific inserts (honeycomb structure), S line-specific side air intake grilles in matte titanium black with platinum grey inlays, radiator grille in matte titanium black with louvers in matte aluminum silver, S-specific side sill/door trim strips painted in body color, illuminated door sill trims with aluminum inlay front and rear, with S lettering at the front, S line emblem on the front fenders, S line-specific diffuser insert, tailpipe look in matte aluminum silver)
- Panoramic glass roof (2-piece) (extra-large, tinted glass surface for a progressive design; electric operation for tilting and opening, including an electrically operated, lightproof sunshade; convenient opening and closing from the outside via the remote key ensures a pleasant, light-flooded interior; improved interior climate through efficient ventilation; integrated wind deflector reduces wind noise when the roof is open)
- Reversing camera (The reversing camera displays the area behind the vehicle on the upper display. Dynamic display elements such as a steering angle-dependent lane calculation assist with parking or maneuvering.)
- Seats: Electrically adjustable front seats including memory function for the driver's seat (electric adjustment of seat height, seat longitudinal position, seat and backrest tilt with memory function for driver's side, 2 memory locations per personal user profile for the electrically adjustable front seats and the exterior mirrors, electric 4-way lumbar support)

- Auxiliary heater/ventilation (The auxiliary heater warms the interior and defrosts the windows without starting the engine. The auxiliary ventilation system supplies fresh air and lowers the interior temperature. Both functions can be activated via a timer and separate remote control. An intelligent control system with timer and departure time programming calculates the heating duration efficiently in terms of time and energy. Separate remote control with illuminated display. 2 selectable heating modes: - defrost (defrost mode for the windows only) - warm)
- Glazing: Sun protection glazing, tinted (rear window, rear door and side windows tinted)
- Telephone: Audi smartphone interface (The Audi smartphone interface (Android Auto and Apple CarPlay) connects your smartphone to your Audi and seamlessly displays your smartphone content directly on the MMI display via USB. Navigation, telephony, music and selected third-party apps can be conveniently controlled via the MMI touchscreen as well as via voice control on your smartphone.)
- Glazing: Acoustic glazing for the side windows (improved external noise insulation through double glazing)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Alloy rim - front left side - Scratch(es) - Loss in value
2	Wheel / tyres	Alloy rim - front left side - Broken / torn - Replace
3	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Loss in value
4	Rear bumper	Rear bumper - Scratched - Paint
5	Front bumper	Front bumper - Scratched - Paint

Wear and tear

No.	Component group	Description
1	Interior	Interior - Soiled - No deduction
2	Interior	Interior - Soiled - No deduction
3	Bonnet	Bonnet - Stone chips - No deduction
4	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Accident damages

No.	Accident
1	Side right

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.

- Die beigefügte Reparaturkostenkalkulation wurde nach bestem Wissen und Gewissen unter eingeschränkten Besichtigungsbedingung im demontagefreien Zustand erstellt. Es können aufgrund verdeckter Beschädigung erhebliche Mehrkosten und somit Abweichung der für den Unfall ausgewiesenen Reparaturkosten nicht ausgeschlossen werden.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.




Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Damage 1: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Loss in value



Damage 1: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Loss in value



Damage 2: Wheel / tyres: Alloy rim - front left side - Broken / torn - Replace



Damage 2: Wheel / tyres: Alloy rim - front left side - Broken / torn - Replace




Damage 3: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 3: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value




Damage 4: Rear bumper: Rear bumper - Scratched - Paint



Damage 4: Rear bumper: Rear bumper - Scratched - Paint



Damage 4: Rear bumper: Rear bumper - Scratched - Paint



Damage 5: Front bumper: Front bumper - Scratched - Paint




Damage 5: Front bumper: Front bumper - Scratched - Paint




Damage 5: Front bumper: Front bumper - Scratched - Paint




Accident 1: Side right



Accident 1: Side right



Accident 1: Side right




Accident 1: Side right




Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right