MACADAM

Mercedes-Benz EQS '21 BEV

Vehicle information


Make:	**Mercedes-Benz**	License:	
Gearbox:	**Automatic**	Body color:	
Model:	**EQS '21 BEV**	VIN:	**W1K2971211A018277**
Fuel type:	**Electric**	Power:	**215 kW**
Version:	**EQS 350 Luxury Line**	First registration	**25/08/2022**
Mileage:	**65053 km**	N° of doors:	

Damage summary

Front	1
Left	1

Commercial pictures



























Options according to the inspector

Central consol F	**Yes**	GPS	**Yes**	Headlights Xenon/LED/Laser	**Yes**
Panoramic roof	**Yes**	Radio multimedia	**Yes**	Rear view camera	**Yes**
Sun Roof electric	**Yes**	Telephone equipment	**Yes**		

Damages

Alloy rim RL
Scratch(es)
Repair and paint (complete)
Left




Bonnet
Stone chip(s)
Repair and paint (complete)
Front




Tyres

Front Left	
Summer	
255/45/20/105/H	
Goodyear	
5.3 mm	
Front Right	
Summer	
255/45/20/105/H	
Goodyear	
5.2 mm	
Rear Left	
Summer	
255/45/20/105/H	
Goodyear	
5.5 mm	
Rear Right	
Summer	
255/45/20/105/H	
Goodyear	
3.9 mm	

Checks

CO2 Emission	**0**	Digital maintenance	**Yes**
GPS storage	**Yes**	Luggage cover	**Yes**
Number head rests	**5**	Number of charging cables (rapid charge)	**1**
Number of keys total	**2**	Reset to factory settings	**Yes, vehicle is reset to factory settings**
Service book	**N/A**	User's manual	**Yes**

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.