TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Expertise

Protocol number: 48416081
Order No. / Reference: 27211646
Inspection date: 28 Oct 2026

Manufacturer: Kia	Model: Sorento 2.2 CRDi DCT8 2WD Spirit
VIN: KNARH81BGP5222363	





Vehicle details

Manufacturer / Type / Model / Equipment	
Kia Sorento 2.2 CRDi DCT8 2WD Spirit	
Vehicle Identification number	KNARH81BGP5222363
Mileage (Read)	80,602 km
First registration	12 Oct 2023
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	2,151 ccm / 4
Power	142 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Schneeweiß
Doors / Seats	5 / 5
Upholstery type	Leather
Colour of upholstery	Black

TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	7,753 km
Last service on / at	12/2025 at 58,355 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GY700604
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	2233 / ABL 00031		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,550 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 105Y	Summer tyres on Light alloy	Continental	5mm / 5mm
2)	235/55 R19 105Y	Summer tyres on Light alloy	Continental	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 105V	Winter tyres on Light alloy	Hankook	6mm / 6mm
2)	235/55 R19 105V	Winter tyres on Light alloy	Hankook	4mm / 4mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 05/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 7 airbags
- Active brake light
- Ambient lighting
- Exit assistant
- Heated, electrically adjustable and folding exterior mirrors
- Hill descent control
- Roof rails
- Digital instrument cluster with 31.2 cm (12.3 inch) screen diagonal
- Drive Mode Select
- EcoDynamics (Start-Stop System and Energy Regeneration System)
- Electric tailgate, sensor-controlled
- Electronic Stability Control (ESC) with Traction Control System (TCS)
- Front grill in piano black
- Forward Collision Warning with Turning Function (FCA-JX)
- floor mat set
- luggage compartment cover
- Cruise control, navigation-based
- Front cup holder
- Inductive charging station for smartphones
- Interior rearview mirror self-dimming (electrochromatic)
- Intelligent speed assistant
- Automatic air conditioning
- Paint finish: Solid Snow White
- LED daytime running lights
- LED fog lights
- Steering wheel: Multifunction steering wheel
- front center armrest
- Driver Alert System (DAW)
- Level control (rear axle)
- Emergency call service eCall
- Upholstery: Leather interior "Nero"
- Rear cross-traffic alert including emergency braking function
- Radio: Digital radio reception (DAB+)
- Radio accessories: 12 speakers including subwoofer
- Radio accessories: Bluetooth hands-free system
- Radio accessory: Voice amplifier via the speakers (Driver Talk)
- Radio accessories: USB port in the rear of the center console
- Tire pressure monitoring system
- Wheels: 19" alloy wheels
- paddle shifters on the steering wheel
- Seat belts
- Seat: Passenger seat electrically adjustable
- Seat: Front passenger seat with side control panel for rear passengers
- Seat: Driver's seat with electrically adjustable lumbar support (2-way)
- Smart key and start button
- Sunshades in the rear doors
- Lane keeping assist with visual/acoustic warning signal
- Front and rear underride protection
- Electronic immobilizer
- Active blind spot assist with steering and braking intervention
- Anti-lock braking system (ABS)
- Highway assistant
- Exterior mirrors with integrated turn signals
- Hill start assist
- Diesel particulate filter (DPF)
- Tachometer
- Third brake light
- twilight sensor
- Electric windows front and rear with one-touch function on all doors
- Electronic parking brake (EPB)
- Energy Regeneration System (AMS)
- High Beam Assist (HBA)
- Forward Collision Warning (FCA)
- Headlights with escort function
- Vehicle Stability Management (VSM)
- Adaptive cruise control with stop-and-go function
- 8-speed automatic transmission
- Rear window defroster and windshield wipers
- Interior elements with ion plating design
- Inmate alarm
- ISOFIX mount
- Headrests (5)
- LED taillights
- LED interior lighting
- Heated leather steering wheel
- Rear center armrest with cup holders
- Multi Collision Braking (MCB)
- Navigation: KIA map navigation with a 26 cm (10.25 inch) screen diagonal
- Front and rear parking sensors
- Privacy glazing
- Radio: Bose surround sound system with external amplifier
- Radio: Kia radio with a 20.2 cm (8 inch) screen diagonal
- Radio accessories: Android Auto and Apple CarPlay
- Radio accessories: Kia Connect online services with Kia Live
- Radio accessories: USB port on the back
- Radio accessories: USB port on the front
- Rain sensor
- Tire repair kit
- Rear view camera
- Power steering
- Seat: 2nd row of seats is adjustable and foldable (60:40)
- Seat: Passenger seat height adjustable
- Seat: Driver's seat electrically adjustable
- Seat: Driver's seat height adjustable
- Seat: Rear seat heating (outer seats of the 2nd row)
- Seat: Front seat heating
- Solar glass windshield and front side windows
- Lane Following Assist (LFA)

- Door handles in satin chrome
- Full LED headlights

Extra equipment

- Upholstery: Leather interior "Nero"

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Door - front right side	Door - dent(s) - Smooth repair work
3	Door - rear right side	Door - dent(s) - Smooth repair work

Wear and tear

No.	Component group	Description
1	Front bumper	Front bumper - Stone chips - No deduction
2	2nd wheel set	2 tyres (Nicht Bestandteil der Ausstattung) - Does not meet the leasing specifications - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Der angegebene Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.

- Ein Nachweis über die Zulässigkeit des beiliegenden Radsatzes wurde nicht erbracht.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres




Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.



Damage 2: Door - front right side: Door - dent(s) - Smooth repair work



Damage 2: Door - front right side: Door - dent(s) - Smooth repair work



Damage 3: Door - rear right side: Door - dent(s) - Smooth repair work



Damage 3: Door - rear right side: Door - dent(s) - Smooth repair work



Damage 3: Door - rear right side: Door - dent(s) - Smooth repair work



Damage 3: Door - rear right side: Door - dent(s) - Smooth repair work



Wear and tear 1: Front bumper: Front bumper - Stone chips - No deduction



Wear and tear 1: Front bumper: Front bumper - Stone chips - No deduction