APPRAISAL REPORT



VEHICLE IDENTIFICATION

Driver name:	HM Tongeren
Make:	VOLKSWAGEN
Model / version:	Tiguan
Wine:	WVGZZZ5NZMM142557
Plate:	2BAX911
Mileage:	94336
First registration:	14/09/2021
Color:	Platinum Gre

ADDITIONAL INFORMATION


Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?




DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book	
Number of keys:	2
Original key:	✓

PICTURES








































WINE INFORMATION

8 speakers	Phone pre-wiring	Manual transmission
6 reports	Automatic headlights	Adaptive headlights
Halogen spotlights	Fog lights	LED daytime running lights
Heated front windshield washer nozzles	Comfortline Equipment	Material: alloy
Reference letter (J)	Front diameter 17	Rear diameter 17
Front width 7.0	Rear width 7.0	Front diameter 17
Rear diameter 17	Front height 65	Rear height 65
Forward speed index V	Rear speed index V	Front width 215
Rear width 215	Automatic climate control	Air conditioning refrigerant 1234YF
Chrome interior finish	On-board computer	Essence
1498 cm3	1.50 liters	110 kW
150 hp	140 Amp Alternator	Metallic varnished

Electrically folding mirrors	Automatic day/night interior rearview mirror	Heated front left seat
Heated front seats	Electrically adjustable front left seat	Electrically adjustable front seats
Front seats with lumbar adjustment	Sièges arrière chauffants	Garnitures cuir
Direction assistée variable	Volant cuir	Volant multifonction
Aide au stationnement avant	Aide au stationnement arrière	Assistance au parking
Caméra avant	Caméra arrière de recul	Régulateur automatique de la distance
Equipement Stop & Start	Affichage lecture des panneaux de signalisation	Verrouillage centralisé à commande à distance
Carte mains libres	Ouverture du coffre électriquement	Lunette arrière teintée foncée
Vitres portes arrière teintées foncées	Vitres de custode teintées foncées	détecteur de pluie essuie-vitre
Fixotoit	Airbag passager	Airbag passager désactivable
Airbag de genoux	Assistant maintien de la voie	Freinage d'urgence assistée autonome (urbain)
enjoliveurs des vitres latérales blancs	depuis 05.21	rétroviseur g avec miroir asphérique
rétroviseur d convexe	radio avec récepteur numérique	antenne AM/FM
Infotainment-System (MIB3)	tiroirs sous les sièges av	plancher de coffre séparable
tablette rabattable dans les dossiers des sièges av	dossier d rabattable	console pavillon avec vide-poches
roues av motrices (traction)	réservoir à charbon actif (EVAP)	barre stabilisatrice ar 21,7x3,6 mm
services Online	norme anti-pollution Euro 6 AP	

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	×	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	×
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlight type:		**Tow bar type:**	
Charging cables:	0	**Fast charging cables:**	0

TIRES

Position	Depth	Brand	Dimensions	Kind	Rims	Runflat
Front left	5 mm		215/65R17 99V	Summer		?
Front right	5 mm		215/65R17 99V	Summer		?
Rear left	5 mm		215/65R17 99V	Summer		?
Rear right	5 mm		215/65R17 99V	Summer		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Rental	Damage type
1	Floor covering	Damaged
2	Contact key - Boordcomputer resetten	Not original part
4	Alloy rim FL polished	Grooved
5	Inner door sill RL	Teeth)
6	Alloy rim RL polished	Grooved
7	Alloy rim FR polished	Grooved

Total: 6

ACCEPTABLE / NOT TO BE INVOICED

#	Rental	Damage type	Renta®	Repaired	Already invoiced
3	Bodywork	Teeth and scratches	✓	×	×

Total: 1

DAMAGE DETAILS

1 - Floor covering - Damaged







2 - Contact key - Boordcomputer resetten - Not original part





4 - Alloy rim FL polished - Grooved

5 - Inner door sill RL - Dent(s)




6 - Alloy rim RL polished - Grooved







7 - Alloy rim FR polished - Grooved







3 - Bodywork - Dent(s) and scratch(es) - Renta®









SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

12/10/2026 13:52

