TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Expertise

Protocol number: 48443163
Order No. / Reference: 27171121
Inspection date: 2 Nov 2026

Manufacturer: Mercedes-Benz	Model: GLC 300 d 4Matic 9G-TRONIC AMG Line Premium Plus (Advanced)
VIN: W1NKM0HB8RU047343	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz GLC 300 d 4Matic 9G-TRONIC AMG Line Premium Plus (Advanced)	
Vehicle Identification number	W1NKM0HB8RU047343
Mileage (Read)	61,129 km
First registration	27 Nov 2023
Number of holders	1
Next periodical technical inspection (Report not on hand)	11/2026
Fuel type	Hybrid Diesel / E
Engine displacement / Cylinder	1,993 ccm / 4
Power	198 kW
Gearbox / Number of gears	Automatic / 9
Type of drive	All-wheel drive
Type of vehicle	SUV
Colour / colour code	SPEKTRALLBLAU METALLIC
Doors / Seats	5 / 5
Upholstery type	Artificial leather
Colour of upholstery	Grey-Black
Re-import	no
Vehicle with smoke odor	no
readiness to drive	Not roadworthy / moveable

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	203 Tag(e)
Last service on / at	04/2026 at 51,756 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GY537078
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Not roadworthy / moveable		
Manufacturer key number/ type code number	2222 / BLA 00127		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,570 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	255/45 R20 105W	Summer tyres on Light alloy	Continental	3mm / 3mm
2)	285/40 R20 108W	Summer tyres on Light alloy	Continental	3mm / 3mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/60 R18 103H	Winter tyres on Light alloy	Continental	6mm / 6mm
2)	235/60 R18 103H	Winter tyres on Light alloy	Continental	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 01/2029		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Adaptive Highbeam Assist
- Airbag: Kneebag for driver
- Airbag: Windowbag
- Active Lane Keeping Assist
- Ambient lighting
- AMG floor mats
- AMG Line Exterior
- AMG sports pedal assembly made of brushed stainless steel with black rubber studs
- ATTENTION ASSIST
- Basic services
- Roof rails made of glossy anodized aluminum
- Double cup holder
- Tachometer
- EASY-Pack: Cargo area cover
- Driver display
- Fingerprint scanner
- Rear window heated
- Interior headliner fabric crystal grey
- Climate: THERMATIC automatic climate control
- Communication module (LTE) for the use of Mercedes me connect services
- Paint finish: Solid
- Steering wheel: Multifunction sports steering wheel in Nappa leather
- Center console in high-gloss black
- Navigation accessories: Pre-installation for Live Traffic Information
- Navigation: Hard disk navigation
- Package: Storage
- Package: Chrome Interior Package
- Package: Boot Comfort Package
- Package: Seating comfort
- Package: USB package
- Radio accessories: Digital radio (DAB)
- Tire pressure loss warning
- Wheels: 48.3 cm (19") AMG light-alloy wheels in 5-spoke design, painted tantalum grey
- Windscreen wipers with rain sensor
- Heated seats for driver and front passenger
- Phone accessories: Wireless charging system for mobile devices
- Pre-installation for digital key handover
- Immobiliser
- Central display
- Decorative elements: metal structure
- Airbag for driver and front passenger
- Airbag: Side airbag for driver and front passenger
- Active Brake Assist
- 4MATIC all-wheel drive
- AMG front apron with sporty air intakes and chrome trim element
- AMG Line interior
- Anti-lock braking system (ABS)
- Traction control (ASR)
- Automatic passenger airbag deactivation
- Brake system with larger brake discs on the front axle
- Diesel particulate filter
- Downhill Speed Regulation (DSR)
- EASY-PACK tailgate
- Electronic Stability Program (ESP)
- Chassis: Sport chassis
- Transmission: 9G-TRONIC
- Rear window wiper/washer system
- Instrument panel and door sills in ARTICO man-made leather in black nappa look
- Radiator grille with Mercedes-Benz pattern and integrated Mercedes star
- LED High Performance Headlights
- Steering: Sport direct steering
- Mercedes-Benz emergency call system
- Navigation accessories: Extended MBUX functions
- Navigation accessories: Pre-installation for navigation services
- Navigation: MBUX Navigation Premium
- Package: AMG Line Advanced
- Package: Interior light
- Package: Parking package with reversing camera
- Package: Mirror Package
- Upholstery: ARTICO leatherette/MICROCUT microfiber
- Radio accessories: MBUX multimedia system
- Remote Services
- Wheels: Summer tires
- Wheel accessories: TIREFIT with tire inflator compressor
- Seats: 4-way lumbar support for driver and front passenger
- Sporty engine sound
- Phone accessories: Smartphone integration
- Cruise control
- High-visibility vest for drivers
- Heat-insulating dark tinted glass
- Central locking with remote control

Extra equipment

- Towbar with ESP trailer stabilization
- Black fabric headliner
- Paint finish: Metallic
- Center console diamond pattern silver grey
- Package: AMG Line Premium Plus (Electrically adjustable driver's seat with memory function - Blind Spot Assist - Illuminated door sills with "Mercedes-Benz" lettering - Traffic Sign Assist - Acoustic glass - KEYLESS-GO Comfort Package - DIGITAL LIGHT with projection function - Parking Package with 360° camera - MBUX Augmented Reality for navigation - Panoramic sliding sunroof - Head-up display - THERMOTRONIC automatic climate control - Burmester 3D surround sound system - Ambient lighting Plus)
- Package: Night (Radiator grille with Mercedes-Benz pattern and louvre in high-gloss black - Attractive 48.3 cm (19") AMG 5-spoke light-alloy wheels in high-gloss black and polished finish 235/55 R19 on 8.0 J x 19 ET 32.5 - AMG front apron with visual underguard in high-gloss black - Belt trim strip and window surrounds in high-gloss black - Exterior mirror housings painted in high-gloss black - Roof rails in matte black, rear apron and diffuser in black)
- Package: Technology package (AIRMATIC with all-round level control and ADS PLUS - rear axle steering with 4.5° maximum steering angle)
- Radio accessories: Pre-installation for MBUX Entertainment (integration of music streaming services (user account required): Spotify, Amazon Music, Apple Music, TIDAL, TuneIn (no user account required) - Extended radio information - Extended radio station tracking - Internet radio - Third-party convenience data volume)
- Wheels: 50.8 cm (20") AMG multi-spoke light-alloy wheels (painted black, rim flange polished - front axle 255/45 R20 on 8.5 J x 20 ET 34.5 and rear axle 285/40 R20 on 9.5 J x 20 ET 35.5)
- Illuminated running boards in aluminum look with rubber studs
- Decorative elements in diamond pattern, silver-grey
- ENERGIZING AIR CONTROL (Air quality sensor and separate fine dust sensors for indoor and outdoor use detect harmful inhalable gases in the outdoor air as well as fine dust (PM2.5) in the outdoor and indoor air - Fine dust filtration with 2 filters, consisting of a fine dust pre-filter and an indoor air filter - Indoor air filter in the air conditioner based on activated carbon with filter layers against fine dust (PM2.5) and nitrogen oxides (NOx) or sulfur dioxide (SO2) as well as pollen, allergens and soot particles - automatic recirculation)
- Package: Driving Assistance Package Plus (Active Distance Assist DISTRONIC, Active Speed Limit Assist, Extended Automatic Restart, Route-Based Speed Adaptation with Traffic Jam Definition, Active Steering Assist, Active Lane Change Assist, Active Emergency Stop Assist with SOS Radio, Emergency Lane Radio, Active Brake Assist, Turn and Intersection Radio, Traffic Jam Emergency Brake Radio, Evasive Steering Assist, Active Lane Keeping Assist, Active Blind Spot Assist, Exit Warning Radio, PRE-SAFE PLUS Pedestrian Warning Function, Traffic Sign Assist, Active Traffic Jam Assist, PRE-SAFE Impulse Side)
- Upholstery: ARTICO man-made leather
- Radio accessories: Sound personalization (A tailor-made listening experience: Personalizing the sound system makes it easy to achieve your perfect sound setup. A setup assistant with an innovative algorithm works with you to determine your music preferences and adjusts the Burmester® sound system to your wishes. The result is saved in a personal profile.)
- Wheel arch trims in body color
- Wheels: Complete winter wheel sets fitted at the factory
- Auxiliary heater (with auxiliary ventilation)
- Cargo net (This feature protects you from loose items in the luggage compartment. The cargo net is very easy to use. You can attach or remove it in just a few steps.)
- Winter complete wheels M+S 4-way

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was not capable of driving under its own power at the time of inspection, but can be moved on its own axle with the aid of assistance.

Value reducing factors

No.	Component group	Description
1	Door - rear left side	Door edge - Scratch(es) - Smart repair
2	Rear bumper	Spoiler - Scratch(es) - Smart repair
3	Door - front left side	Door edge - Scratch(es) - Smart repair
4	Wheel / tyres	Alloy rim - rear left side - Scratched - Loss in value
5	Wheel / tyres	Tyre - front right side - Damaged - Replace
6	Sill - right side	Cat walk - Broken / torn - Replace
7	Wheel / tyres	Alloy rim - front right side - Scratched - Replace
8	Wheel / tyres	Alloy rim - rear right side - Scratched - Replace
9	Rear bumper	Rear bumper (Eingedrückt/Delle) - Scratched - Replace
10	Front bumper	Front bumper - Scratched - repair according to calculation

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Front bumper	Front bumper - Stone chips - No deduction
4	2nd wheel set	Wheel cover set - complete (Nabenkappen) - Missing - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Provided by user / customer, from 25 May 2024	18.633,39 €

Repainting

No.	Repainting
1	Mudguard - left side, Professionally carried out

Paint coat thickness measurement

Mudguard - left side	183 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area



Figure 10: VIN



Figure 11: Mounted tyres




Figure 12: Documents



Figure 13: Documents



Figure 14: Additional tyres




Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.




Figure 33: Misc.




Figure 34: Misc.




Damage 1: Door - rear left side: Door edge - Scratch(es) - Smart repair



Damage 1: Door - rear left side: Door edge - Scratch(es) - Smart repair



Damage 1: Door - rear left side: Door edge - Scratch(es) - Smart repair




Damage 2: Rear bumper: Spoiler - Scratch(es) - Smart repair



Damage 2: Rear bumper: Spoiler - Scratch(es) - Smart repair




Damage 3: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 3: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 3: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 3: Door - front left side: Door edge - Scratch(es) - Smart repair




Damage 4: Wheel / tyres: Alloy rim - rear left side - Scratched - Loss in value



Damage 4: Wheel / tyres: Alloy rim - rear left side - Scratched - Loss in value



Damage 4: Wheel / tyres: Alloy rim - rear left side - Scratched - Loss in value



Damage 5: Wheel / tyres: Tyre - front right side - Damaged - Replace




Damage 5: Wheel / tyres: Tyre - front right side - Damaged - Replace



Damage 5: Wheel / tyres: Tyre - front right side - Damaged - Replace



Damage 6: Sill - right side: Cat walk - Broken / torn - Replace



Damage 6: Sill - right side: Cat walk - Broken / torn - Replace



Damage 6: Sill - right side: Cat walk - Broken / torn - Replace



Damage 6: Sill - right side: Cat walk - Broken / torn - Replace



Damage 6: Sill - right side: Cat walk - Broken / torn - Replace



Damage 6: Sill - right side: Cat walk - Broken / torn - Replace



Damage 6: Sill - right side: Cat walk - Broken / torn - Replace



Damage 7: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 7: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 7: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 7: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 7: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 8: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 8: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 8: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 8: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 9: Rear bumper: Rear bumper (Eingedrückt/Delle) - Scratched - Replace



Damage 9: Rear bumper: Rear bumper (Eingedrückt/Delle) - Scratched - Replace



Damage 9: Rear bumper: Rear bumper (Eingedrückt/Delle) - Scratched - Replace



Damage 9: Rear bumper: Rear bumper (Eingedrückt/Delle) - Scratched - Replace




Damage 9: Rear bumper: Rear bumper (Eingedrückt/Delle) - Scratched - Replace




Damage 9: Rear bumper: Rear bumper (Eingedrückt/Delle) - Scratched - Replace




Damage 9: Rear bumper: Rear bumper (Eingedrückt/Delle) - Scratched - Replace




Damage 9: Rear bumper: Rear bumper (Eingedrückt/Delle) - Scratched - Replace




Damage 9: Rear bumper: Rear bumper (Eingedrückt/Delle) - Scratched - Replace



Damage 9: Rear bumper: Rear bumper (Eingedrückt/Delle) - Scratched - Replace



Damage 9: Rear bumper: Rear bumper (Eingedrückt/Delle) - Scratched - Replace



Damage 9: Rear bumper: Rear bumper (Eingedrückt/Delle) - Scratched - Replace



Damage 10: Front bumper: Front bumper - Scratched - repair according to calculation




Damage 10: Front bumper: Front bumper - Scratched - repair according to calculation



Damage 10: Front bumper: Front bumper - Scratched - repair according to calculation



Damage 10: Front bumper: Front bumper - Scratched - repair according to calculation



Damage 10: Front bumper: Front bumper - Scratched - repair according to calculation



Damage 10: Front bumper: Front bumper - Scratched - repair according to calculation




Damage 10: Front bumper: Front bumper - Scratched - repair according to calculation



Damage 10: Front bumper: Front bumper - Scratched - repair according to calculation



Damage 10: Front bumper: Front bumper - Scratched - repair according to calculation



Previous damage 1: Side - left



Previous damage 1: Side - left



Previous damage 1: Side - left



Previous damage 1: Side - left



Previous damage 1: Side - left



Previous damage 1: Side - left



Previous damage 1: Side - left



Previous damage 1: Side - left



Repainting 1: Mudguard - left side



Repainting 1: Mudguard - left side