BMW

VIN: WBA6M510X0FL73583



Description

Registration number 2AWA201	**First registration date** 11/08/2021	**Odometer** 143989 km
Color Phytonicblau (metallic)	**Model year** -	**Upholstery** -
Number of doors 5	**Number of seats** -	**Generation** -
Engine displacement 1995	**Max power** 90 KW	

Vehicle Equipments

Rear-view camera	Rain-sensitive wipers	Automatic headlights
Hydraulic tail board	Alloy wheel rims	Electrically foldable door mirrors
Cruise control	SATNAV	Electrically adjustable seats
Park Assist	Climate control	

Statement details

Inspection loc PARC HÖDLMAYR TONGEREN	**Statement date** 22/10/2026	**Inspection approval date** 23/10/2026

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction
001	Personal Data / -	Non Compliant	Carry out

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.




002	Rim / Front Right Rim/Tyre diameter : 17 "	Scratched	Repair






003	Bumper / Back [1] Painted : Yes	Scratched	Painting





004	Wing / Back Right	Scratched	Smart repair




005	Door / Back Right	Dent	Smart repair





006	Door / Front Right	Chip	Acceptable




007	Door sill / Front Right [2]	Scratched	Painting






008	Tailgate / Boot door / -	Sticker	Removal




009	Door sill / Back Left	Scratched	Painting




010	Exterior door mirror shell / Right	Scratched	Acceptable



011	Bumper / Front Painted : Yes	Scratched	Acceptable



[1] Rayures + enfoncement

[2] + enfoncement

Loose Items

- [x] Conformity certificate
- [x] Registration certificate
- [x] Registration certificate owner
- [x] Card key
- [x] Spare Key
- [x] Rear parcel shelf

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Main set of tyres

Front Left	FULDA	225/50/17 Summer	9 mm
Front Right	FULDA	225/50/17 Summer	9 mm
Back Left	HANKOOK	225/50/17 Summer	7 mm
Back Right	HANKOOK	225/50/17 Summer	7 mm

Comments

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.


Pictures


Front left


Rear left


Boot opened



Rear right


Rear passenger compartment


Dashboard from rear seat


Front passenger compartment


Front right




Odometer



Navigation




Vin


Other

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Other




Other



Other



Personal Data / - / Non Compliant



Personal Data / - / Non Compliant



Rim / Front Right / Scratched



Rim / Front Right / Scratched



Rim / Front Right / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched




Bumper / Back / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched




Bumper / Back / Scratched



Wing / Back Right / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Wing / Back Right / Scratched



Door / Back Right / Dent



Door / Back Right / Dent



Door / Back Right / Dent



Door / Front Right / Chip



Door / Front Right / Chip



Door sill / Front Right / Scratched



Door sill / Front Right / Scratched



Door sill / Front Right / Scratched



Door sill / Front Right / Scratched



Tailgate / Boot door / - / Sticker




Door sill / Back Left / Scratched



Door sill / Back Left / Scratched



Exterior door mirror shell / Right / Scratched



Bumper / Front / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.