TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48368264
Order No. / Reference: 27182619
Inspection date: 26 Oct 2026

Manufacturer: Ford	Model: Transit Custom 280 L1H1 LKW VA Trend
VIN: WF0YXXTTGYLC53280	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Transit Custom 280 L1H1 LKW VA Trend	
Vehicle Identification number	WF0YXXTTGYLC53280
Mileage (Read)	135,060 km
First registration	5 Aug 2020
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,995 ccm / 4
Power	79 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Frost Weiß Uni
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Vehicle details

Maintenance booklet / proof	Available / incomplete	**Next maintenance in**	30,000 km
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FV051388
Previous damage / Accident	None detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8566 / BSF 00299		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,800 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R15 104T	Winter tyres on Steel rim with wheel cover	Falken	6mm / 6mm
2)	215/65 R15 104T	Winter tyres on Steel rim with wheel cover	Falken	8mm / 8mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R15 104T	Summer tyres on Steel	Goodyear	8mm / 8mm
2)	215/65 R15 104T	Summer tyres on Steel	Goodyear	8mm / 8mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 11/2030		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 1 battery
- Anti-lock braking system with electronic brake force distribution (EBD)
- roof, flat
- Headliner in driver's cab (up to the partition wall to the cargo area)
- Electronic Stability Program (ESP) with Traction Control System (TCS) (Hill Start Assist - Crosswind Assist - Emergency Brake Assist - Rollover Protection)
- FordPass Connect (including live traffic information and Wi-Fi hotspot: Information about the current status or location of the vehicle, as well as control of selected vehicle functions via smartphone with the FordPass app. Real-time traffic information (in conjunction with audio systems 24 and 25). Wi-Fi hotspot (up to 4G/LTE, for up to 10 mobile devices). Further information about FordPass Connect can be found at https://www.ford.de/fordpass-connect.)
- Interior lighting with delay function (with reading lights at the front)
- Cargo area lighting with activatable switch-off delay (after 30 minutes)
- Package: Style color package (front and rear bumpers and exterior mirror caps painted in body color)
- Front and rear parking pilot system including fog lights
- Radio: Audio system 13 additionally with DAB/DAB+ (Radio (FM/AM) - Four speakers, antenna - Audio remote control on the steering wheel - Bluetooth, USB port and hands-free system - MyFord Dock - additionally with digital radio reception DAB/DAB+ (Digital Audio Broadcasting))
- Sliding door entry light automatically illuminates when the door is opened
- Sliding door: Sliding door, right
- Side protection strips
- Power steering
- Safety kit: First aid kit, warning triangle, 2 wares
- Start-stop system
- Front bumper in body color
- Immobiliser
- Central locking with remote control
- Second key with remote control
- Driver's side airbag
- Battery monitoring (isolating relay function)
- On-board computer (with consumption and mileage information (e.g. remaining range) and outside temperature display)
- Tachometer
- Front electric windows (with quickdown/up function for driver's side)
- Ford Easy Fuel (comfortable fuel filler cap and misfuelling protection)
- Warranty: 2-year Ford new car warranty including Ford Assistance mobility guarantee
- Generator, 240 A
- Cruise control including leather steering wheel (with adjustable speed limiter)
- Transmission: 6-speed transmission
- Lockable glove compartment with lid
- Windscreen washer system heater
- Front air conditioning (including dust and pollen filter)
- Paint finish: Solid color paint
- Steering column, adjustable in height and reach
- Emergency brake assist including emergency brake light (pulsating illumination of the brake lights during hard braking)
- Particulate filter: diesel particulate filter
- Wheel trims
- Wheels/Tires: Spare wheel, steel wheel
- Wheels: Steel wheels 6.5 J x 15 with 215/65 R 15 tires (6.5 J x 15 with 215/65 R 15 tires)
- Headlights: Halogen projector headlights (with LED daytime running lights and fog lights with static cornering lights)
- Mud flaps front and rear
- Low side paneling
- Seat belts (front seat belt tensioners and force limiters - warning system for unfastened driver's seat belt)
- Power outlet: 12-volt connection
- Lashing eyes 8
- Heat-insulating glazing, lightly tinted
- Auxiliary heater, electric

Extra equipment

- Exterior mirrors, electrically adjustable, heated and foldable
- Package: Cargo area protection package "Heavy Duty" (hardwood cargo floor (Delignit) with anti-slip coating including 3 recessed airline rails and high plastic side wall cladding)
- Seats: Seat Package 15 - Partition (load-through hatch), without window (Custom Truck Trend) (Driver's seat, 4-way adjustable (forward/backward, backrest, seat cushion tilt, height) - Double passenger seat with storage compartment under individually foldable seat cushions - Height-adjustable headrests - Integrated tray in the double passenger seat (fold-out) - Heated driver's seat - Heated passenger seat (outer seat) - Inner armrest for driver - Manual lumbar support (driver's seat) - TREND seat cover: fabric - Partition without window with load-through hatch)
- Tire Pressure Monitoring System (TPMS)
- 4 additional winter tires
- Adaptive cruise control
- Conversion high-performance package SVO No: A550
- Exterior mirrors with blind spot assist
- Interior finishing Lot 2
- LED lights in the cargo area
- Package: Visibility Package I (Trend) (Heated windshield)
- Radio: Audio system 16
- Rear swing door without window (without interior mirror)
- Reversing camera with front and rear parking pilot system with fog lights (with image transmission of the rear driving path in the multifunction display [additionally with coupling aid in conjunction with trailer hitch (extra charge)] with high-mounted LED exterior light downlight)
- Tire repair kit (space and weight saving, instead of spare wheel (maximum speed of 80 km/h when used))

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance - No evidence - No deduction
2	Misc.	Main inspection - No evidence - No deduction
3	Instrument panel	Indicator light (Reifendruck) - on - Perform diagnosis
4	Side panel - rear right side	Elbow - Corrosion - Smart repair

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction
2	Boot lid / rear door	Boot lid - dent(s) - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction
4	Wing mirror - left side	Cap - Stone chips - No deduction
5	Door - front left side	Door - Scratch(es) - No deduction
6	Seat - front	Seat cover - left side - Scratch(es) - No deduction
7	Side panel - rear left side	Side panel - Dent / paintcoat damage - No deduction
8	Documents	Service book - Incomplete - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Repainting

No.	Repainting
1	Boot lid / rear door, Professionally carried out
2	Door - rear right side, Professionally carried out
3	Door - front right side, Professionally carried out

Paint coat thickness measurement

Boot lid / rear door	673 µm	Door - rear right side	309 µm
Door - front right side	527 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument cluster



Figure 9: Instrument panel

Figure 10: Interior 360° view (Online Link)



Figure 11: Cargo area




Figure 12: VIN



Figure 13: Mounted tyres




Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Additional tyres



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Damage 3: Instrument panel: Indicator light (Reifendruck) - on - Perform diagnosis



Damage 4: Side panel - rear right side: Elbow - Corrosion - Smart repair



Damage 4: Side panel - rear right side: Elbow - Corrosion - Smart repair



Damage 4: Side panel - rear right side: Elbow - Corrosion - Smart repair



Damage 4: Side panel - rear right side: Elbow - Corrosion - Smart repair



Damage 4: Side panel - rear right side: Elbow - Corrosion - Smart repair



Damage 4: Side panel - rear right side: Elbow - Corrosion - Smart repair



Damage 4: Side panel - rear right side: Elbow - Corrosion - Smart repair



Repainting 1: Boot lid / rear door



Repainting 1: Boot lid / rear door



Repainting 2: Door - rear right side



Repainting 2: Door - rear right side



Repainting 3: Door - front right side



Repainting 3: Door - front right side