ARVAL
BNP PARIBAS GROUP

2CPT861

INSPECTION REPORT

End of contract

GENERAL INFO

File	323174
License plate	2CPT861
Vehicle identification number	TMBJF7NU8N5066393
Dossier	2021 187 039
Make	Skoda Karoq 2.0TDi 85kW Clever
Mileage	112551
First registration	11/10/2022
client availability date	05/10/2026
inspectionDate	07/10/2026










CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





2 CPT 861
KEURING
BELCAR


DAMAGES

Damages	Type	Acceptable
106	Door Rear Left // Polish	Y
116	Wing Rear Left // Polish	Y
136	Bumper Rear // Polish	Y
186	Wing Rear Right // Polish	Y
193	Door Rear Right // Painting	Y
216	Door Front Right // Polish	Y
316	Tyre Front Left // Replace	Y
346	Tyre Front Right // Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures

Door Front Right // Polish-scratch

Door Rear Right // Painting-scratch




Wing Rear Right // Polish-scratch




Bumper Rear // Polish-scratch





Wing Rear Left // Polish-scratch




Door Rear Left // Polish-scratch




Interior Cleaning // Small-stain




Tyre Front Left // Replace-worn




Tyre Front Right // Replace-worn