Skoda

SKODA KODIAQ (NS)(2016->) AMBITION MOTEUR 2,0 LITRE(S) - 110 KW TDI 5 PORTES

VIN: TMBJJ7NS6P8530523



Description

Registration number 2DVV821	**Registration date** 10/07/2023	**Odometer** 201136 km
Color Gris Graphite Métallisé	**Year** 2021	**Upholstery** -
Number of doors 5	**Number of seats** 5	**Generation** -
CO2 167	**Engine displacement** 1968	**Gearbox type** Automatic
Engine type Combustion	**Fuel Type** Diesel	**Number of gears** 7
Drivetrain Front Wheel Drive (FWD)	**Max power** 110 KW	

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

DEKRA

Vehicle Equipments

Standard

3. brake light	8 speaker(s)	center armrest front
multifunction display	airbag driver side	airbag passenger side
airbag passenger side deactivatable	kneebag driver side	sidebag front
alarm system for seat belts	lashing eyes cargo space sideways	immobilizer
lumbar support seat front right	lumbar support seat front left	head rests rear
head rests front	driver assistance system: brake assistant (Audi pre sense front)	rear seatbench split/folding (1/3-2/3)
roof rails	battery 59 Ah	electronic differential lock (Q2)
start-stop button	transmission 7-speed - dual-clutch transmission S-tronic	sunglasses compartment
cargo space partition wall high without window	body: 5-door	remote control for central locking system
air conditioning Climatronic 2-zone	steering column (steering wheel) height-adjustable	steering column (steering wheel) longitudinally adjustable
Electronic Stability Control (ESP)	tire pressure control system	power steering electronically controlled
comfort hands-free equipment Bluetooth	brake discs rear (300 mm x 12 mm)	wheelbase 2791 mm
Longlife-Service	interior equipment decorative trim inserts aluminium brushed	rear window wiper
windshield wiper Aero (flat-blade wiper)	windshield wiper with rain sensor	rear lights LED (crystal glass look)
licence plate illumination LED	refrigerant R 1234 YF	windshield washer jets heated
engine hood insulation	Light-alloy rims	headlight washer system (headlight washer system)
shift/selector lever leather	vehicle speed limiter	window lifter electric front + rear
Type of drive: front-wheel drive	bumper vehicle colour	sun visor right with mirror
sun visor left with mirror	Pneus 215/65 R17 ..T	door handles outside vehicle colour
power outlet (12V outlet) front	power outlet (12V outlet) in trunk/load space	headlight LED
front fog lights	seat belt tensioner rear	model refinement
radio reception digital (DAB+)	braking energy recovery (recovery system)	cruise control (cruise control)
exterior mirror vehicle colour	exterior mirror electrically adjustable and heated, both	exterior mirror electrically folding, all mirror with automatic dimming
interior mirror with automatic dimming	seat covers/upholstery: cloth Ambition black	seat front right height-adjustable
seat front left height-adjustable	Isofix mounts for child seat at rear seat	traction control system (ASR)
audio system Swing with touchscreen	head airbag system (Sideguard)	antilock braking system (ABS)
driver assistance system: safety system SYNC with automatic emergency call	headlight assist with day/night sensor	driver assistance system: hill-start assist (Hill-Holder)
driver assistance system: collision warning system with brake function	driver assistance system: multi-collision brake (Multi Collision Brake)	start/stop system
long-cargo channel (center armrest rear)	VarEq-méthode Equipement Ambition	central locking system
storage bag at front seatbacks	glazing tinted	steering wheel (leather - 2-spoke) with multiple function
daytime running lights LED		

Optional

keyless door release	Parkpilot system front and rear	generator 180 A
reversing camera	voice control for infotainment system	rear lid open+close automatic (Hands-Free-Access system)
trailer coupling preparation	brake discs front (314 mm x 30 mm)	seatback release the rear seat backrest in trunk
Moteur 2,0 litre(s) - 110 kW TDI FAP Catalyseur (DTSB)	low emissions according to emission standard Euro 6d	windshield heated
metallic paintwork	Phonebox	power outlet 230V
roll-up sun protection at side window rear	exterior mirror convex, left	seat heating front
rear spoiler (tailgate / trunk lid)	driver assistance system: driving-profile selection	SCR system (AdBlue technology)
side window rear and rear window darkened	Wireless SmartLink	

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Statement details

Inspection loc
PARC HÖDLMAYR TONGEREN

Statement date
08/09/2026

Inspection approval date
10/09/2026

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction
001	Door sill / Back Right	Scratched	Acceptable



002	Door / Back Right	Scratched	Painting




003	Door / Front Right	Dent	Acceptable



004	Wing extension moulding / Front Right Painted : No	Broken	Replace





005	Wheel arch trim / Front Right	Broken	Replace

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.





006	Bumper / Front Painted : Yes	Broken	Replace






007	Bumper moulding / Front Right Painted : No / Chromed : No	Broken	Replace




008	Windscreen / - Rain sensor : Yes	Chip	Acceptable




Loose Items

- [x] Rear parcel shelf
- [x] Tyre repair kit complete
- [x] Document holder
- [x] Registration certificate owner
- [ ] Toolkit
- [ ] Jack handle crank
- [ ] Slow charging cable (Type 2, Mode 2)
- [ ] Charging cable bag
- [x] Spare Key
- [ ] Service book
- [ ] Towing hook
- [ ] Cargo net
- [ ] Remote key
- [ ] Security Kit
- [x] Triangle
- [ ] Warranty booklet
- [ ] Hook /Hicth ball
- [ ] Card key
- [ ] Locking wheel nuts key
- [x] Conformity certificate
- [ ] Spare wheel tyre
- [ ] Quick charging cable (Type 2, Mode 3)
- [x] Safety vest
- [ ] Remote control
- [ ] Compressor tyre repair kit
- [x] First aid kit
- [x] User manual
- [ ] Jack
- [ ] Load cover
- [ ] Refill tyre repair kit
- [x] Registration certificate
- [ ] Satellite navigation
- [ ] In-car tools
- [ ] Locking wheel nut

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Main set of tyres

Front Left	PIRELLI	215 / 65 / 17 / Summer	2 mm
Front Right	PIRELLI	215 / 65 / 17 / Summer	2 mm
Back Left	PIRELLI	215 / 65 / 17 / Summer	3 mm
Back Right	PIRELLI	215 / 65 / 17 / Summer	3 mm

Comments

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures



Front left



Rear left



Boot opened



Rear right



Rear passenger compartment



Dashboard from rear seat



Front passenger compartment



Front right




Odometer



Navigation



Spare Tyre




Vin


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Other



Other



Other



Door sill / Back Right / Scratched



Door / Back Right / Scratched



Door / Back Right / Scratched



Door / Front Right / Dent



Wing extension moulding / Front Right / Broken



Wing extension moulding / Front Right / Broken



Wing extension moulding / Front Right / Broken



Wheel arch trim / Front Right / Broken



Wheel arch trim / Front Right / Broken



Bumper / Front / Broken



Bumper / Front / Broken




Bumper / Front / Broken

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Bumper / Front / Broken



Bumper moulding / Front Right / Broken



Bumper moulding / Front Right / Broken



Windscreen / - / Chip



Windscreen / - / Chip

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.