TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz

Expertise

Protocol number: 48283917
Order No. / Reference: 27130865
Inspection date: 23 Oct 2026

Manufacturer: Audi	Model: A4 Avant 50 TDI quattro tiptronic S line
VIN: WAUZZZF47RA125772	





Vehicle details

Manufacturer / Type / Model / Equipment	
Audi A4 Avant 50 TDI quattro tiptronic S line	
Vehicle Identification number	WAUZZZF47RA125772
Mileage (Read)	83,585 km
First registration	16 Jul 2024
Number of holders	1
Next periodical technical inspection	07/2027
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	2,967 ccm / 6
Power	210 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	All-wheel drive
Type of vehicle	Car station wagon
Colour / colour code	Mythosschwarz Metallic (Y9T)
Doors / Seats	5 / 5
Upholstery type	Artificial leather
Colour of upholstery	Black-Unknown
Re-import	no
Vehicle with smoke odor	no
readiness to drive	Roadworthy

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	7,800 km
Last service on / at	09/2025 at 61,305 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HD529710
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	0588 / BXA 00407		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,385 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	255/35 R19 96Y	Summer tyres on Light alloy	Pirelli	5mm / 5mm
2)	255/35 R19 96Y	Summer tyres on Light alloy	Pirelli	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/50 R17 98V	Winter tyres on Light alloy	Pirelli	7mm / 7mm
2)	225/50 R17 98V	Winter tyres on Light alloy	Pirelli	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 05/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- AdBlue tank (12 liters)
- Airbag: Front side airbags and head airbag system
- All-wheel drive "quattro" with self-locking center differential
- Traction control (ASR)
- Audi drive select
- Audi pre sense city
- Exterior mirror housings in body color
- third brake light, raised
- S line roof spoiler
- Decorative inlays diamond lacquer silver grey
- Tachometer
- Electromechanical parking brake
- Electronic Differential Lock (EDS)
- Driver Information System
- electric window regulators
- Remote key, without SafeLock
- Cruise control system with speed limiter
- rear window wiper
- Interior mirror dimming
- ISOFIX child seat attachment and Top Tether for the outer rear seats
- Headrests (5)
- Manual cargo cover
- Steering wheel: Leather steering wheel in 3-spoke design with multifunction
- Mild hybrid
- Non-smoking version
- Radio accessories: 8 speakers (passive) front and rear
- Tire pressure monitoring system
- Headlights using LED technology
- Electromechanical power steering
- Seats: Rear seat backrest foldable
- First aid kit with warning triangle
- Electronic immobilizer
- Central locking "Keyless-Go" without deadbolt
- Airbag for driver and front passenger
- Accent areas matte black
- Anti-lock braking system (ABS)
- Audi connect emergency call & service with Audi connect Remote & Control
- Electrically adjustable and heated exterior mirrors
- Vehicle tool kit
- Fabric headliner
- Black roof rails
- Diesel particulate filter (DPF)
- Door sill trims with aluminum inlay at the front, illuminated, with S lettering
- Electronic Stability Control (ESC)
- Chassis: Sport chassis
- Window channel strips in black (rubber)
- front and rear floor mats
- Transmission: 8-speed automatic transmission tiptronic
- Interior lighting
- Child lock
- Automatic air conditioning
- boot floor mat
- Fuel tank with increased filling volume (58 l)
- LED taillights
- Steering column, manually adjustable in height and axis
- Light/rain sensor
- front center armrest
- Radio: MMI Radio plus
- Radio accessories: Digital radio reception (DAB)
- Tire repair kit (compressor and tire sealant, maximum permissible speed 80 km/h)
- Fabric seat covers Index
- Start-stop system
- Glazing: Windscreen in heat-insulating and acoustic glazing

Extra equipment

- AdBlue tank (24 liters) (larger tank for AdBlue solution to reduce nitrogen oxides in the exhaust gas using an SCR system)
- Electrically adjustable, heated and folding exterior mirrors, automatically dimming on both sides
- Decorative inlays in matt brushed aluminum
- Rear parking sensors
- High beam assist
- Hold assist (holds the vehicle indefinitely after stopping on typical road inclines and declines. The system is activated by pressing a button and allows the driver to start off comfortably.)
- Comfort key with sensor-controlled luggage compartment release, electric tailgate including anti-theft alarm system (including visual differentiation on the top and bottom of the key; access authorization system: The vehicle key only needs to be carried with the vehicle; locking and unlocking of the vehicle from the outside via sensors on all door handles. The tailgate can also be opened when the vehicle is locked. Additionally, a foot gesture (kick movement) below the rear bumper unlocks the tailgate and allows it to swing open automatically.)
- Storage and luggage compartment package (flexible transport of items and comfort while traveling, consisting of: - storage net on the back of the front seatbacks - cupholder in the rear center armrest - storage compartment on the driver's side - lockable glove compartment in the luggage compartment: - luggage compartment net - net recesses left and right - tension strap right)
- Business Package (MMI Navigation plus with MMI touch (including driver information system with color display) - Audi phone box - Leather steering wheel in 3-spoke design with multifunction plus - Heated front seats - Automatically dimming, frameless interior mirror - Electrically adjustable, heated and folding exterior mirrors, automatically dimming on both sides - Rear parking aid - High-beam assistant - Manual sunshade for the rear door windows)
- S line interior package (sports seats in front - black fabric/leather combination with S embossing in the backrests of the front seats - 3-spoke leather steering wheel with multifunction plus including steering wheel grips in perforated leather and S emblem - brushed matt aluminum inlays - glossy black accent surfaces - illuminated front door sill trims with aluminum inlays and S lettering - stainless steel pedals and footrest - black fabric headliner - velour floor mats in the front)
- Rail system with fixing set (in the luggage compartment, with telescopic rod, fixing strap and variable lashing eyes for individual partitioning of the luggage compartment and for fixing objects)
- Audi virtual cockpit plus (Innovative, fully digital instrument cluster with 12.3-inch display, full HD resolution with additional graphic display options: Classic, Sport and Dynamic design - For flexible and needs-based display of the respective information according to the driver's needs: speed/RPM, map display, Audi connect services, radio/media information, etc. - VIEW button in the multifunction steering wheel)
- Comfort automatic climate control 3-zone (in addition to the automatic climate control: - climate control unit with large TFT display and capacitive rocker switches - electronically regulates the air temperature and distribution individually for driver and front passenger - additional climate control unit for setting the rear compartment temperature in the rear center console - automatic recirculation control with dust and odor separating allergen filter - residual heat utilization)
- Steering wheel: Sport contour leather steering wheel in 3-spoke design, flattened at the bottom with multifunction plus (with more contoured steering wheel rim; adjustable in height and distance; with 12 multifunction buttons for convenient operation of the available infotainment features with shift paddles for manual gear changes in automatic transmissions)
- City Assistance Package with Parking Assistance Package in conjunction with Business Package (City: - Parking aid plus - Reversing camera - Lane change warning - Audi pre sense basic - Audi pre sense rear - Exit warning and rear cross traffic assist Parking: - Parking assistant - Surround view cameras)
- Competition Edition Plus package (A4 Avant S line) (Metallic paint, pearl effect, Audi Sport wheels, 5-arm flag, anthracite black, gloss-printed, 8.5 J x 19, tires 245/35 R 19; Black Optics Plus package, deletion of performance/technology lettering, red painted brake calipers; Gloss black: radiator grille, side air intakes, blade and radiator grille, exterior mirror housings, side sill trims, diffuser; roof rails, RS4 roof spoiler, standard exhaust system - chrome, "Audi Rings" design film, Matrix LED headlights, LED entry lights with logo projection at the front (diamond-shaped S logo); Ambient Lighting Plus package)
- Radio accessories: Bang & Olufsen Premium Sound System with 3D sound (19 speakers (including center speaker/subwoofer and additional 3D sound tweeters and midrange drivers) - 16-channel amplifier with 755 watts - illuminated front speaker grilles - speed-dependent volume adjustment - spatial sound reproduction thanks to the new 3D sound feature. This is created by additional speakers in the A-pillar, by the midrange drivers and by Fraunhofer Symphoria technology.)
- Seat covers in fine Nappa leather with S embossing (seat center panels, seat side bolsters, headrest center panels and center armrest in fine Nappa leather black or rotor grey, for S models for sport seats plus front additionally in fine Nappa leather magma red - with contrasting stitching - with S embossing in the backrests of the front seats fine Nappa leather)

- Seats: Sport seats plus front (electric adjustment of seat height, seat fore/aft position, seat and backrest tilt; manual adjustment of belt height - pronounced seat side bolsters for better lateral support in curves - extendable thigh support - pneumatic backrest bolster adjustment - pneumatic lumbar support with massage function - integrated front headrests - L-shaped headrests for 3 rear seats - S-embossing in the backrests of the front seats - with diamond stitching)
- Front seat heating
- Glazing: Sun protection glazing, tinted (rear window, rear door and side windows tinted)
- Seats: Front seats electrically adjustable (with electric adjustment of seat height, seat longitudinal position, seat and backrest tilt)
- Telephone: Audi Smartphone Interface (The Audi smartphone interface (Android Auto and Apple CarPlay) connects your smartphone to your Audi and seamlessly displays your smartphone content directly on the MMI display. Navigation, telephony, music, and selected third-party apps can be conveniently controlled via the MMI touchscreen and voice control. The connection can be established either using a suitable USB cable or wirelessly.)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Seat - front	Seat - right side (Rückseite verkratzt) - Scratch(es) - Loss in value
2	Instrument panel	Indicator light (Notruf) - on - Diagnosed and repair if necessary
3	Front bumper	Front bumper (Lackablösung) - Paint defect - Repair and paint
4	Bonnet	Bonnet - Dent / paintcoat damage - Repair and paint
5	Vehicle glazing	Windscreen (Abplatzung im Sichtbereich) - Stone chips - Replace

Wear and tear

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratch(es) - No deduction
2	Mudguard - left side	Mudguard - left side - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer, from 29 Jan 2026	952,65 €
2	Front, Provided by user / customer, from 25 Dec 2024	5.253,73 €
3	Side right, Provided by user / customer, from 19 Oct 2025	6.549,51 €

Repainting

No.	Repainting
1	Roof rail - right side, Side panel - rear right side, Door - front right side

Paint coat thickness measurement

Roof	118 µm	Roof rail - left side	103 µm
Roof rail - right side	176 µm	Boot lid / rear door	131 µm
Mudguard - left side	109 µm	Mudguard - right side	111 µm
Bonnet	118 µm	Side panel - rear left side	107 µm
Side panel - rear right side	181 µm	Door - rear left side	116 µm
Door - rear right side	121 µm	Door - front left side	118 µm
Door - front right side	179 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Additional tyres




Figure 16: Navigation



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Damage 1: Seat - front: Seat - right side (Rückseite verkratzt) - Scratch(es) - Loss in value




Damage 1: Seat - front: Seat - right side (Rückseite verkratzt) - Scratch(es) - Loss in value




Damage 2: Instrument panel: Indicator light (Notruf) - on - Diagnosed and repair if necessary



Damage 2: Instrument panel: Indicator light (Notruf) - on - Diagnosed and repair if necessary




Damage 3: Front bumper: Front bumper (Lackablösung) - Paint defect - Repair and paint



Damage 3: Front bumper: Front bumper (Lackablösung) - Paint defect - Repair and paint




Damage 3: Front bumper: Front bumper (Lackablösung) - Paint defect - Repair and paint



Damage 3: Front bumper: Front bumper (Lackablösung) - Paint defect - Repair and paint



Damage 3: Front bumper: Front bumper (Lackablösung) - Paint defect - Repair and paint



Damage 4: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 4: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 4: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 5: Vehicle glazing: Windscreen (Abplatzung im Sichtbereich) - Stone chips - Replace




Damage 5: Vehicle glazing: Windscreen (Abplatzung im Sichtbereich) - Stone chips - Replace



Damage 5: Vehicle glazing: Windscreen (Abplatzung im Sichtbereich) - Stone chips - Replace




Damage 5: Vehicle glazing: Windscreen (Abplatzung im Sichtbereich) - Stone chips - Replace



Wear and tear 1: Rear bumper: Rear bumper - Scratch(es) - No deduction



Wear and tear 1: Rear bumper: Rear bumper - Scratch(es) - No deduction



Wear and tear 1: Rear bumper: Rear bumper - Scratch(es) - No deduction



Wear and tear 2: Mudguard - left side: Mudguard - left side - Scratch(es) - No deduction



Wear and tear 2: Mudguard - left side: Mudguard - left side - Scratch(es) - No deduction



Roof rail - right side: 176 µm



Side panel - rear right side: 181 µm



Side panel - rear right side: 181 µm



Door - front right side: 179 µm



Door - front right side: 179 µm