TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48404594
Order No. / Reference: 27216299
Inspection date: 28 Oct 2026

Manufacturer: Volkswagen	Model: Transporter T6.1 4MOTION Kurz
VIN: WV1ZZZ7HZMX016039	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Transporter T6.1 4MOTION Kurz	
Vehicle Identification number	WV1ZZZ7HZMX016039
Mileage (Read)	61,932 km
First registration	20 May 2021
Number of holders	2
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Manual / 6
Type of drive	All-wheel drive
Type of vehicle	Van
Colour / colour code	Candy White (B9A)
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black-Grey

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	12,900 km
Last service on / at	07/2025 at 48,809 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GA787028
Previous damage / Accident	None detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / BXT 53882		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,800 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/65 R16 107T	All-season tyres on Steel rim with wheel cover	Falken	6mm / 6mm
2)	205/65 R16 107T	All-season tyres on Steel rim with wheel cover	Falken	6mm / 6mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments and boxes (glove compartment with lockable flap)
- 4MOTION all-wheel drive (permanent)
- Electrically adjustable and heated exterior mirrors
- Hill Start Assist
- third brake light
- Tachometer
- Chassis: 16" chassis with 16" brake system
- Electric windows, front
- Transmission: 6-speed transmission
- Heating system with electronic control
- Headrests (2)
- Paint finish: Solid
- Multi-collision brake
- Particulate filter: Diesel particulate filter (incl. SCR and AdBlue tank)
- Radio accessories: 2 speakers (wideband)
- Wheels: Tire Mobility Set (12-volt compressor and tire sealant)
- Keys for locking system: 2 remote control flip keys
- Electromechanical power steering (speed-dependent control, steering column height and length adjustable)
- Start-stop system (with brake energy recuperation)
- Telephone: Mobile phone interface
- First aid kit, warning triangle and high-visibility vest
- Electronic immobilizer
- Central locking with remote control and interior operation
- Airbag for driver and front passenger (with front passenger airbag deactivation - seat belt tensioners for the outer seats)
- Exterior mirrors, left and right convex
- Floor coverings: Rubber floor covering in the driver's cab
- Braking systems: Electronic Stability Program, ABS, ASR (with deactivation button), EDS (Hill Start Assist, Brake Assist)
- Fresh air system with multi-stage fresh air blower (recirculation flap, center vents and defroster nozzles)
- Child safety lock, electrically operated
- Fuel tank with a 70-liter tank capacity
- Headlight range control
- Non-smoking version (12V socket and cup holder in the dashboard)
- Radio: Digital radio reception (DAB+)
- Wheels/Tire Accessories: Wheel covers for 16" wheels
- Sliding door in the passenger/cargo compartment: sliding door on the right
- Crosswind assist
- Seat belts: Three-point automatic seat belts (height-adjustable on the outer seats in the driver's cab)
- Daytime running lights (continuously switched on while driving)
- Lashing eyes for securing cargo
- Green thermal insulation glazing
- Registration as a truck

Extra equipment

- Rigid towbar (including trailer stabilization)
- Bridgestone T6.1 205/65 R16 107/105T M+S T6.1 Wint
- Roof rails/roof load carrier: Mounting rails on the roof (preparation for sliding roof load carriers)
- Driver assistance systems: Front Assist area monitoring system with City Emergency Braking function
- Windows: Front window and closed rear side wall, in the cargo/passenger compartment, right
- Total weight: Permissible total weight 3000 kg
- Cruise control system including speed limiter
- Rear window with heat-insulating glazing, heated, and rear window wiper/washer system
- Air conditioning in the driver's cab with electronic control (heating in the cargo/passenger compartment, separately controllable)
- Multifunction display "Plus" with fatigue detection (Multifunction display "Plus" with black and white display)
- ParkPilot in the rear area
- Radio "Composition Colour" (Radio "Composition Colour" with 6.5" touchscreen, 2 USB ports (Type C) in the dashboard, 4 speakers: 2 tweeters, 2 woofers, App-Connect)
- "Transporter" lettering on the fender, no lettering on the rear
- Seat configuration - 4. Lumbar support: Lumbar support (manually adjustable) for single seat in the driver's cab, left.
- Auxiliary heaters/parking heaters: Water-based auxiliary heater with programmable parking heater function
- Batteries: 2nd battery (75 Ah, AGM) with isolating relay and battery monitoring
- Driver assistance systems: Rearview camera "Rear View" ((static lines))
- Chassis: Reinforced suspension, damping and stabilizers (suitable for rough roads) (permissible front axle load 1,680 kg)
- Fleet management system interface (electrical terminal block and function control unit 1 with body manufacturer (ABH) programming)
- Rear wing doors with windows, heated (Rear wing doors with window cutouts - Rear wing door locking with unlocking function from inside - Rear window, heated - Safety interior mirror, dimmable)
- Steering wheel: Multifunction leather steering wheel (3 spokes)
- Fog lights including cornering lights
- Upholstery: Robust fabric seat covers, "Robusta" design in the driver's cab (artificial leather, "Mesh" design for existing seats in the passenger compartment)
- Tire pressure monitoring system
- Mud flaps, front and rear
- Seat configuration - 3. Seat settings: Height adjustment for the left single seat in the driver's cab
- Seat configuration - 5. Armrests: Armrests for the left seat in the driver's cab
- Sortimo conversion
- Power outlets: 2 12-volt sockets in the dashboard
- Telephone: Mobile phone interface "Comfort" (with inductive charging function)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - front right side	Door - Scratch(es) - Smart repair
2	Side panel - rear right side	Side panel - Dent / paintcoat damage - Smart repair
3	Roof	Roof - Dent / paintcoat damage - Smart repair
4	Body	Body - Glued / labelled - De-glue / neutralise
5	Sliding door, right	Sliding door - Scratch(es) - Paint
6	Vehicle glazing	Windscreen - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Wheel / tyres	Wheel cover - front right side - Scratch(es) - No deduction
2	Wheel / tyres	Wheel cover - rear right side - Scratch(es) - No deduction
3	Boot lid / rear door	Rear door - right side - dent(s) - No deduction
4	Rear bumper	Rear bumper - Scratch(es) - No deduction
5	Front bumper	Front bumper (unpainted) - Scratch(es) - No deduction
6	Bonnet	Bonnet - Stone chips - No deduction
7	Wing mirror - right side	Cap - Scratch(es) - No deduction
8	Door - rear left side	Door - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Equipment - Tirefit complete

Repainting

No.	Repainting
1	Boot lid / rear door, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Boot lid / rear door	231 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Damage 1: Door - front right side: Door - Scratch(es) - Smart repair



Damage 1: Door - front right side: Door - Scratch(es) - Smart repair



Damage 2: Side panel - rear right side: Side panel - Dent / paintcoat damage - Smart repair




Damage 2: Side panel - rear right side: Side panel - Dent / paintcoat damage - Smart repair



Damage 3: Roof: Roof - Dent / paintcoat damage - Smart repair



Damage 3: Roof: Roof - Dent / paintcoat damage - Smart repair



Damage 3: Roof: Roof - Dent / paintcoat damage - Smart repair



Damage 4: Body: Body - Glued / labelled - De-glue / neutralise



Damage 4: Body: Body - Glued / labelled - De-glue / neutralise



Damage 5: Sliding door, right: Sliding door - Scratch(es) - Paint



Damage 5: Sliding door, right: Sliding door - Scratch(es) - Paint



Damage 5: Sliding door, right: Sliding door - Scratch(es) - Paint




Damage 5: Sliding door, right: Sliding door - Scratch(es) - Paint



Damage 5: Sliding door, right: Sliding door - Scratch(es) - Paint



Damage 6: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 6: Vehicle glazing: Windscreen - Broken / torn - Replace



Wear and tear 8: Door - rear left side: Door - dent(s) - No deduction



Wear and tear 8: Door - rear left side: Door - dent(s) - No deduction



Repainting 1: Boot lid / rear door



Repainting 1: Boot lid / rear door