TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48593445
Order No. / Reference: 27272213
Inspection date: 10 Nov 2026

Manufacturer: Hyundai	Model: TUCSON 1.6 T-GDi 48V-Hybrid 4WD DCT Trend
VIN: TMAJD81BHMJ097094	





Vehicle details

Manufacturer / Type / Model / Equipment	
Hyundai TUCSON 1.6 T-GDi 48V-Hybrid 4WD DCT Trend	
Vehicle Identification number	TMAJD81BHMJ097094
Mileage (Read)	106,534 km
First registration	13 Aug 2021
Number of holders	1
Next periodical technical inspection	11/2028
(Report on hand)	
Fuel type	Hybrid Petrol / E
Engine displacement / Cylinder	1,598 ccm / 4
Power	132 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	All-wheel drive
Type of vehicle	SUV
Colour / colour code	Phantom Black Mineraleffekt
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black

Vehicle details

Maintenance booklet / proof	Available / complete	**Next maintenance in**	426 km
Last service on / at	03/2026 at 91,960 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GF831090
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	1349 / AFY 00015		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,170 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R18 104V	Winter tyres on Light alloy	Continental	6mm / 6mm
2)	235/55 R18 104V	Winter tyres on Light alloy	Continental	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 08/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage options
- Adaptive Cruise Control with Stop Function (ASCC)
- Airbag: Front airbags for driver and front passenger
- Airbag: Curtain airbags extending to the rear seats
- Alarm system
- Trailer Stability Assist (TSA)
- Autonomous emergency braking assistant including front collision warning
- Exterior mirrors with integrated turn signals
- Hill Descent Control (DBC)
- On-board computer
- Roof rails
- Display, 10.25-inch color touchscreen
- Rear parking sensors
- Electronic Stability Control (ESC)
- Electric windows front and rear
- luggage compartment cover
- Transmission: 7-speed DCT
- Rear window wiper concealed under roof spoiler
- ISOFIX child seat attachment at the rear
- Headrests (5) front and rear height adjustable
- LED daytime running lights
- Heated steering wheel
- multifunction steering wheel
- light sensor
- Front center armrest with storage compartment
- Package: Function
- Package: Navigation
- Particle filter
- Radio: Audio system
- Radio accessories: Apple CarPlay, Android Auto
- Tire Pressure Monitoring System (TPMS)
- Wheels: Tire repair kit
- Tinted windows all around
- Seat belts
- Seats: Driver's seat height adjustable
- Seats: Rear seat backrest split 40:20:40, foldable
- Lane Following Assist (LFA)
- Static cornering lights
- Phone: Smartphone holder with wireless charging function
- USB charging ports (2), rear
- Glazing: Heat-insulating windshield
- Central locking with remote control
- ABS with EBV
- Airbag: Center airbag between driver and passenger
- Airbag: Front side airbags
- Active Lane Keeping Assist (LKA)
- All-wheel drive, automatically engaging
- Attention Assistant (DAW)
- Electrically folding exterior mirrors
- Electrically adjustable and heated exterior mirrors (from inside)
- Hill Start Assist (HAC)
- Brake Assist (BAS)
- Roof spoiler with 3rd brake light
- Tachometer
- Front parking sensors
- Vehicle Stability Management (VSM)
- High Beam Assist (HBA)
- Cruise control with limiter
- Heated rear window
- Interior mirror automatically dimming
- Child safety locks on the rear doors
- LED taillights
- Leather steering wheel and gearshift lever
- Steering wheel adjustable for height and reach
- Steering wheel: Paddle shifters
- Armrest - centre, rear
- Emergency call system (eCall)
- Package: LED grill design
- Electronic parking brake (EPB) with Auto Hold
- Upholstery: Cloth
- Radio: Digital radio reception (DAB+)
- Rain sensor
- Wheels: Alloy wheels 7.5 J x 18 with tires 235/55 R 18
- Rear view camera
- Power steering
- Seats: Passenger seat height adjustable
- Seats: Driver's seat with adjustable lumbar support
- Smart key system with start-stop button
- Start/Stop System
- 12-volt power outlet, front and in the luggage compartment
- USB charging port, front
- Dark tinted glazing from the B-pillar back
- Electronic immobilizer

Extra equipment

- Package: Family (3-zone automatic climate control - Rear Occupant Alarm (ROA) - Sunshade on the rear door windows)
- Electrically operated tailgate
- Paint finish: Mineral effect two-tone paint

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Door - front left side	Door - Scratch(es) - Smart repair
3	Door - rear left side	Door - Scratch(es) - Smart repair
4	Side panel - rear right side	Side panel - Scratch(es) - Paint
5	Door - rear right side	Door - Scratch(es) - Paint
6	Mudguard - left side	Mudguard - left side - Scratch(es) - Paint
7	Mudguard - right side	Mudguard - right side - Dent / paintcoat damage - Paint

Wear and tear

No.	Component group	Description
1	Body	Body (Waschanlagenspuren) - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Documents




Figure 16: Navigation




Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.




Figure 32: Misc.



Figure 33: Misc.




Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Door - front left side: Door - Scratch(es) - Smart repair




Damage 2: Door - front left side: Door - Scratch(es) - Smart repair



Damage 3: Door - rear left side: Door - Scratch(es) - Smart repair



Damage 3: Door - rear left side: Door - Scratch(es) - Smart repair



Damage 4: Side panel - rear right side: Side panel - Scratch(es) - Paint



Damage 4: Side panel - rear right side: Side panel - Scratch(es) - Paint



Damage 4: Side panel - rear right side: Side panel - Scratch(es) - Paint




Damage 5: Door - rear right side: Door - Scratch(es) - Paint



Damage 5: Door - rear right side: Door - Scratch(es) - Paint



Damage 5: Door - rear right side: Door - Scratch(es) - Paint



Damage 6: Mudguard - left side: Mudguard - left side - Scratch(es) - Paint




Damage 6: Mudguard - left side: Mudguard - left side - Scratch(es) - Paint



Damage 6: Mudguard - left side: Mudguard - left side - Scratch(es) - Paint



Damage 7: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Paint



Damage 7: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Paint



Damage 7: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Paint