BMW X1



Vehicle information


Brand:	**BMW**	License plate:	**2BTZ516**
Gearbox:		Body color:	
Model:	**X1**	LEVEL:	**WBA71AB0805V17240**
Fuel type:		Power:	**92 kW**
Version:	**1.5 XDRIVE25E PHEV 162KW)**	First registration	**23/03/2022**
Mileage:	**143160 km**	Number of doors:	

Summary of damages



Before	1
RIGHT	2
LEFT	2
Interior	2
Roof & other	1


Commercial photos






















Made in Germany
BAYERISCHE MOTOREN WERKE AG
e1*2007/46*1676
WBA71AB0805V17240
2330 kg
3080 kg
1- 1110 kg
2- 1270 kg


Equipment corresponding to the VIN according to the manufacturer's information


Center armrest	Airbag	Alarm	Roof bars
Rain sensor	Distance control	Battery current	Power steering
Windscreen wipers / rear nozzles	Electrical operation of windows	GPS	Alloy wheels
Fog lights	Electrically adjustable mirrors	Heated front seats (ECS&B)	Sport Seats
Adjustable lumbar support	Phone	Central locking	Leather steering wheel
Multifunction steering wheel			

Options according to the inspector


GPS	**Yes**

Damages

Left rear wing
repaired
. No repairs
.



Bodywork
Damaged - Acceptable.
Roof & other



Ignition key
- Worn - Acceptable
- Interior





Damaged **Interior**
- Acceptable
Interior







Windshield Chip
(s)
Acceptable
Front

Front Right Tire
Worn
- Replace
Right




Right rear door
repaired.
No repairs
.



Left rear door repaired . No repairs .



Tires

Front Left
Summer
Aluminum
225/55/17/97/W
Continental
4.0 mm

Front Right
Summer
Aluminum
225/55/17/97/W
Continental
4.0 mm

Left Back
Summer
Aluminum
225/55/17/97/W
Continental
5.0 mm

Rear Right
Summer
Aluminum
225/55/17/97/W
Continental
4.0 mm

Controls

Category	**Private vehicle**	Registration certificate - home address section	**No**
Vehicle registration certificate	**Yes**	Certificate of Conformity	**Yes**
Compressor	**P/A**	Interview	**OK**
Interview	**over 33000 km**	Repair kit	**P/A**
Number of charging cables (220V)	**1**	Nbr cable de charge (charge rapide)	**1**
Nbre clés total	**2**	Réinitialisation des paramètres d'usine	**Oui, le véhicule a été réinitialisé aux paramètres d'usine**
Type de carnet d'entretien	**Entretien digital**		

Détails du NIV

ABS (antiblocage des freins)	Accès confort	Accoudoir central arrière avec 2 porte-boissons
Accoudoir central AV	Actionnement automatique du hayon	Active Guard
Adaptive LED-Headlights	Affichage de la pression de gonflage	Airbag conducteur
Airbag passager	Airbags latéraux avant	Airbags tête avant et arrière
Antidémarrage électronique (EWS III)	Appuie-tête AR (3)	Appuie-tête AV
ASC - X (control stabilité)	Avertisseur acoustique pour piétons	Bac de rangement à gauche/droite du coffre
Banquette AR régl.inclinaison et rabat.40/20/40	Batterie haute tension garantie 6 ans 100.000 km	BMW TeleServices
Boulons antivol	Bouton start/stop	Brake Energy Regeneration
Câble de charge rapide+câble standard	Caméra de recul	CBC (cornering brake control)
Ceintures à réglage manuel en hauteur	Ceintures arrière 3 points	Ceintures AV aut.+prétens.+limiteur de tension
Ceintures de sécurité AV à 3 points	Ciel de pavillon en anthracite	Climatisation à réglage électronique 2 zones
Climatiseur indépendant	Compartiment rabattable tableau bord côté cond.	Compartiment sous le fond du coffre
Connected eDrives Services	ConnectedDrive Services (BMW Online) via SIM	Connexions AUX-IN/USB dans la console centrale
Cruise Control avec fonction freinage	DAB-tuner	DBC (contrôle dynamique de freinage)
Désactivation airbag passager	Driving Assistant Plus (ACC+Traffic-queue)	Driving Experience Control incl. ECO PRO
DSC - Contrôle dynamique de la stabilité	DTC (Contrôle Dynamique de Traction)	Eclairage diurne
ECO PRO	Eléments extérieurs en Aluminium satiné	Espace de rangement sous le siège conducteur
Essuie-glace AR	Extension de garantie BMW jusqu'à 3 ans	Feux arrière en LED avec iconic design 3D
Feux stop adaptatifs	Filet au dos des sièges avant	Filet de séparation du compartiment à bagages
Filet multi-usage	Filtre à particules Otto (OPF)	Fixation Isofix sièges enfants AR
Fonction Auto start/stop	Gicleurs de lave-glace chauffants	Head-Up Display
Inserts Aluminium Längsschliff fein+Perlglanz Chr.	Inserts Oxidesilber dark matt+Schwarz hochglänzend	Intelligent Emergency Call - eCall
Intérieur sensatec	Intérieur tissu Grid	Interrupteur de verrouillage central
JAV rayons doubles 564 7.5Jx17''+225/55	JAV rayons en V 560 7.5Jx17''+225/55	Kit éclairage
Kit rétroviseurs	Kit sécurité (triangle-trousse-extincteur-veste)	LED Headlights
Lève-vitres électriques à l'arrière	Littérature de bord en néerlandais	Media: radio Pro.coul.6.5''+6HP+USB+AUX+Bluet.
Miroir de courtoisie pour conducteur et passager	Naseaux contours chromés+barreaux Schwarz hochgl.	Ordinateur de bord
Park Distance Control (PDC) à l'arrière	Park Distance Control (PDC) avant et arrière	Peinture métallisée
Peinture unie Schwarz	Performance Control	LED fog lights
Cup holder in the center console (2)	Apple CarPlay preparation	Additional 12V socket (passenger legroom)
Power outlet (12V) in luggage compartment	Power outlet in the center console	Aluminium roof mounting rails
Black roof mounting rails	Storage in the center console	Headlight reminder
Auto-dimming interior rearview mirror.	Heated and folding electric mirrors	Body-colored exterior mirrors
Electric and heated exterior mirrors	Retaining strap on the side wall of the trunk	Rain sensor and light sensor
Servotronic	Heated front seats	Height-adjustable front seats
BMW sport seats for driver and passenger	Sound system	Lumbar support for driver and passenger
Alarm system with remote control	Navigation Plus system with Head-Up Display	Velvet carpeting at the front and rear
Convenient telephony with wireless charging	Panoramic glass sunroof	Warning triangle and first aid kit
Third stop light	Tool kit	Central locking with collision sensor
Central locking with remote control	German language version	Dutch language version
Heat-insulating windows tinted green	Electric front windows with comfort/anti-pinch closure	Tinted rear windows
Heated steering wheel	Multifunction steering wheel	Leather sports steering wheel

Information on the content and scope of the inspection report:

- The evaluation is based on the sales standards specified by the client.
- Acceptable wear and tear according to sales standards is not always documented in this condition report.
- The specified repair methods and/or resulting repair times were determined taking into account modern industrial repair methods.
- The reseller must assess individual repair costs.
- The inspection was carried out without dismantling. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.