
MACADAM







Polestar 2: N319KF

Vinnumber:	**LPSVSECEKNL054360**	Versionname:	**Polestar 2 165kW/ 63kWh Single Motor Standard Range**
First Registrationdate:	**19/11/2021**	Fiscalpower:	
Expertise Mileage:	**129164**	Power Kw:	**165**
Bodytype:		Body colour	**Void**
Gearbox:	**Automatic**	Paint type	**Opaque**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Electric**	Parking lot	**1111**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**No**		

Options

Number of keys total	**2**	Rear parking sensors	
GPS		Rear view camera	
Autom climate control			
Radio multimedia			

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	245 / 45 / 19 / 102 / Y / Aluminium	4,8 mm	Pirelli	Summer
	Right	245 / 45 / 19 / 102 / Y / Aluminium	4,8 mm	Pirelli	Summer
Rear	Left	245 / 45 / 19 / 102 / Y / Aluminium	5,2 mm	Pirelli	Summer
	Right	245 / 45 / 19 / 102 / Y / Aluminium	5,8 mm	Pirelli	Summer

Assistance equipment

Number of charging cables (rapid charge)	**1**

Interior, Dirty, Cleaning






Door FL, Dent(s), Repair and paint (complete)





LED headlight R, Scratch(es), Replace




Bonnet, Scratch(es), Repair and paint (complete)






Bumper F, Scratch(es), Repair and paint (complete)








Door RR, Dent(s) and scratch(es), Repair and paint (complete)







Wing RR, Scratch(es), Repair and paint (complete)





Bumper R, Scratch(es), Repair and paint (complete)





Bumper RM, Scratch(es), Replace




Bumper moulding RR, Scratch(es), Replace and paint




Tailgate / Boot, Dent(s), Repair and paint (complete)





Onderhoudshistorie van: LPSVSECEKNL054360

ALPHABET

Kenteken	N319KF
Merk Model	Polestar Polestar 2 165kW/ 63kWh Single Motor Standard Range
Brandstofsoort	Elektrisch
Datum deel1	11/19/21

Datum reparatie	Kilometerstand	Reparatie omschrijving
6/23/26	5	On Board Charger
6/21/26	0	Accu
6/19/26	0	Accu
6/12/26	0	Accu
6/4/26	0	Accu
5/27/26	0	Accu
3/4/26	105,656	Onderhoudsbeurt
3/4/26	105,656	Remvloeistof
11/13/25	97,146	APK
1/29/25	77,145	Boordcomputer
1/29/25	77,145	Onderhoudsbeurt
1/29/25	77,145	Ruitenwisserblad(en) voorzijde
7/16/24	69,000	Vervanging band
6/14/24	64,066	Reparatie band(en)
5/14/24	62,295	Vervanging band
8/28/23	45,698	Airco reinigen
8/28/23	45,698	Onderhoudsbeurt
8/28/23	45,698	Ruitenwisserblad(en) voorzijde
3/9/22	8,643	Reparatie band(en)