APPRAISAL REPORT



IDENTIFICATION VEHICLE

Make:	BMW
Model / version:	X2
Vin:	WBAYN910605V55140
Plate:	2CFW589
Mileage:	62170
SOH:	
First registration:	08/07/2022
Color:	Saphirschwar



ADDITIONAL INFORMATION


Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?


DOCUMENTS


Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✓
Maintenance book:	
Number of keys:	2
Original key:	✓

PICTURES















































VIN INFORMATION

Système navigation	10 Haut-parleurs	Transmission automatique
6 rapports	4 roues motrices	Projecteurs à LED
Matière : alliage	Lettre repère (J)	Diamètre avant 17
Diamètre arrière 17	Largeur avant 7,5	Largeur arrière 7,5
Diamètre avant 17	Diamètre arrière 17	Hauteur avant 55
Hauteur arrière 55	Indice de vitesse avant W	Indice de vitesse arrière W
Largeur avant 225	Largeur arrière 225	Climatisation automatique
Accoudoir central avant	Hybride essence	1499 cm3
1.50 litre	92 kw	125 ch
Métallisée vernissée	Rétroviseur gauche chauffant	Rétroviseur droit chauffant
Rétroviseur gauche jour/nuit automatique	Rétroviseur droit jour/nuit automatique	Rétroviseurs rabattables électriques

Rétroviseur intérieur jour/nuit automatique	Siège avant gauche chauffant	Sièges avant chauffants
Siège avant gauche à réglage lombaire	Sièges avant à réglage lombaire	Garnitures tissu
Volant cuir	Volant sport	Volant multifonction
Aide au stationnement avant	Aide au stationnement arrière	Assistance au parking
Caméra avant	Caméra arrière de recul	Régulateur automatique de la distance
Affichage tête haute	Ouverture du coffre électriquement	Alarme
Appel de secours	Protection piéton	Freinage d'urgence assistée autonome (urbain)
Avertisseur de collision avant	Contrôle pression des pneus	depuis 05.22
Advantage	mesures CO2 étendues	norme supplémentaire RDE
tuner DAB	Connected Drive Services	pack de rangement
boulons antivol de roue	encarts intérieurs oxyde d'argent foncé mat avec accents noir brillant	spécifique Europe

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	×	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	×
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	1	**Fast charging cables:**	1

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm		225/55R17 97W	Summer		?
Front right	5 mm		225/55R17 97W	Summer		?
Rear left	5 mm		225/55R17 97W	Summer		?
Rear right	5 mm		225/55R17 97W	Summer		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Interior	Dirty
2	Contact key - Boordcomputer resetten	Not original part
3	Certificate of registration 2	Teared
4	Windscreen	Crack
6	Alloy rim FL	Grooved
7	Outside rear-view mirror housing L	Scratch(es)
8	Wing RR	Scratch(es)
9	Door RR	Dent(s) and scratch(es)

Total: 8

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
5	Bodywork	Dent(s) and scratch(es)	✓	×	×

Total: 1

DAMAGES DETAILS

1 - Interior - Dirty







2 - Contact key - Boordcomputer resetten - Not original part






3 - Certificate of registration 2 - Teared




4 - Windscreen - Crack

6 - Alloy rim FL - Grooved






7 - Outside rear-view mirror housing L - Scratch(es)




8 - Wing RR - Scratch(es)








9 - Door RR - Dent(s) and scratch(es)








5 - Bodywork - Dent(s) and scratch(es) - Renta®








SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

22/10/2026 09:56

