Audi

VIN: WAUZZZGYXPA017113



Description

Registration number 2CNZ349	**First registration date** 03/10/2022	**Odometer** 173534 km
Color 0E0E Mythoszwart metaalkleur	**Model year** 2022	**Upholstery** -
Number of doors 4	**Number of seats** -	**Generation** -
Engine displacement 999	**Max power** 81 KW	

Vehicle Equipments

Automatic headlights	Cruise control	Alloy wheel rims
Hydraulic tail board	Park Assist	SATNAV
Front sensors	Rear sensors	Xenon headlights
Heated door mirrors	Climate control	

Statement details

Inspection loc PARC HÖDLMAYR TONGEREN	**Statement date** 23/10/2026	**Inspection approval date** 26/10/2026

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction
001	A-pillar trim / Interior Front Left	Burn mark	Replace

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.




002	A-pillar trim / Interior Front Right	Tear	Replace




003	Rim / Front Left Material : Aluminium alloy / Rim/Tyre diameter : 16 " / Surface : Painted	Scratched	Repair






004	Wing / Front Left	Scratched	Acceptable



005	Windscreen / Front	Broken	Repair

006	Rim / Front Right Material : Aluminium alloy / Rim/Tyre diameter : 16 " / Surface : Painted	Scratched	Repair





007	Door / Back Left	Dent	Acceptable

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



008	Door sill / Interior Back Left	Dent	Acceptable




009	Rim / Back Left Material : Aluminium alloy / Rim/Tyre diameter : 16 " / Surface : Painted	Scratched	Acceptable




010	Wing / Back Left	Dent	Acceptable



011	Bumper / Back [1] Painted : Yes	Dent	Repair






012	Wing / Back Right	Dent	Repair






013	Rim / Back Right Material : Aluminium alloy / Rim/Tyre diameter : 16 " / Surface : Painted	Scratched	Acceptable

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



014	Exterior door mirror shell / Front Right	Scratched	Acceptable



015	Door / Front Right	Dent	Acceptable



016	Roof post A/B/C / Back Right	Dent	Smart repair





[1] Ovb

Loose Items

- [x] Tyre repair kit complete
- [x] Registration certificate owner
- [x] Registration certificate
- [x] Triangle
- [x] Rear parcel shelf
- [x] Spare Key
- [x] First aid kit
- [x] Conformity certificate
- [x] Safety vest

Main set of tyres

Front Left	NEXEN	205/55/16 Summer	3 mm
Front Right	NEXEN	205/55/16 Summer	3 mm
Back Left	GOODYEAR	205/55/16 Winter	6 mm
Back Right	GOODYEAR	205/55/16 Winter	6 mm

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Comments

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left


Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat


Front passenger compartment



Front right




Odometer


Navigation


Spare Tyre


Vin


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.




Other




Other



Other



Other



Other



Other



A-pillar trim / Interior Front Left / Burn mark



A-pillar trim / Interior Front Left / Burn mark



A-pillar trim / Interior Front Right / Tear



A-pillar trim / Interior Front Right / Tear



Rim / Front Left / Scratched



Rim / Front Left / Scratched



Rim / Front Left / Scratched




Wing / Front Left / Scratched



Windscreen / Front / Broken

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Windscreen / Front / Broken



Rim / Front Right / Scratched



Rim / Front Right / Scratched



Rim / Front Right / Scratched



Door / Back Left / Dent



Door sill / Interior Back Left / Dent



Rim / Back Left / Scratched



Wing / Back Left / Dent



Bumper / Back / Dent



Bumper / Back / Dent



Bumper / Back / Dent



Bumper / Back / Dent



Bumper / Back / Dent



Bumper / Back / Dent



Bumper / Back / Dent

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Wing / Back Right / Dent



Wing / Back Right / Dent



Wing / Back Right / Dent



Wing / Back Right / Dent



Rim / Back Right / Scratched



Exterior door mirror shell / Front Right / Scratched



Door / Front Right / Dent



Roof post A/B/C / Back Right / Dent



Roof post A/B/C / Back Right / Dent

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.