ARVAL
BNP PARIBAS GROUP

2DDK720

INSPECTION REPORT

End of contract

GENERAL INFO

File	324445
License plate	2DDK720
Vehicle identification number	WF0FXXWPMHNG16301
Dossier	2022361087
Make	Ford Kuga 2.5i EB 165kW ST-L.X
Mileage	173156
First registration	13/02/2023
client availability date	07/10/2026
inspectionDate	13/10/2026











CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





2-DDK-720
KEURING
BELCAR

DAMAGES

Damages	Type	Acceptable
32	Front Bonnet // Painting	Y
40	Windshield // Repair	Y
72	Side View Mirror Left // Painting	N
86	Door Front Left // Polish	Y
103	Door Rear Left // Painting	Y
183	Wing Rear Right // Painting	Y
190	Door Rear Right // Smart Repair Small	N
216	Door Front Right // Polish	Y
331	Wheel Alloy Rear Right // Repair	Y
341	Wheel Alloy Front Right // Repair	Y
412	Seat Front Left / Bottom Coating / Replace	Y
883	Key Price Range 2 //	N

Damage Pictures




Wheel Alloy Front Right // Repair-scratch





Door Front Right // Polish-scratch





Wheel Alloy Rear Right // Repair-scratch





Wing Rear Right // Painting-scratch







Door Rear Left // Painting-scratch




Door Front Left // Polish-scratch




Side View Mirror Left // Painting-scratch





Door Rear Right // Smart Repair Small-dent





Seat Front Left / Bottom Coating / Replace-cracked




Key Price Range 2 //-cracked




Windshield // Repair-glass damage


Front Bonnet // Painting-stone chipping