Audi

VIN: WAUZZZFY9M2123415

Estimated repair cost

90.50 EUR
TOTAL



Description

Registration number 2FHB670	**First registration date** -	**Odometer** 44498 km
Color -	**Model year** -	**Upholstery** -
Number of doors -	**Number of seats** -	**Generation** -

Statement details

Inspection loc
PARC LIZY

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Defects & corrections

#	Element	Defect	Correction	net cost
001	Interior pillar trim / - Trim material : Plastic	Scratched	Smart repair	68.00 EUR



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	**68.00 EUR**
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

#	Element	Defect	Correction	net cost
002	Interior complete / -	Stained	Cleaning	22.50 EUR



Bodywork time	Paint time	Part Price	Lumpsum
0.30 h	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
22.50 EUR	-	-	

#	Element	Defect	Correction	net cost
003	Bumper / Back Painted : Yes	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

#	Element	Defect	Correction	net cost
004	Door / Front Right Material : Metal / Windowed : Yes	Dent	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

#	Element	Defect	Correction	net cost
005	Bumper / Front Painted : Yes	Scratched	Acceptable	-



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Loose Items

- Quick charging cable (Type 2, Mode 3)
- First aid kit
- Rear parcel shelf
- Spare Key
- Document holder
- Registration certificate owner
- Charging cable bag
- Triangle
- User manual
- Registration certificate

Main set of tyres


Front Left	PIRELLI	255/45/20 101 W Summer	5 mm
Front Right	PIRELLI	255/45/20 101 W Summer	5 mm
Back Left	PIRELLI	255/45/20 101 W Summer	5 mm
Back Right	PIRELLI	255/45/20 101 W Summer	5 mm

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left



Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat


Front passenger compartment


Front right




Odometer


Cable



Vin


Other

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Other



Other



Interior pillar trim / - / Scratched



Interior pillar trim / - / Scratched



Interior pillar trim / - / Scratched



Interior complete / - / Stained



Interior complete / - / Stained



Interior complete / - / Stained



Bumper / Back / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched



Door / Front Right / Dent



Door / Front Right / Dent



Door / Front Right / Dent

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Bumper / Front / Scratched



Bumper / Front / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.