AUDI A5 SPORTBACK


Vehicle information


Make:	**AUDI**	License:	**2AVL710**
Gearbox:		Body color:	
Model:	**A5 SPORTBACK**	VIN:	**WAUZZZF54NA002157**
Fuel type:		Power:	**100 kW**
Version:	**2.0 30 TDI S TRONIC BUS. ED. ATTRACTION**	First registration	**04/08/2021**
Mileage:	**76535 km**	N° of doors:	

Damage summary



Front	1
Interior	2
Rear	2
Right	2
Roof & others	1



Commercial pictures























VIN equipment according to manufacturer information

Airbag	Central consol	Central locking	Distance control
Electric adjustable mirrors	GPS	Headlight sprinkler	Integrated child seat
Interior leather	Isofix	Power steering	Rims alloy
Seats F heated (ECS&B)	Steering wheel multifunctional	Telephone	Windows electric functioning

Options according to the inspector

GPS	**Yes**

Damages

Alloy rim FR

Scratch(es)

Repair and paint (complete)

Right









Bodywork


Damaged


Acceptable

Roof & others



















Bumper F
Scratch(es)
Paint
Front








Bumper R
Repaired
Acceptable
Rear



Door FR
Repaired
Acceptable
Right




Interior
Damaged
Acceptable
Interior



Rear light L
Crack
Replace
Rear





Service
Maintenance
Check
Interior



Tyres

Front Left
Summer
Aluminium
225/50/17/98/Y
Hankook
5.0 mm
Front Right
Summer
Aluminium
225/50/17/98/Y
Hankook
5.0 mm
Rear Left
Summer
Aluminium
225/50/17/84/H
Pirelli
4.0 mm
Rear Right
Summer
Aluminium
225/50/17/84/H
Pirelli
4.0 mm

Checks

Category	**Passenger Car**	Certificate of Conformity	**Yes**
Compressor	**Yes**	Maintenance	**NOT OK**
Number of charging cables (normal)	**0**	Number of charging cables (rapid charge)	**0**
Number of keys total	**3**	Registration Certificate Car (BE)	**Yes**
Registration Certificate Home (BE)	**Yes**	Repair kit	**Yes**
Reset to factory settings	**No, not possible**	Type of Maintenance book	**Digital maintenance**

VIN detail - *If the description in the language of your choice is not available, the French description is shown*

ABS (antiblocage des freins)	Accoudoir central avant	Airbag conducteur
Airbag passager	Airbag passager désactivable manuellement	Airbags latéraux aux sièges avant
Airbags latéraux façon ''rideau'' Sideguard AV/AR	Antivol électronique transpondeur Audi	APS (Acoustic Parking System) arrière
ASR (antipatinage électronique)	Audi Drive Select avec Efficiency	Audi Virtual Cockpit Plus
Chauffage d'appoint électrique à air	Climatisation électronique monozone	Contours de fenêtres en aluminium
Cuir-similicuir	Direction électromécanique	Dossier de banquette arr. rabattable en 2 parties
DPF (Diesel Particle Filter)	Eclairage intérieur	EDS
Encarts décoratifs Diamond gris argenté	ESP (Electronic Stability Programm)	Feux arrière LED
Feux de jour DEL	Fixations Isofix et Top Tether arrière	Fonction start/stop
Habillage du coffre	Haut-parleurs (8)	Hayon ouverture et fermeture électriques
JAV 15 branches 7.5Jx17''+225/50	Kit Assistance stationnement: APS+hill assist+cam.	Kit Confort ''rétroviseurs''
Kit Infotainment Navigation	Kit Infotainment smartphone	Kit Infotainment smartphone(si Infotainement Navi)
Limiteur de vitesse	Listels de seuil de porte en aluminium	Ordinateur de bord monochrome
Outillage de bord	Pack Busin.Plus (convention A/B/C/D/E/F/H/P)(Obl.)	Pack Business Plus (Obligatoire)
Peinture unie	Phares LED à l'avant	Phares Matrix LED+clignotants dynamiques AV/AR
Pré-installation GSM Bluetooth	Préparation pour MMI Navigation Plus	Rappel sonore & optique si ceinture non bouclée
Régulateur de vitesse	Réservoir de carburant (54 litres)	Rétroviseur intérieur avec position jour/nuit
Rétroviseurs électriques	Rétroviseurs extérieurs à dégivrage électrique	Rétroviseurs extérieurs couleur carrosserie
Sécurité enfant aux places arrière	Sièges avant chauffants	Système de contrôle de pression des pneus
Tapis de coffre	Tapis de sol complémentaires AV/AR	Tissu Index
Trousse secours+triangle présignalisation+extincteur	Tuner numérique (DAB)	Tyre Mobility System
Verrouillage central avec commande à distance	Vitres athermanes de couleur verte	Vitres électriques arrière
Vitres électriques avant	Volant multifonctions 3 branches gainé de cuir	Volant multifonctions à 3 branches gainé de cuir

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.