# TESLA MODEL Y


## Vehicle information


| | | | |
|---|---|---|---|
| Brand: | **TESLA** | License plate: | **2CRR363** |
| Gearbox: | | Body color: | |
| Model: | **MODEL Y** | LEVEL: | **LRWYGCEK2NC472777** |
| Fuel type: | | Power: | **378 kW** |
| Version: | **BEV LONG RANGE AUTO 4WD** | First registration | **31/10/2022** |
| Mileage: | **165967 km** | Number of doors: | |

## Summary of damages

| | |
|---|---|
| **Before** | 1 |
| **RIGHT** | 3 |
| **LEFT** | 2 |
| **Interior** | 1 |
| **Roof & other** | 1 |

## Commercial photos

































## Options according to the inspector

| | |
|---|---|
| GPS | **Yes** |

## Damages

**Bodywork**

Damaged -

Acceptable.

Roof & other







Damaged **Interior**

- Acceptable

Interior








**Alloy wheel, right rear, scratch**
(es)
, left front - Repair and paint (complete),
right side





**Alloy wheel, left-hand side,**
scratch(es)
- Repair and paint (complete
)





**Alloy wheel AVD**
Scratch(es)
LI - Repair and paint (complete)
Right






**Alloy wheel AVG**
Scratch(es)
LI - Repair and paint (complete)
Left





**Front Right Wing Molding**
Broken
E - Replace
Right




**Front bumper,**
scratch(es),
paint
front







## Tires

**Front Left**
Summer
Aluminum
255/40/20/101/Y
Goodyear
5.0 mm
**Front Right**
Summer
Aluminum
255/40/20/101/Y
Goodyear
5.0 mm
**Left Back**
Summer
Aluminum
255/40/20/101/Y
Goodyear
3.0 mm
**Rear Right**
Summer
Aluminum
255/40/20/101/Y
Goodyear
3.0 mm

## Controls

| | | | |
|---|---|---|---|
| Category | **Private vehicle** | Registration certificate - home address section | **No** |
| Vehicle registration certificate | **Yes** | Certificate of Conformity | **Yes** |
| Compressor | **P/A** | Vehicle inspection | **OK** |
| Vehicle inspection | **31/10/2026** | Interview | **OK** |
| Repair kit | **P/A** | Number of charging cables (220V) | **0** |
| Number of charging cables (fast charging) | **1** | Total number of keys | **2** |
| Charge level | **50** | Factory reset | **No, that's not possible.** |
| Type of maintenance log | **Digital interview** | | |

### Information on the content and scope of the inspection report:

- The evaluation is based on the sales standards specified by the client.
- Acceptable wear and tear according to sales standards is not always documented in this condition report.
- The specified repair methods and/or resulting repair times were determined taking into account modern industrial repair methods.
- The reseller must assess individual repair costs.
- The inspection was carried out without dismantling. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.