MACADAM
Volvo XC40 '17

Vehicle information

Make:	**Volvo**	License:	
Gearbox:	**Automatic**	Body color:	
Model:	**XC40 '17**	VIN:	**YV1XZEDVEM2508019**
Fuel type:	**Electric**	Power:	**300 kW**
Version:	**XC40 P8 AWD 78kWh EV Recharge**	First registration	**22/12/2020**
Mileage:	**191583 km**	N° of doors:	

Damage summary

Front	3
Left	1
Rear	3

Commercial pictures

Tripcomputer
Reset TM
Sluiten
ODO: 191 583 km


YV1XZEDVEM2508019

Batterijcertificaat
Datum van diagnose: 16/07/2026
90,05%
Status van de gezondheid (SOH)*
Volvo XC40 Recharge
VIN : YV1XZEDVEM2508019
Kilometerstand : 191.583 km
*SOH berekend op basis van fabrieksgegevens, informatie om rekening mee te houden voor de fabrieksgarantie
Raadpleeg het Moba-certificaat door deze QR-code te scannen
Meer weten over:
www.get-moba.com
CARA

Options according to the inspector

Central consol F	**Yes**	GPS	**Yes**	Headlights Xenon/LED/Laser	**Yes**
Panoramic roof	**Yes**	Radio multimedia	**Yes**	Rear view camera	**Yes**
Sun Roof electric	**Yes**	Telephone equipment	**Yes**		

Damages

Alloy rim FL
Scratch(es)
Repair and paint (complete)
Left



Bonnet
Stone chip(s)
Repair and paint (complete)
Front

Boot lid covering R
Scratch(es)
Smart repair
Rear

Bumper corner RL
Scratch(es)
Repair and paint (complete)
Rear



Bumper F
Scratch(es)
Repair and paint (complete)
Front

Bumper spoiler F
Scratch(es)
Smart repair
Front

Charging cable (normal)
Missing
Replace
Rear

Tyres

Front Left	
Summer	
235/50/19/103/V	
Goodyear	
7.0 mm	
Front Right	
Summer	
235/50/19/103/V	
Goodyear	
7.0 mm	
Rear Left	
Summer	
235/50/19/103/V	
Continental	
3.2 mm	
Rear Right	
Summer	
235/50/19/103/V	
Continental	
3.2 mm	

Checks

CO2 Emission	**0**	Digital maintenance	**N/A**
GPS storage	**Yes**	Luggage cover	**Yes**
Number head rests	**5**	Number of charging cables (rapid charge)	**1**
Number of keys total	**3**	Reset to factory settings	**Yes, vehicle is reset to factory settings**
Service book	**Yes**	User's manual	**Yes**

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.