Audi

AUDI Q5 (FYG)(06.2020->) 35 TDI BASE HYBRIDATION LÉGÈRE 120 KW (MOTEUR 2,0 LITRE(S) - 120 KW 16V TDI) 4 PORTES

VIN: WAUZZZFY6P2005424



Description

Registration number 2CMV714	**Registration date** 20/09/2022	**Odometer** 105314 km
Color Argent Fleuret Métallisé	**Year** 2020	**Upholstery** -
Number of doors 5	**Number of seats** 5	**Generation** -
Engine displacement 1968	**Gearbox type** Automatic	**Engine type** Combustion
Fuel Type Diesel	**Number of gears** 7	**Drivetrain** Front Wheel Drive (FWD)
Max power 120 KW		

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Vehicle Equipments

Standard

8 speaker(s)	Park-Distance-Control (PDC)	airbag driver side/passenger side
sidebag front	immobilizer (electronic)	Audi connect (Emergency and Assistance System)
Audi Drive Select	battery 68 Ah	roof edge spoiler
transmission 7-speed - dual-clutch transmission S-tronic	rear lid open+close automatic (Hands-Free-Access system)	multi-functional camera
body: 4-door	air auxiliary heating electric	standard suspension
automatic air-conditioning system	radio-remote key	steering column (steering wheel) mech. height/longitudinal adjustment
power steering electromechanical	brake discs front (318 mm x 30 mm)	rear seat backrest split/folding
wheelbase 2819 mm	Longlife-Service	interior equipment decorative trim inserts Micro metallic silver
interior equipment decorative trim inserts accent parts black matte	rear lights LED	diesel particulate filter
parking brake electromechanical	roof liner cloth	universal interface Bluetooth
Light-alloy rims	tire repair kit	vehicle speed limiter
Mild-Hybrid-Technologie	Type of drive: front-wheel drive	Moteur 2,0 litre(s) - 120 kW 16V TDI hybridation légère (DTNA)
low emissions according to emission standard Euro 6d	non-smoking package	windshield acoustic glass
bumper variant: base	tire 235/65 R17 ...W	headlight LED
scuff rails with aluminium insert	loading edge protector	radio reception digital (DAB)
cruise control (cruise control)	exterior mirror vehicle colour	exterior mirror electrically adjustable and heated, both
seats front manually adjustable	standard seats front	beverage holder
Isofix mounts for child seat	floor mats velours	head airbag system (Sideguard)
antilock braking system (ABS)	driver assistance system: City emergency braking function	SCR system (AdBlue technology)
start/stop system	cargo space partition (net)	trunk lining
tire puncture indicator	heat protection glazing green-tinted	daytime running lights LED

Optional

center armrest front comfort equipment	Alternateur 130-200 A	Audi connect (web-based services)
roof rails (aluminium)	trailer coupling (pivoting ball head)	Disques de frein AR (330 mm x 22 mm)
Disques de frein AV (338 mm x 30 mm) Brembo	refrigerant R 1234 YF	multi-media Interface MMI Navigation Plus with MMI Touch
Driver Information System (DIS) (FIS) with colour display	Shine package	metallic paintwork
urea tank (SCR) 24 liter	fuel tank: 70 liter	exterior mirror aspherical, right
exterior mirror aspherical, left	seat covers/upholstery: leather / imitation leather mono.pur 550 combination	seat heating front
pedestrian protection system	steering wheel (leather - 3-spokes) with multiple function plus and shift function	Zone climatique : Régions tempérées

Statement details

Inspection loc	Statement date	Inspection approval date
PARC HÖDLMAYR TONGEREN	15/10/2026	16/10/2026





All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction
001	Personal Data / -	Non Compliant	Carry out
	 		
002	Rim / Front Right Material : Aluminium alloy / Rim/Tyre diameter : 17 " / Surface : Painted	Scratched	Repair
	 		
003	Roof / - Sunroof : No	Dent	Repair
	  		
004	Tyre pressure sticker / Front Left	Non Compliant	Replace
	 		
005	Rear windscreen / Back Tinted window : No	Scratched	Polishing
	 		

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

006	Wing extension moulding / Front Right Painted : No	Scratched	Acceptable



Loose Items

- [x] Tyre repair kit complete
- [x] First aid kit
- [x] Refill tyre repair kit
- [x] Spare Key
- [x] Compressor tyre repair kit
- [x] Registration certificate owner
- [x] Conformity certificate
- [x] Towing hook
- [x] Triangle
- [x] Rear parcel shelf
- [x] Registration certificate
- [x] Safety vest

Main set of tyres

Front Left	UNIROYAL	235/65/17 Summer	5 mm
Front Right	UNIROYAL	235/65/17 Summer	5 mm
Back Left	MICHELIN	235/65/17 Summer	4 mm
Back Right	MICHELIN	235/65/17 Summer	4 mm

Comments

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures



Front left



Rear left



Boot opened



Rear right



Rear passenger compartment



Dashboard from rear seat



Front passenger compartment



Front right



Odometer



Navigation



Spare Tyre




Vin


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Other



Other




Other



Other



Personal Data / - / Non Compliant



Personal Data / - / Non Compliant




Rim / Front Right / Scratched




Rim / Front Right / Scratched



Roof / - / Dent



Roof / - / Dent




Roof / - / Dent



Tyre pressure sticker / Front Left / Non Compliant



Tyre pressure sticker / Front Left / Non Compliant



Rear windscreen / Back / Scratched



Rear windscreen / Back / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Wing extension moulding / Front Right / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.