
MACADAM







Citroen C4: R504RG

Vinnumber:	**VR7BCZKXCNE057433**	Versionname:	**e-C4 100kW/50kWh Feel Pack automaat**
First Registrationdate:	**31/10/2022**	Fiscalpower:	
Expertise Mileage:	**110093**	Power Kw:	**100**
Bodytype:		Body colour	**Steel Grey**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Electric**	Parking lot	**631**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**No**		

Options

Number of keys total	**2**	Lining semi-leather	
GPS		Rear parking sensors	
Autom climate control		Rear view camera	
Radio multimedia			

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	195 / 60 / 18 / 96 / H / Aluminium	7,0 mm	Continental	All season
	Right	195 / 60 / 18 / 96 / H / Aluminium	6,9 mm	Continental	All season
Rear	Left	195 / 60 / 18 / 96 / H / Aluminium	5,5 mm	Continental	All season
	Right	195 / 60 / 18 / 96 / H / Aluminium	7,0 mm	Continental	All season

Assistance equipment

Number of charging cables (rapid charge)	**1**

Interior, Stain, Cleaning






Door FL, Dent(s) and scratch(es), Repair and paint (complete)











Wing RL, Scratch(es), Repair and paint (complete)




Door RL, Scratch(es), Repair and paint (complete)







Roof pillar L, Scratch(es), Repair and paint (complete)




Wing FL, Scratch(es), Repair and paint (complete)




Wheel arch cover FL, Scratch(es), Replace




Bumper F, Scratch(es), Repair and paint (complete)








Bumper trim F, Scratch(es), Replace





Windscreen, Stone chip(s), Windscreen repair




Door RR, Scratch(es), Repair and paint (complete)





Wing RR, Dent(s) and scratch(es), Repair and paint (complete)









Wheel arch cover RR, Scratch(es), Replace





Door FR, Dent(s) and scratch(es), Repair and paint (complete)





Wing FR, Scratch(es), Repair and paint (complete)




Bumper R, Dent(s) and scratch(es), Repair and paint (complete)







Bumper trim R, Dent(s) and scratch(es), Replace








Rear spoiler, Scratch(es), Repair and paint (complete)





Roof, Chemical polution, Polish




Onderhoudshistorie van: VR7BCZKXCNE057433

ALPHABET

Kenteken	R504RG
Merk Model	Citroen e-C4 100kW/50kWh Feel Pack automaat
Brandstofsoort	Elektrisch
Datum deel1	10/31/22

Datum reparatie	Kilometerstand	Reparatie omschrijving
10/27/26	160,175	Vervanging band
9/8/26	106,170	Uitlijnen voor en achterwielen
9/8/26	106,170	Vervanging band
8/4/26	103,581	APK
8/4/26	103,581	Onderhoudsbeurt
10/1/25	78,954	Vervanging band
8/14/25	74,993	Onderhoudsbeurt
8/14/25	74,993	Remvloeistof
8/14/25	74,995	Uitlijnen voor en achterwielen
8/14/25	74,995	Vervanging band
8/30/24	69,584	Reparatie band(en)
2/12/24	32,766	Onderhoudsbeurt
8/28/23	18,080	Onderhoudsbeurt