ARVAL
BNP PARIBAS GROUP

2CAR085

INSPECTION REPORT

End of contract

GENERAL INFO

File	324749
License plate	2CAR085
Vehicle identification number	W1K1186121N304301
Dossier	2021 181 321
Make	Mercedes CLA SB 200 d Bus.Solu
Mileage	181394
First registration	12/05/2022
client availability date	15/10/2026
inspectionDate	21/10/2026










CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	




2-CAR-085
KEURING
BELCAR

DAMAGES

Damages	Type	Acceptable
133	Bumper Rear // Painting	N
139	Bumper Rear / Spoiler / Replace	N
12	Bumper Front // Smart Repair Large	Y
40	Windshield // Repair	Y
116	Wing Rear Left // Polish	Y
180	Wing Rear Right // Smart Repair Small	Y
193	Door Rear Right // Painting	Y
216	Door Front Right // Polish	Y
412	Seat Front Left / Bottom Coating / Replace	N
569	Dashboard / Steering Wheel / Replace	Y
634	Rear Left Door Interior Coating // Replace Completely	N
860	Interior Cleaning // Small	N

Damage Pictures




Wing Rear Left // Polish-scratch




Wing Rear Right // Smart Repair Small-dent





Windshield // Repair-glass damage




Rear Left Door Interior Coating // Replace Completely-tear










Interior Cleaning // Small-stain





Dashboard / Steering Wheel / Replace-worn




Seat Front Left / Bottom Coating / Replace-N comf / out of order



Bumper Front // Smart Repair Large-scratch




Door Front Right // Polish-scratch



Door Rear Right // Painting-scratch



Bumper Rear / Spoiler / Replace-scratch



Bumper Rear // Painting-scratch