MACADAM
Citroën C4 '20

Vehicle information

Make:	**Citroën**	License:	
Gearbox:	**Automatic**	Body color:	
Model:	**C4 '20**	VIN:	**VR7BCZKXCNE032855**
Fuel type:	**Electric**	Power:	**100 kW**
Version:	**e-C4 50 kWH Feel**	First registration	**30/06/2022**
Mileage:	**202524 km**	N° of doors:	

Damage summary

Front	1
Interior	1
Left	3
Rear	2
Right	5
Roof & others	1

Commercial pictures













READY
km/h
CHARGE
ECO
POWER
130 km
0
1/2
202524 km


CITROËN
C4
BEKNOPTE HANDLEIDING
GARANTIE- EN ONDERHOUDSBOEKJE


VR7BCZKXCNE032855















Check surroundings before maneuvering




Batterijcertificaat
Datum van diagnose: 02/11/2026
88,19%
Status van de gezondheid (SOH)*
Citroën ë-C4
VIN : VR7BCZKXCNE032855
Kilometerstand : 202.524 km
*SOH berekend op basis van fabrieksgegevens, informatie om rekening mee te houden voor de fabrieksgarantie
Raadpleeg het Moba-certificaat door deze QR-code te scannen
Meer weten over:
www.get-moba.com
CARA



Options according to the inspector

Central consol F	**Yes**	GPS	**Yes**	Headlights Xenon/LED/Laser	**Yes**
Radio multimedia	**Yes**	Rear view camera	**Yes**	Telephone equipment	**Yes**

Damages

Alloy rim FL
Scratch(es)
Repair and paint (complete)
Left





Alloy rim FR
Scratch(es)
Repair and paint (complete)
Right





Alloy rim RL
Scratch(es)
Repair and paint (complete)
Left





Alloy rim RR
Scratch(es)
Repair and paint (complete)
Right




Bodywork
Not original part
Remove lettering
Roof & others






Boot lid covering R
Scratch(es)
Smart repair
Rear







Bumper R
Scratch(es)
Repair and paint (complete)
Rear




Door frame RR
Dent(s) and scratch(es)
Repair and paint (complete)
Right




Interior
Stain
Cleaning
Interior





Wheel arch cover RR
Scratch(es)
Replace
Right







Windscreen
Stone chip(s)
Windscreen repair
Front







Wing FL
Dent(s) and scratch(es)
Repair and paint (complete)
Left





Wing FR
Stone chip(s)
Repair and paint (complete)
Right





Tyres

Front Left
Summer
195/60/18/96/H
Goodyear
5.8 mm
Front Right
Summer
195/60/18/96/H
Goodyear
4.8 mm
Rear Left
Summer
195/60/18/96/H
Goodyear
6.5 mm
Rear Right
Summer
195/60/18/96/H
Goodyear
6.5 mm

Checks

Certificate of Conformity	**No**	CO2 Emission	**0**
Digital maintenance	**N/A**	GPS storage	**HD**
GPS storage	**Yes**	Luggage cover	**Yes**
Number head rests	**5**	Number of charging cables (rapid charge)	**1**
Number of keys total	**2**	Reset to factory settings	**Yes, vehicle is reset to factory settings**
Service book	**Yes**	User's manual	**Yes**

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.