TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

# Expertise

Protocol number: 48238782
Order No. / Reference: 27111734
Inspection date: 19 Oct 2026

| Manufacturer: Seat | Model: Tarraco 2.0 TDI SCR Style |
|---|---|
| VIN: VSSZZZKN2PW008794 | |







## Vehicle details

| | |
|---|---|
| **Manufacturer / Type / Model / Equipment** | |
| Seat Tarraco 2.0 TDI SCR Style | |
| **Vehicle Identification number** | VSSZZZKN2PW008794 |
| **Mileage** (Read) | 53,049 km |
| **First registration** | 31 Jul 2023 |
| **Number of holders** | 1 |
| **Next periodical technical inspection** | 07/2028 |
| (Report on hand) | |
| **Fuel type** | Diesel |
| **Engine displacement / Cylinder** | 1,968 ccm / 4 |
| **Power** | 110 kW |
| **Gearbox / Number of gears** | Manual / 6 |
| **Type of drive** | Front drive |
| **Type of vehicle** | Van |
| **Colour / colour code** | Deep Schwarz Metallic |
| **Doors / Seats** | 5 / 5 |
| **Upholstery type** | Cloth |
| **Colour of upholstery** | Black-Grey |
| **Vehicle with smoke odor** | no |

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

## Vehicle details

| | | | |
|---|---|---|---|
| **Maintenance booklet / proof** | digital proof / complete | **Next maintenance in** | |
| **Last service on / at** | 04/2025 at 31,165 km | | |
| **Key is / should be** | 2 / 2 | **FZG documents** | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
| | | **Letter No.** | GQ507172 |
| **Previous damage / Accident** | None detectable | **Repainting** | None detectable |
| **Inspection conditions** | sufficient | **Lifting equipment / pit** | yes |
| **Test drive** | Not performed | **Engine function test** | Performed |
| **Manufacturer key number/ type code number** | 7593 / AOR 03236 | | |
| **Emission standard** | EURO6 | **fine dust sticker** | |
| **Permitted total weight** | 2,240 kg | **Empty weight** | |

## Tyres

### Mounted tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 215/65 R17 99V | Summer tyres on Light alloy | Pirelli | 7mm / 7mm |
| 2) | 215/65 R17 99V | Summer tyres on Light alloy | Pirelli | 7mm / 7mm |

### Additional tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 215/65 R17 103H | Winter tyres on Steel | Pirelli | 8mm / 8mm |
| 2) | 215/65 R17 103H | Winter tyres on Steel | Pirelli | 6mm / 6mm |

### Replacement

| Typ | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| N | 145/85 R18 103M | Summer tyres on Steel | Sonstige | 4 mm |

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**

## Equipment

### Standard equipment

- 12V socket at the front
- Storage pocket on the back of the front seats
- Automatic coming-home and leaving-home function
- Electrically adjustable, folding and heated exterior mirrors
- Turn signals and welcome light integrated into the exterior mirrors
- Black headliner
- Diesel particulate filter and SCR catalyst
- Tachometer
- Third brake light
- Electronic Stability Control (ESC)
- Footwell lighting
- luggage compartment, illuminated
- Transmission: 6-speed transmission
- LED taillights
- Interior mirror automatically dimming
- Body covers on the wheel arches
- Headrests, 2 front, 3 rear
- Reading lights, 2 in the front and 2 in the rear
- Center console with integrated storage compartment, center armrest, cup holders
- Emergency call service
- Radio: Media System Plus
- Tire pressure monitoring system
- Wheels: Tyre fit
- Electromechanical power steering
- Seats: Comfort seats
- Seats: Lumbar support for driver and front passenger
- Seats: Front seats with height adjustment
- Sun visors with illuminated makeup mirror
- Start-stop technology
- Front Assist area monitoring system with City Emergency Braking function
- Virtual Cockpit
- Electronic immobilizer
- Central locking, including tailgate, with remote control
- Storage compartment for glasses
- Airbags
- Adaptive Cruise Control (ACC) up to 210 km/h
- Exterior mirror housings in body color
- Owner's manual holder under the driver's seat
- Chrome applications in the interior
- Roof rails in black
- Electronic differential lock (XDS)
- Three-point automatic seat belts, front and rear
- Electronic parking brake including auto-hold function
- Electric windows front and rear
- Gear recommendation display
- luggage compartment cover
- Illuminated glove compartment
- Rear window wiper and rear window heater
- ISOFIX child seat restraint system
- Air conditioning
- Black radiator grille
- Light sensor with automatic headlight control
- Fatigue detection
- LED fog lights with cornering light function
- Upholstery: Cloth
- Rain sensor
- Wheels: 4 "Dynamic" alloy wheels
- SEAT CONNECT
- Seats: Front passenger seat backrest can be folded down completely
- Seats: Rear bench seat longitudinally adjustable and asymmetrically split and foldable
- Lane departure warning system
- LED daytime running lights
- Variable luggage compartment floor
- Lashing eyes in the luggage compartment
- Full LED headlights
- thermal insulation glazing

### Extra equipment

- Swiveling towbar with electric release
- Deletion of the lettering on the tailgate
- Paint finish: Metallic
- Steering wheel: Multifunction leather steering wheel, heated
- Package: Driver Assistance Package L for Navigation. PDI
- Package: Winter (STYLE) (Heated front seats)
- Panoramic glass sliding roof, electric, including sunshade blind.
- Rear view camera
- Anti-theft alarm system including interior monitoring. WHAT
- Luggage partition net (including remote release for folding down the rear seat backrest)
- Package: Business Package NAVIGATION (Navigation system with 9.2" color touchscreen, voice control - Full Link: Android Auto, Apple CarPlay - Wireless charger in the storage compartment of the center console - Spare wheel as emergency wheel)
- Park Assist with front and rear parking aid

## Brief expert findings

| | |
|---|---|
| Documents submitted | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection. |
| Inspection | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle. |
| Test drive | No test drive/shunting maneuver was carried out during the inspection of the vehicle. |
| Engine function test | An engine test run was performed. |

## Value reducing factors

| No. | Component group | Description |
|---|---|---|
| 1 | Door - front right side | Door (schleifen + polieren) - Scratch(es) - Smart repair |
| 2 | Wing mirror - right side | Cap - Scratch(es) - Smart repair |
| 3 | Front bumper | Front bumper - Scratched - Smart repair |
| 4 | Rear bumper | Rear bumper - Scratched - Smart repair |
| 5 | Wheel / tyres | Tyre - front right side - Damaged - Replace |
| 6 | Rear bumper | Spoiler - Scratched - Replace |

## Wear and tear

| No. | Component group | Description |
|---|---|---|
| 1 | Side panel - rear left side | Wheel well extension - Scratch(es) - No deduction |
| 2 | Indicator - front | Mirror - left side - Scratch(es) - No deduction |
| 3 | Mudguard - right side | Mudguard - right side - Scratch(es) - No deduction |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  *(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  *(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

## Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.




**Figure 1:** Diagonal front (left)




**Figure 2:** Diagonal front (right)




**Figure 3:** Diagonal rear (left)




**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear



**Figure 7:** Instrument cluster



**Figure 8:** Instrument panel

**Figure 9:** Interior 360° view (Online Link)



**Figure 10:** Cargo area





**Figure 11:** VIN



**Figure 12:** Mounted tyres



**Figure 13:** Mounted tyres




**Figure 14:** Documents




**Figure 15:** Documents



**Figure 16:** Additional tyres




**Figure 17:** Navigation




**Figure 18:** Misc.



**Figure 19:** Misc.



**Figure 20:** Misc.



**Figure 21:** Misc.



**Figure 22:** Misc.



**Figure 23:** Misc.



**Figure 24:** Misc.



**Figure 25:** Misc.




**Figure 26:** Misc.




**Figure 27:** Misc.






**Figure 28:** Misc.




**Damage 1:** Door - front right side: Door (schleifen + polieren) - Scratch(es) - Smart repair



**Damage 1:** Door - front right side: Door (schleifen + polieren) - Scratch(es) - Smart repair



**Damage 2:** Wing mirror - right side: Cap - Scratch(es) - Smart repair



**Damage 2:** Wing mirror - right side: Cap - Scratch(es) - Smart repair



**Damage 3:** Front bumper: Front bumper - Scratched - Smart repair



**Damage 3:** Front bumper: Front bumper - Scratched - Smart repair



**Damage 4:** Rear bumper: Rear bumper - Scratched - Smart repair




**Damage 4:** Rear bumper: Rear bumper - Scratched - Smart repair



**Damage 4:** Rear bumper: Rear bumper - Scratched - Smart repair




**Damage 4:** Rear bumper: Rear bumper - Scratched - Smart repair



**Damage 5:** Wheel / tyres: Tyre - front right side - Damaged - Replace




**Damage 5:** Wheel / tyres: Tyre - front right side - Damaged - Replace




**Damage 6:** Rear bumper: Spoiler - Scratched - Replace



**Damage 6:** Rear bumper: Spoiler - Scratched - Replace



**Damage 6:** Rear bumper: Spoiler - Scratched - Replace



**Damage 6:** Rear bumper: Spoiler - Scratched - Replace



**Damage 6:** Rear bumper: Spoiler - Scratched - Replace