ARVAL
BNP PARIBAS GROUP


2CGX456


INSPECTION REPORT


End of contract

GENERAL INFO

File	321445
License plate	2CGX456
Vehicle identification number	WBY41DU030S398226
Dossier	2021 360 012
Make	BMW iX3
Mileage	125877
First registration	20/07/2022
client availability date	02/09/2026
inspectionDate	09/09/2026




CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	



0
Onderhoud over
062028
10:05
P
+19.0


B
2-CGX-456
BELCAR

DAMAGES

Damages	Type	Acceptable
117	Wing Rear Left / Trim / Replace	N
133	Bumper Rear // Painting	N
187	Wing Rear Right / Trim / Replace	N
197	Door Rear Right / Trim / Replace	N
13	Bumper Front // Painting	N
33	Front Bonnet // Repair & Painting	Y
72	Side View Mirror Left // Painting	N
73	Side View Mirror Left // Replace Not Painted	N
81	Door Front Left // Smart Repair Medium	Y
103	Door Rear Left // Painting	Y
153	Rear Bonnet // Painting	Y
184	Wing Rear Right // Repair & Painting	Y
193	Door Rear Right // Painting	N
216	Door Front Right // Polish	Y
334	Wheel Rear Right / Wheel Cover / Replace	N
344	Wheel Front Right / Wheel Cover / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Door Rear Left // Painting-scratch





Door Front Left // Smart Repair Medium-scratch











Bumper Front // Painting-scratch




Wheel Front Right / Wheel Cover / Replace-scratch

Door Front Right // Polish-scratch




Rear Bonnet // Painting-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch





Door Rear Right // Painting-scratch




Side View Mirror Left // Painting-scratch




Front Bonnet // Repair & Painting-scratch + dent

Wing Rear Right // Repair & Painting-scratch + dent






Wheel Rear Right / Wheel Cover / Replace-cracked




Side View Mirror Left // Replace Not Painted-cracked





Door Rear Right / Trim / Replace-scratch





Wing Rear Right / Trim / Replace-scratch




Wing Rear Left / Trim / Replace-scratch





Bumper Rear // Painting-scratch