MACADAM










VOLVO XC90: GC-722-XE

Vinnumber:	**YV1LFBMVDN1810943**	Versionname:	**VOLVO XC90 Recharge T8 AWD GT 8 Inscription VP [5P] bva 8-390CH-19cv (SUV)**
First Registrationdate:	**9/11/2021**	Fiscalpower:	
Expertise Mileage:	**127770**	Power Kw:	**287**
Bodytype:	**Off-road**	Body colour	**Grey**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Black**
Fueltype:	**Plug-in hybrid**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**7**		
Number head rests	**7**		
Type of rims (mounted)	**Aluminium**		
Category	**Passenger Car**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**2**	Seats electric F L	
GPS big screen color		Seats electric F R	
Windows electric F		Sun Roof electric	
Windows electric R		Panoramic roof	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Steering wheel leather		Headlights Xenon/LED/Laser	
Type of climate control	**Autom climate control**	Front parking sensors	
		Rear parking sensors	
		Rear view camera	
		Seat cover lining	**Lining Leather**

Tyres

Summer tyres:	**275/45/20/110 V**			
	Fr.L.	**Michelin: 45%**	Fr.R.	**Michelin: 45%**
	Re.L.	**Michelin: 35%**	Re.R.	**Michelin: 35%**

Tyre profile depth FL	**5.2**
Tyre profile depth FR	**5.2**
Tyre profile depth RL	**5.8**
Tyre profile depth RR	**5.9**
Tyre size FL	**275/45 R 20 110 V**
Tyre size FR	**275/45 R 20 110 V**
Tyre size RL	**275/45 R 20 110 V**
Tyre size RR	**275/45 R 20 110 V**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**261**
Tyre make FR	**261**
Tyre make RL	**261**
Tyre make RR	**261**

Assistance equipment


Floor mat F, Tear, Replace



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim RL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Door FL, Scratch(es), Paint



Bumper F, Bad repair, Repair and paint (complete)







Wing trim FR, Bad repair, Paint






Door RR, Bad repair, Repair and paint (complete)





Door FR, Bad repair, Repair and paint (complete)





Bumper R, Scratch(es), Paint







Wiper arm rear, Incomplete, Replace




ALPHABET

Historique Maintenance

Immatriculation: **GC-722-XE** Date de 1ère immatriculation: **09/11/2021**

Modèle: **Volvo XC90 Recharge T8 AWD GT 8 Inscription VP [5P] bva 8-390CH-19cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
01/10/2025	108.872	A.B.V.V. AUTOMOBILES	REVISION
	0		LIQUIDE DE FREIN
	0		BALAI ESSUIE GLACE AR
	0		BALAIS ESSUIE GLACE AV
15/05/2025	100.745	A.B.V.V. AUTOMOBILES	DIAG
	0		DIVERS ELEC
18/09/2024	85.452	A.B.V.V. AUTOMOBILES	REMPLACEMENT PNEUS ETE
18/09/2024	85.452	A.B.V.V. AUTOMOBILES	REVISION
	0		PLAQUETTES AR RPLT
14/09/2023	57.120	A.B.V.V. AUTOMOBILES	BALAIS ESSUIE GLACE AV
	0		LIQUIDE DE FREIN
	0		REVISION ET CLIM ET AIR ET BOUGIES
22/09/2022	29.015	ACTENA AUTOMOBILES	REVISION ET CLIM