TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48405768
Order No. / Reference: 27224923
Inspection date: 27 Oct 2026

Manufacturer: MAN	Model: TGE 3,5T 4x2F (03V)
VIN: WMA03VUY3P9023155	





Vehicle details

Manufacturer / Type / Model / Equipment	
MAN TGE 3,5T 4x2F (03V)	
Vehicle Identification number	WMA03VUY3P9023155
Mileage (Read)	85,471 km
First registration	20 Jul 2023
Number of holders	1
Next periodical technical inspection	06/2027
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	103 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Candy Weiß Uni
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black
Re-import	no
readiness to drive	Not roadworthy / moveable

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	13,000 km
Last service on / at	05/2026 at 78,410 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GW443186
Previous damage / Accident	None detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Not roadworthy / moveable		
Manufacturer key number/ type code number	1516 / AYN 61613		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,500 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/75 R16 113R	All-season tyres on Steel	Continental	3mm / 2mm
2)	205/75 R16 113R	All-season tyres on Steel	Continental	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	205/75 R16 113R C	All-season tyres on Steel	Continental	9 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Equipment

- "Multifunction display ""Plus"" "
- "Front disc brakes, 16"" "
- "Seat ""Standard"" right "
- 2 remote flip keys
- 3-button module
- 4 steel wheels 6 1/2 J x 16, with a load capacity of 1,050 kg, in silver
- 6-speed
- Exhaust concept, EU6 AR
- Airbag for driver and front passenger with front passenger airbag deactivation
- Component set without country-specific building regulations
- Operating voltage 12 V
- Onboard literature in German
- CO2-optimized variant
- Digital radio reception (DAB+)
- Three-phase generator 140 A
- A tow hook at the front
- Entry handle on the partition wall in the cargo area
- Factory
- Driver/passenger airbag
- Vehicle class differentiation-7C0-
- Suspension/damping and stabilization package 1
- Front drive
- All-season tyres
- Weight range front axle class 2
- Gray Mesh-Man Black/Titanium Black-Palladium/Pearl Gray
- Seatbelt monitoring, electrical contact in the seatbelt buckle
- Lockable glove compartment
- Rear wing doors 270° opening
- Rear wing doors without window cutouts
- Signposts without country group
- High roof, painted in the car's color on the outside
- Interior noise dampening measures Plus
- Instrument panel
- Not a special vehicle, standard version
- Fuel tank 75l
- LED interior lighting
- Unladen weight range 3
- Left-hand drive
- MAN brand/class specific features
- MAN SmartLink
- With first-aid supplies and a warning triangle
- Standard engine start
- Not hot country
- Without roof-mounted turn signals
- Without voice control
- Center wheel cover
- Digital radio reception
- Long wheelbase 4,490 mm with long overhang
- Tires without specifying the tire brand
- "Reversing camera ""Rear View"""
- "Seat ""Comfort"" left "
- Single-layer solid color - Candy white
- 205/75 R 16 C
- 4 speakers
- 4-cyl. turbo diesel engine 2.0 l/103 KW (4V) common rail
- 4490mm with extended frame (L5)
- from 09.2018
- Filing package
- Exterior mirrors, electrically adjustable and heated
- 520A (92Ah) battery
- Hill start assist
- Operating permit supplement C38
- Floor in the cargo area
- On-board tools and jack
- Roof gallery with storage compartments, two 1-DIN slots and reading light
- Three-point automatic seat belts with belt height adjustment and electric belt tensioners at the front
- Electronic Stability Program (ESP) and ABS with electronic differential lock
- Cab doors, additionally with reinforced door hinges on the driver's side
- Front Assist with City Emergency Braking function
- Radio frequency 433 MHz
- Generator 140 A
- Weight class front axle, weight range 2
- Rubber flooring in the driver's cab
- Halogen dual headlights
- Handbrake lever, standard
- Glove compartment with lockable, illuminated flap
- Rear wing doors with an enlarged opening angle
- Heating in the driver's cab, electronically controlled
- High roof (H2)
- Wooden floor in the cargo area with wheel arch cladding
- Instrument cluster, display in km/h
- panel van
- No category
- Radiator guard, black with chrome strip
- LED interior lighting concept in the passenger/cargo area
- Steering wheel
- LNFZ version with up to 3 seats
- MAN Media Van package with 4 speakers
- Side marker lights
- Mobile phone interface
- National registration documentation Germany
- Emergency brake assist
- No speed limit
- Online service, with OCU, without head unit coding, without WFS network

- Spare wheel (steel rim) with driving tires
- Rear view camera
- 6-speed manual transmission
- Sliding door, right
- Crosswind assist
- Service indicator: 50,000 km or 2 years (variable)
- Sun visors, foldable and swiveling to the side
- Start-stop system
- Daytime running light
- Rear step, across the entire width
- USB dual function module 45W
- Lashing rails (airline) in the cargo area: side walls
- Front axle (1,800 kg load capacity)
- Electronic immobilizer
- Central locking with remote control and interior operation
- Two 12V sockets in the driver's cab (in the instrument panel)
- Wheel bolts without wheel locking mechanism
- Smoker's version: 12V socket with cigarette lighter, ashtray, 4 cup holders in the dashboard
- Spare wheel in driving tire size, steel, as well as on-board tools and jack
- Windscreen wiper intermittent control
- Sliding door, right, in the cargo/passenger compartment
- Side marker lights
- Seat covers in "Toronto Grid" fabric
- Standard climate zones
- Start-stop system with brake energy recuperation
- Partition wall
- Type testing country: Germany
- Laminated glass windshield in heat-insulating glazing
- Lashing eyes for securing cargo
- Front axle weight version 1
- Central locking with remote control
- Approval as 3.5t

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was not capable of driving under its own power at the time of inspection, but can be moved on its own axle with the aid of assistance.

Value reducing factors

No.	Component group	Description
1	Side panel - rear left side	Side panel (Zierleiste) - Scratch(es) - Loss in value
2	Sliding door, right	Sliding door - dent(s) - Smart repair
3	Side panel - rear left side	Side panel - dent(s) - Smart repair
4	Boot lid / rear door	Rear door - right side - Dent / paintcoat damage - Smart repair
5	Boot lid / rear door	Rear door - left side - Dent / paintcoat damage - Smart repair
6	Wheel / tyres	Tyre - rear right side - Porous / cracked - Replace
7	Rear bumper	Rear bumper (Reflektor rechts) - Broken / torn - Replace
8	Tail light	Tail lamp - left side - Broken / torn - Replace
9	Tail light	Tail lamp - right side - Broken / torn - Replace
10	Wheel / tyres	Tyre - front (Zusätzlich VR porös) - Worn - Replace
11	Body	Body - Glued / labelled - De-glue / neutralise
12	Door - front right side	Door - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Front bumper	Front bumper - Scratch(es) - No deduction
2	Sill - right side	Sill - Scratch(es) - No deduction
3	Side panel - rear right side	Side panel (Zierleiste) - Scratch(es) - No deduction
4	Roof	Roof - dent(s) - No deduction
5	Vehicle glazing	Windscreen - Stone chips - No deduction
6	Wing mirror - right side	Cap - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Repainting

No.	Repainting
1	Side panel - rear right side, Professionally carried out

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Damage 1: Side panel - rear left side: Side panel (Zierleiste) - Scratch(es) - Loss in value



Damage 1: Side panel - rear left side: Side panel (Zierleiste) - Scratch(es) - Loss in value



Damage 2: Sliding door, right: Sliding door - dent(s) - Smart repair



Damage 2: Sliding door, right: Sliding door - dent(s) - Smart repair



Damage 2: Sliding door, right: Sliding door - dent(s) - Smart repair



Damage 2: Sliding door, right: Sliding door - dent(s) - Smart repair



Damage 2: Sliding door, right: Sliding door - dent(s) - Smart repair



Damage 3: Side panel - rear left side: Side panel - dent(s) - Smart repair



Damage 3: Side panel - rear left side: Side panel - dent(s) - Smart repair



Damage 3: Side panel - rear left side: Side panel - dent(s) - Smart repair



Damage 4: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Smart repair



Damage 4: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Smart repair



Damage 4: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Smart repair



Damage 4: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Smart repair



Damage 5: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Smart repair



Damage 5: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Smart repair



Damage 5: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Smart repair



Damage 5: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - Smart repair



Damage 6: Wheel / tyres: Tyre - rear right side - Porous / cracked - Replace



Damage 6: Wheel / tyres: Tyre - rear right side - Porous / cracked - Replace



Damage 6: Wheel / tyres: Tyre - rear right side - Porous / cracked - Replace



Damage 6: Wheel / tyres: Tyre - rear right side - Porous / cracked - Replace



Damage 7: Rear bumper: Rear bumper (Reflektor rechts) - Broken / torn - Replace



Damage 7: Rear bumper: Rear bumper (Reflektor rechts) - Broken / torn - Replace



Damage 7: Rear bumper: Rear bumper (Reflektor rechts) - Broken / torn - Replace



Damage 7: Rear bumper: Rear bumper (Reflektor rechts) - Broken / torn - Replace



Damage 8: Tail light: Tail lamp - left side - Broken / torn - Replace



Damage 8: Tail light: Tail lamp - left side - Broken / torn - Replace



Damage 9: Tail light: Tail lamp - right side - Broken / torn - Replace



Damage 9: Tail light: Tail lamp - right side - Broken / torn - Replace



Damage 9: Tail light: Tail lamp - right side - Broken / torn - Replace



Damage 9: Tail light: Tail lamp - right side - Broken / torn - Replace



Damage 10: Wheel / tyres: Tyre - front (Zusätzlich VR porös) - Worn - Replace



Damage 10: Wheel / tyres: Tyre - front (Zusätzlich VR porös) - Worn - Replace



Damage 10: Wheel / tyres: Tyre - front (Zusätzlich VR porös) - Worn - Replace



Damage 10: Wheel / tyres: Tyre - front (Zusätzlich VR porös) - Worn - Replace



Damage 10: Wheel / tyres: Tyre - front (Zusätzlich VR porös) - Worn - Replace



Damage 10: Wheel / tyres: Tyre - front (Zusätzlich VR porös) - Worn - Replace



Damage 11: Body: Body - Glued / labelled - De-glue / neutralise



Damage 11: Body: Body - Glued / labelled - De-glue / neutralise



Damage 11: Body: Body - Glued / labelled - De-glue / neutralise



Damage 11: Body: Body - Glued / labelled - De-glue / neutralise



Damage 12: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 12: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 12: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 12: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 12: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 12: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 12: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 12: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Repainting 1: Side panel - rear right side



Repainting 1: Side panel - rear right side