TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

# Expertise

Protocol number: 48566461
Order No. / Reference: 27260291
Inspection date: 5 Nov 2026

| | |
|---|---|
| Manufacturer: Mercedes-Benz | Model: B 180 d 8G-DCT Entry |
| VIN: W1K4F1AB2RJ615913 | |







## Vehicle details

| | |
|---|---|
| **Manufacturer / Type / Model / Equipment** | |
| Mercedes-Benz B 180 d 8G-DCT Entry | |
| **Vehicle Identification number** | W1K4F1AB2RJ615913 |
| **Mileage** (Read) | 66,139 km |
| **First registration** | 11 Dec 2024 |
| **Number of holders** | 1 |
| **Fuel type** | Diesel |
| **Engine displacement / Cylinder** | 1,950 ccm / 4 |
| **Power** | 85 kW |
| **Gearbox / Number of gears** | Automatic / |
| **Type of gearbox** | 8 |
| **Type of drive** | Front drive |
| **Type of vehicle** | Car station wagon |
| **Colour / colour code** | Mountaingrau Metallic |
| **Doors / Seats** | 5 / 5 |
| **Upholstery type** | Artificial leather |
| **Colour of upholstery** | Black |

TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

## Vehicle details

| | | | |
|---|---|---|---|
| **Maintenance booklet / proof** | digital proof / complete | **Next maintenance in** | 342 Tag(e) |
| **Last service on / at** | 10/2026 at 65,570 km | | |
| **Key is / should be** | 2 / 2 | **FZG documents** | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
| | | **Letter No.** | HB185638 |
| **Previous damage / Accident** | None detectable | **Repainting** | None detectable |
| **Inspection conditions** | sufficient | **Lifting equipment / pit** | No |
| **Test drive** | Not performed | **Engine function test** | Performed |
| **Manufacturer key number/ type code number** | 2222 / AYA 00073 | | |
| **Emission standard** | EURO6 | **fine dust sticker** | |
| **Permitted total weight** | 2,075 kg | **Empty weight** | |

## Tyres

### Mounted tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 205/55 R17 91H | Winter tyres on Light alloy | Hankook | 7mm / 7mm |
| 2) | 205/55 R17 91H | Winter tyres on Light alloy | Hankook | 6mm / 6mm |

### Additional tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 205/55 R17 91W | Summer tyres on Light alloy | Continental | 5mm / 5mm |
| 2) | 205/55 R17 91W | Summer tyres on Light alloy | Continental | 5mm / 5mm |

### Replacement

| Typ | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| | Tirefit | Expiration date 04/2029 | | |

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**

## Equipment

### Standard equipment

- Storage compartment in center console with roller blind
- Airbag for driver and front passenger
- Airbag: Automatic passenger airbag deactivation
- Airbag: Side airbag for driver and front passenger
- Anti-lock braking system (ABS)
- Foldable armrest in the center console for driver and front passenger
- Outdoor temperature display
- Basic services
- Diesel particulate filter
- Door sills with "Mercedes-Benz" lettering
- Chassis: Comfort chassis with lowered suspension
- Velour floor mats
- Transmission: 8G-DCT automatic
- Rear lights with taillights and brake lights using LED light guide technology
- Heated rear window with timer
- ISOFIX child seat attachment with top tether in the rear
- THERMATIC automatic climate control
- Front headrests are height-adjustable
- Steering wheel: Multifunction sports steering wheel in leather
- Steering: Direct steering
- Navigation: MBUX Navigation Premium
- Package: USB Package Plus
- Radio: MBUX multimedia system
- Radio accessories: Digital radio
- Remote Services
- Rear view camera
- Seats: Comfort seats
- Heated seats for driver and front passenger
- Bumpers in body color
- TIREFIT with tire inflation compressor
- Electronic immobilizer
- Decorative elements Star Pattern
- ADAPTIVE BRAKE with hill start assist, HOLD function, pre-filling and drying braking in wet conditions
- Airbag: Kneebag for driver
- Airbag: Windowbag
- Traction control (ASR)
- ATTENTION ASSIST
- Heated exterior mirrors (left and right), electrically adjustable from inside
- Brake assist, active
- Third brake light in LED technology
- Electronic Stability Program (ESP)
- Electric windows (4-way)
- Speed Limit Assistant
- Halogen headlights with integrated LED daytime running lights
- Rear window wiper with intermittent function
- Interior headliner fabric crystal grey
- Mechanical child safety lock
- Rear headrests (3)
- Cargo area cover
- Steering column mechanically adjustable in height and length
- Mercedes-Benz emergency call system
- Package: Seating comfort
- Upholstery: ARTICO leatherette/Bertrix fabric
- Radio accessories: Central Media Display
- Tire pressure monitoring system
- Wheels: 40.6 cm (16") alloy wheels, 4-spoke design
- Seat belts B-Class
- Seats: Rear seat backrests foldable in a 40/20/40 ratio
- Lane Keeping Assist, active
- Cruise control
- Pre-installation for digital key handover
- Central locking with remote control

### Extra equipment

- Elimination of type designation
- Package: Winter package (heated steering wheel - heated windshield washer system)
- Package: Winter Package Plus with 40.6 cm (17") winter complete wheels (Winter Package - 43.2 cm (17") light alloy wheels in 5-twin-spoke design, aerodynamically optimized, vanadium silver painted with 215/65 R17 on 6.5J x 17 ET44)
- Paint finish: Metallic (according to sample card)
- Phone accessories: Smartphone integration (consisting of Apple CarPlay and Android Auto)
- Separation net
- Traffic Sign Assistant
- Wheels: Complete summer wheel sets fitted at the factory
- Fully digital instrument display (Experience the full range of digital display options. The large, high-resolution 10.25" display can be individually configured – for example, classically with speedometer on the left and tachometer on the right.)
- Package: Advanced (LED High Performance headlights - EASY-PACK tailgate - Mirror package (automatically dimming interior mirror, electrically folding exterior mirrors) - Parking package with reversing camera (Active Parking Assist with PARKTRONIC) - 4-way lumbar support - Adaptive Highbeam Assist)
- Wheels: 43.2 cm (17") alloy wheels, 4-piece set in 5-twin-spoke design (aerodynamically optimized, painted black and polished with 205/55 R17 tires on 6.5J x 17 ET44 rims)

## Brief expert findings

| | |
|---|---|
| Documents submitted | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection. |
| Inspection | The inspection conditions were sufficient for the assessment of the vehicle.<br>No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent. |
| Test drive | No test drive/shunting maneuver was carried out during the inspection of the vehicle. |
| Engine function test | An engine test run was performed. |

## Value reducing factors

| No. | Component group | Description |
|---|---|---|
| 1 | Boot lid / rear door | Boot lid - dent(s) - Smooth repair work |
| 2 | Rear bumper | Rear bumper - Scratch(es) - Smart repair |
| 3 | Trim / covers | Door trim - rear left side - Scratch(es) - Replace |
| 4 | Trim / covers | Door trim - rear right side - Scratch(es) - Replace |
| 5 | Front bumper | Front bumper - Scratch(es) - Paint |

## Wear and tear

| No. | Component group | Description |
|---|---|---|
| 1 | Interior | Interior - Scratch(es) - No deduction |
| 2 | Vehicle glazing | Windscreen - Stone chips - No deduction |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  *(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  *(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

## Comments

- Die Unterbodenbesichtigung war nur ebenerdig
und eingeschränkt möglich.
- Mehrkosten möglich




**Figure 1:** Diagonal front (left)




**Figure 2:** Diagonal front (right)




**Figure 3:** Diagonal rear (left)




**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear




**Figure 7:** Instrument cluster



**Figure 8:** Instrument panel



**Figure 9:** Cargo area




**Figure 10:** VIN



**Figure 11:** Mounted tyres




**Figure 12:** Documents




**Figure 13:** Documents



**Figure 14:** Additional tyres




**Figure 15:** Navigation





**Figure 16:** Misc.



**Figure 17:** Misc.




**Figure 18:** Misc.



**Figure 19:** Misc.



**Figure 20:** Misc.




**Figure 21:** Misc.



**Figure 22:** Misc.




**Figure 23:** Misc.



**Figure 24:** Misc.




**Figure 25:** Misc.




**Figure 26:** Misc.




**Figure 27:** Misc.



**Figure 28:** Misc.



**Figure 29:** Misc.




**Figure 30:** Misc.




**Figure 31:** Misc.



**Figure 32:** Misc.




**Figure 33:** Misc.




**Figure 34:** Misc.



**Damage 1:** Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



**Damage 1:** Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



**Damage 2:** Rear bumper: Rear bumper - Scratch(es) - Smart repair



**Damage 2:** Rear bumper: Rear bumper - Scratch(es) - Smart repair



**Damage 3:** Trim / covers: Door trim - rear left side - Scratch(es) - Replace




**Damage 3:** Trim / covers: Door trim - rear left side - Scratch(es) - Replace



**Damage 4:** Trim / covers: Door trim - rear right side - Scratch(es) - Replace



**Damage 4:** Trim / covers: Door trim - rear right side - Scratch(es) - Replace



**Damage 5:** Front bumper: Front bumper - Scratch(es) - Paint



**Damage 5:** Front bumper: Front bumper - Scratch(es) - Paint



**Damage 5:** Front bumper: Front bumper - Scratch(es) - Paint