APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	HM Tongeren
Make:	BMW
Model / version:	X3
Vin:	WBATS110509H28050
Plate:	2ASL896
Mileage:	120214
SOH:	
First registration:	30/06/2021
Color:	Sophistograu

ADDITIONAL INFORMATION


Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?


DOCUMENTS


Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book:	
Number of keys:	2
Original key:	✓


PICTURES













































VIN INFORMATION

10 Haut-parleurs
Equipement Advantage
Diamètre avant 18
Largeur arrière 7,0
Hauteur avant 60
Indice de vitesse arrière W
Climatisation automatique 2 zones
1998 cm3
292 ch
Rétroviseur gauche jour/nuit automatique
Rétroviseur intérieur jour/nuit automatique
Transmission automatique
Matière : alliage
Diamètre arrière 18
Diamètre avant 18
Hauteur arrière 60
Largeur avant 225
Climatisation réfrigérant 1234YF
2.00 litres
Euro 6
Rétroviseur droit jour/nuit automatique
Siège avant gauche chauffant
8 rapports
Lettre repère (J)
Largeur avant 7,0
Diamètre arrière 18
Indice de vitesse avant W
Largeur arrière 225
Hybride essence
215 kw
Minérale vernissée
Rétroviseurs rabattables électriques
Sièges avant chauffants

Siège avant gauche à réglage électrique
Sièges avant à réglage mémorisé
Aide au stationnement arrière
Caméra arrière de recul
Vitres de portes avant acoustiques
Toit ouvrant vitré panoramique
Protection piéton

Contrôle pression des pneus
mesures CO2 étendues
tuner DAB
protection acoustique des piétons spécifique Europe

Sièges avant à réglage électrique
Garnitures cuir
Assistance au parking
Alarme
Vitres de portes arrière acoustiques
Attelage avec boule rétractable électrique
Freinage d'urgence assistée autonome (urbain)
depuis 04.21
système d'accès confort
filet de séparation coffre
chargeur sans fil

Siège avant gauche à réglage mémorisé
Aide au stationnement avant
Caméra avant
Appel de secours
Toit ouvrant électrique
Fixotoit aluminium satiné
Avertisseur de collision avant

pack de rangement
contrôle gestuel
BMW Live Cockpit Pro
boulons antivol de roue

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	×	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	×
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	1	**Fast charging cables:**	1

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm		225/60R18 104W	Summer		?
Front right	5 mm		225/60R18 104W	Summer		?
Rear left	5 mm		225/60R18 104W	Summer		?
Rear right	5 mm		225/60R18 104W	Summer		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Contact key - Boordcomputer resetten	Not original part
3	Windscreen - Ontstickeren	Not original part
4	Wing FL	Dent(s)
5	Alloy rim FL	Grooved
6	Door RL	Dent(s) and scratch(es)
7	Bumper R	Grooved
8	Door RR	Dent(s) and scratch(es)
9	Wing RR	Dent(s) and scratch(es)
10	Outside rear-view mirror housing R	Scratch(es)
11	Alloy rim FR	Grooved

Total: 10

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
2	Bodywork	Dent(s) and scratch(es)	✓	×	×

Total: 1

DAMAGES DETAILS

1 - Contact key - Boordcomputer resetten - Not original part




3 - Windscreen - Ontstickeren - Not original part




4 - Wing FL - Dent(s)





5 - Alloy rim FL - Grooved





6 - Door RL - Dent(s) and scratch(es)





7 - Bumper R - Grooved








8 - Door RR - Dent(s) and scratch(es)







9 - Wing RR - Dent(s) and scratch(es)








10 - Outside rear-view mirror housing R - Scratch(es)





11 - Alloy rim FR - Grooved


2 - Bodywork - Dent(s) and scratch(es) - Renta®











SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

21/10/2026 11:46