TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Expertise

Protocol number: 48115122
Order No. / Reference: 27080880
Inspection date: 14 Oct 2026

Manufacturer: Ford	Model: S-Max 2.0 EcoBlue Aut. Trend
VIN: WF0JXXWPCJNM10465	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford S-Max 2.0 EcoBlue Aut. Trend	
Vehicle Identification number	WF0JXXWPCJNM10465
Mileage (Read)	52,377 km
First registration	12 Oct 2022
Number of holders	1
Next periodical technical inspection	10/2027
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,995 ccm / 4
Power	140 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Car station wagon
Colour / colour code	Magnetic-Grau Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite-Black

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	7,000 km
Last service on / at	11/2024 at 29,923 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GP431495
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8566 / BQR 00353		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,555 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R17 103V	Summer tyres on Light alloy	Continental	4mm / 4mm
2)	235/55 R17 103V	Summer tyres on Light alloy	Continental	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R17 103V	Winter tyres on Light alloy	Bridgestone	4mm / 4mm
2)	235/55 R17 103V	Winter tyres on Light alloy	Pirelli	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 08/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments
- Exterior mirrors in body color, driver and passenger side, electrically adjustable and heated
- third brake light
- Dual exhaust system
- Driver information system display 10.7cm color
- Electronic parking brake
- luggage compartment cover
- Transmission: 8-speed automatic transmission
- rear window wiper
- Intelligent security system
- Electric child safety lock
- Radiator grille
- Steering wheel: Steering column, adjustable in height and reach
- Steering wheel: Paddle shifters on the steering wheel
- Front center console with padded armrest
- Fog light
- Upholstery: Cloth
- Tire repair kit
- Headlight dipped beam with switch-off delay including "greeting function"
- Seats: Flexible seating system "FoldFlatSystem (FFS)"
- Seats: Front sports seats
- Storage compartment under driver and passenger seats
- Daytime running light
- Warning system for unfastened seat belts for the 1st and 2nd rows of seats
- Anti-lock braking system (ABS)
- Tires: 7.5 J x 17 alloy wheels (4) with 235/55 R 17 tires
- Hill start assist
- Diesel particulate filter (DPF)
- Tachometer
- Electric windows front and rear
- Ford Power Start function
- Luggage compartment lighting
- Back window, heater
- Interior lighting with delay circuit
- Isofix mount
- Air conditioning with automatic temperature control
- Paint finish: Solid
- Steering wheel: Multifunction leather steering wheel and leather gear knob
- Reading lights front and rear
- MyKey key system (individually programmable second key)
- Emergency brake light
- Radio equipment: CD audio system
- Tire Pressure Monitoring System (TMPS)
- Electromechanical power steering
- Seats: Driver and passenger seats, 4-way manually adjustable
- Start-stop system
- Power outlet: 12-volt connection at the front
- Carpet floor mats in the front
- Immobiliser
- Central locking with remote control

Extra equipment

- Airbag: Side airbags on the outer seats of the 2nd row.
- BUSINESS PACKAGE I
- Roof rails "aluminum look"
- Paint finish: Magnetic Grey Metallic and Cyan Blue Metallic
- Package: Winter (heated windscreen - individually and variably heated front seats)
- Radio equipment: CD audio system including Ford SYNC 3 with AppLink, touchscreen and Ford navigation system (radio/CD player, MP3-compatible, 2 USB ports, 8 speakers, steering wheel remote control, 20.3 cm screen diagonal), communication and entertainment system with extended voice control, Bluetooth interface, integration of various telephony functions and hands-free systems with voice command control, SMS text-to-speech function with display, music playback, Bluetooth audio streaming, emergency call assist, control of selected smartphone apps, support for Android Auto and Apple CarPlay)
- Reversing camera with display (including front and rear parking assist system)
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Power outlet: 230-volt connection (150 watts) (in the passenger compartment)
- Detachable towbar (ESP trailer stabilization - continuous power supply - switched power supply - hill start assist)
- Cruise control system with intelligent speed limiter (interior mirror, automatically dimming - traffic sign recognition system)
- Active Park Assist (with parking and exiting function and front and rear parking pilot system)
- Radio equipment: CD audio system including Ford SYNC 3 with AppLink, touchscreen, DAB and Ford navigation system (radio/CD player, MP3-compatible, 2 USB ports, 8 speakers, steering wheel remote control, 20.3 cm screen diagonal, communication and entertainment system with extended voice control, Bluetooth interface, integration of various telephony functions and hands-free systems with voice command control, SMS text-to-speech function with display, music playback, Bluetooth audio streaming, emergency call assist, control of selected smartphone apps, support for Android Auto and Apple CarPlay, DAB/DAB+)
- Safety partition net behind the 2nd row of seats
- Sunshades in the rear side doors (manual)
- LED daytime running lights

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace

Wear and tear

No.	Component group	Description
1	Door - front right side	Door - Scratch(es) - No deduction
2	Front bumper	Front bumper - Stone chips - No deduction
3	Interior	Interior - Scratch(es) - No deduction
4	Bonnet	Bonnet - Stone chips - No deduction
5	Vehicle glazing	Windscreen - Stone chips - No deduction
6	Rear bumper	Rear bumper - Scratch(es) - Cover / polish

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Rear of vehicle - Key trailer hitch (2 Schlüssel)

Rear of vehicle - Trailer hitch - removable

Interior - Separation net

Accident damages

No.	Accident
1	Side - left

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig und eingeschränkt möglich.
- Mehrkosten möglich .



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Wear and tear 1: Door - front right side: Door - Scratch(es) - No deduction



Wear and tear 6: Rear bumper: Rear bumper - Scratch(es) - Cover / polish




Wear and tear 6: Rear bumper: Rear bumper - Scratch(es) - Cover / polish



Missing part 1: Rear of vehicle: Key trailer hitch (2 Schlüssel) - Missing - Replace



Missing part 2: Rear of vehicle: Trailer hitch - removable - Missing - Replace



Missing part 3: Interior: Separation net - Missing - Replace



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left



Accident 1: Side - left