TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

# Expertise

Protocol number: 48090241
Order No. / Reference: 27067122
Inspection date: 13 Oct 2026

| Manufacturer: Audi | Model: A6 Avant 50 TDI quattro tiptronic |
|---|---|
| VIN: WAUZZZF29PN093119 | |







## Vehicle details

| | |
|---|---|
| **Manufacturer / Type / Model / Equipment** | |
| Audi A6 Avant 50 TDI quattro tiptronic | |
| **Vehicle Identification number** | WAUZZZF29PN093119 |
| **Mileage** (Read) | 175,734 km |
| **First registration** | 6 Sept 2023 |
| **Number of holders** | 1 |
| **Fuel type** | Diesel |
| **Engine displacement / Cylinder** | 2,967 ccm / 6 |
| **Power** | 210 kW |
| **Gearbox / Number of gears** | Automatic / 8 |
| **Type of drive** | All-wheel drive |
| **Type of vehicle** | Station wagon |
| **Colour / colour code** | Firmamentblau Metallic |
| **Doors / Seats** | 5 / 5 |
| **Upholstery type** | Cloth |
| **Colour of upholstery** | Black |
| **Vehicle with smoke odor** | no |

## Vehicle details

| | | | |
|---|---|---|---|
| **Maintenance booklet / proof** | digital proof / complete | **Next maintenance in** | 4,200 km |
| **Last service on / at** | 04/2026 at 149,920 km | | |
| **Key is / should be** | 2 / 2 | **FZG documents** | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
| | | **Letter No.** | GV321045 |
| **Previous damage / Accident** | None detectable | **Repainting** | None detectable |
| **Inspection conditions** | Conditional: Light/moisture/dirt | **Lifting equipment / pit** | No |
| **Test drive** | Not performed | **Engine function test** | Performed |
| **Manufacturer key number/ type code number** | 0588 / BSU 02724 | | |
| **Emission standard** | EURO6 | **fine dust sticker** | |
| **Permitted total weight** | 2,570 kg | **Empty weight** | |

## Tyres

### Mounted tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 225/60 R17 99Y | Summer tyres on Light alloy | Bridgestone | 5mm / 5mm |
| 2) | 225/60 R17 99Y | Summer tyres on Light alloy | Bridgestone | 5mm / 5mm |

### Additional tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 225/60 R17 99H | Winter tyres on Light alloy | Nexen | 5mm / 5mm |
| 2) | 225/60 R17 99H | Winter tyres on Light alloy | Nexen | 5mm / 5mm |

### Replacement

| Typ | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| N | 145/65 R20 105M | Summer tyres on Steel | Sonstige | 5 mm |

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**

## Equipment

### Standard equipment

- AdBlue tank (12 liters)
- Airbag: Front side airbags and head airbag system
- Anti-lock braking system (ABS)
- Audi connect emergency call & service m.connect remote & control
- Audi virtual cockpit plus
- Exterior mirror housings in body color
- Vehicle tool kit
- Fabric headliner
- Diesel particulate filter (DPF) with nitrogen oxide catalyst and AdBlue tank
- Door sills with aluminum inlay front and rear
- key fob
- Cruise control system with speed limiter
- Interior lighting
- ISOFIX child seat attachment and Top Tether for the outer rear seats
- Steering wheel: Leather steering wheel with multifunction controls
- Non-smoking version
- Progressive steering
- Wheel: Alloy wheels, 10-spoke design (7.5J x 17 with 225/60 R17 tires)
- Wheel: Tire pressure monitoring system
- Radio: MMI Radio plus with MMI touch response (10.1-inch color display - Audi music interface; 2 USB-C ports with data and charging function - Bluetooth interface (hands-free calling and audio streaming) - Remote MMI touch control unit with 8.6-inch color display including MMI touch response with haptic feedback; for controlling the climate control function and input field for handwriting recognition - AM/FM phase diversity - DAB+ - speed-dependent volume adjustment)
- Start-stop system
- Glazing: Windscreen in heat-insulating glazing
- Glazing: Rear window, rear door and side windows in clear glass
- Thermal insulation glazing on the sides and rear
- Airbag for driver and front passenger
- All-wheel drive "quattro" with self-locking center differential
- Audi connect navigation & infotainment
- Audi drive select
- Audi pre sense front
- Electrically adjustable and heated exterior mirrors
- Control buttons, matte black
- third brake light
- Decorative inlays, fine lacquer, graphite grey
- Tachometer
- Parking aid plus with surround view
- Electronic Stability Control (ESC)
- Luggage compartment lid, electrically opening and closing
- Transmission: 8-speed automatic transmission tiptronic
- Interior mirror dimming
- Comfort center armrest in front
- Headrests (4)
- Manual steering wheel adjustment
- MMI Navigation with MMI touch response (10.1-inch color display (1,540 × 720) - Navigation map or arrow display in the Audi virtual cockpit plus - Map updates - 3D map display - Efficiency assistant - Online traffic information - MMI search - MMI touch response for quick, intuitive operation - Easy operation of the infotainment system via natural language interaction - Detailed route information - Input of up to 10 waypoints - Selected Audi connect Navigation & Infotainment portfolio)
- Rail system with fixing set
- Fabric seat covers with effect
- Seats: Standard front seats
- Seats: Split-folding rear seat backrest Avant
- Sun visor on driver and passenger side
- Lane Departure Warning
- First aid kit including warning triangle and high-visibility vests
- Camera-based traffic sign recognition
- Electronic immobilizer
- Central locking

## Extra equipment

- AdBlue tank with increased filling volume (AdBlue tank with 22 liter filling volume - for diesel vehicles with SCR technology, to reduce nitrogen oxides in the exhaust gas)
- Electrically adjustable, heated and folding exterior mirrors, automatically dimming on both sides (including curb view function for the passenger-side exterior mirror with integrated LED turn signal, including heated windshield washer nozzles, aspherical mirror glass. The curb view function tilts the passenger-side exterior mirror downwards when reverse gear is engaged, providing the driver with a better view of the curb.)
- Headrests: variable headrests for front seats (with manual adjustment of headrest height and distance)
- Fuel tank (73 liters) (fuel tank for 73 liters of gasoline/diesel fuel)
- Paint finish: Metallic
- LED matrix headlights, LED taillights and headlight cleaning system (Matrix LED technology enables precise and high-resolution illumination of the road. When vehicles are detected by the camera system, the system selectively dims only the area of the detected vehicle, while the high beam remains active in the remaining segments. LED taillights with dynamic turn signals, brake lights, taillights, rear license plate lights, reversing lights and a single-sided rear fog light)
- Audi pre sense rear seat package (The package includes a selection of features that increase safety and comfort in the rear seat - Side airbags in the rear - Reversible rear seat belt tensioners with illuminated seat belt buckles)
- Business Package (Assistance Package Tour (adaptive speed assist, efficiency assist, turn assist, evasive steering assist, emergency assist) - 4-zone automatic climate control - heated front seats - Audi phone box - automatically dimming interior mirror - automatically dimming exterior mirrors - adaptive windscreen wipers with integrated washer nozzles - high-beam assist)
- Parking assistant with parking aid plus (The parking assistant supports parking maneuvers by making suitable steering corrections. Ultrasonic sensors search for suitable parallel and perpendicular parking spaces. For perpendicular parking spaces (forwards and backwards), the ideal parking path is calculated; for parallel parking spaces, the ideal entry and exit paths are calculated. The system takes over the steering. The driver only needs to follow the instructions on the display to change gears, accelerate, brake, and monitor the parking process.)
- Radio accessories: Audi sound system (10 speakers including center speaker and subwoofer - 6-channel amplifier - total output of 180 watts)
- Front seat heating (heats seat and backrest center panels; with leather upholstery, sport seats and sport seats plus also seat side bolsters - individually adjustable in multiple stages for driver and front passenger side via the climate control unit)
- Swiveling towbar with electric release (with swiveling ball head, trailer stabilization via electronic stability control (ESC), release via button in the luggage compartment, the integrated swiveling system socket allows continuous operation of electrical devices in the trailer or caravan while driving)
- Deletion of model designation and performance/technology lettering
- Comfort key with sensor-controlled luggage compartment unlocking (The vehicle can be opened by operating the door handle without actively using the key. To lock the vehicle from the outside, simply touch one of the sensor buttons on the door handles. The drive authorization is also activated without actively using the comfort key. The driver must be inside the vehicle and have the comfort key with them. The engine is started and stopped using the engine start/stop button in the center console.)
- Steering wheel: Double-spoke leather steering wheel with multifunction, paddle shifters and steering wheel heating (paddle shifters allow manual gear changes. The steering wheel rim is also heated).
- Assistance Package Plus (Parking Assistance Package with Remote Parking Assistant Plus (surround view cameras, Remote Parking Assistant Plus) - City Assistance Package (Intersection Assist, Lane Change Warning, Exit Warning, Rear Cross Traffic Assist, Audi pre sense 360°) - Tour Assistance Package (Adaptive Cruise Assist, Efficiency Assist, Turn Assist, Evasive Steering Assist, Emergency Assist))
- Package: Ambient lighting package plus (contour lighting front/rear doors, color-matched - ambient fabric lighting front/rear doors, color-matched - ambient lighting front center console, color-matched - contour lighting front center console, color-matched - contour lighting with illuminated quattro lettering (for all-wheel drive) on the instrument panel on the passenger side, color-matched - ambient lighting of the instrument panel)
- Wheel: Audi new car tire warranty (36-month term from vehicle handover to the first customer)
- Wheel: Tire pressure monitoring system (monitors the set air pressure and temperature of the wheels while driving, even with factory-fitted winter wheels. - Air pressures and temperatures of individual wheels can be displayed in the Audi virtual cockpit)
- Wheel: Spare wheel, space-saving
- Wheel: Winter alloy wheels, 10-spoke design (7.5 J x 17 with tires 225/60 R17)
- Seats: 4-way lumbar support (electrically adjustable, horizontally and vertically)
- Telephone: Preparation for smartphone interface (Preparation for subsequent booking of the smartphone interface via Functions on Demand.)
- Glazing: Sun protection glazing, tinted (rear window, rear door and side windows tinted)

## Brief expert findings

| | |
|---|---|
| Documents submitted | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection. |
| Inspection | A proper visual inspection of the paintwork and bodywork was only possible to a limited extent due to insufficient lighting conditions/dampness or dirt.<br>No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent. |
| Test drive | No test drive/shunting maneuver was carried out during the inspection of the vehicle. |
| Engine function test | An engine test run was performed. |

## Value reducing factors

| No. | Component group | Description |
|---|---|---|
| 1 | Misc. | Main inspection - No evidence - No deduction |
| 2 | Instrument panel | Indicator light (Reifendruck) - on - Perform diagnosis |
| 3 | Roof | Roof rail - right side - Scratch(es) - Smart repair |
| 4 | Bonnet | Bonnet - Dent / paintcoat damage - Paint |
| 5 | Front bumper | Front bumper - Scratch(es) - repair according to calculation |
| 6 | Vehicle glazing | Windscreen - Stone chips - repair according to calculation |

## Wear and tear

| No. | Component group | Description |
|---|---|---|
| 1 | Misc. | Main inspection - No evidence - No deduction |
| 2 | Rear bumper | Rear bumper - Scratch(es) - No deduction |
| 3 | Side panel - rear right side | Sill - Scratch(es) - No deduction |
| 4 | Roof | Roof - Scratch(es) - No deduction |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  *(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  *(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.




**Figure 1:** Diagonal front (left)




**Figure 2:** Diagonal front (right)




**Figure 3:** Diagonal rear (left)




**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear




**Figure 7:** Instrument cluster




**Figure 8:** Instrument cluster



**Figure 9:** Instrument panel



**Figure 10:** Interior 360° view



**Figure 11:** Cargo area




**Figure 12:** VIN



**Figure 13:** Mounted tyres



**Figure 14:** Documents





**Figure 15:** Documents





**Figure 16:** Documents




**Figure 17:** Documents





**Figure 18:** Documents



**Figure 19:** Additional tyres




**Figure 20:** Navigation



**Figure 21:** Misc.




**Figure 22:** Misc.




**Figure 23:** Misc.




**Figure 24:** Misc.



**Figure 25:** Misc.




**Figure 26:** Misc.



**Figure 27:** Misc.



**Figure 28:** Misc.



**Figure 29:** Misc.



**Figure 30:** Misc.



**Figure 31:** Misc.



**Figure 32:** Misc.




**Figure 33:** Misc.





**Damage 2:** Instrument panel: Indicator light (Reifendruck) - on - Perform diagnosis




**Damage 3:** Roof: Roof rail - right side - Scratch(es) - Smart repair




**Damage 3:** Roof: Roof rail - right side - Scratch(es) - Smart repair



**Damage 4:** Bonnet: Bonnet - Dent / paintcoat damage - Paint



**Damage 4:** Bonnet: Bonnet - Dent / paintcoat damage - Paint



**Damage 4:** Bonnet: Bonnet - Dent / paintcoat damage - Paint




**Damage 4:** Bonnet: Bonnet - Dent / paintcoat damage - Paint



**Damage 4:** Bonnet: Bonnet - Dent / paintcoat damage - Paint



**Damage 4:** Bonnet: Bonnet - Dent / paintcoat damage - Paint



**Damage 5:** Front bumper: Front bumper - Scratch(es) - repair according to calculation



**Damage 5:** Front bumper: Front bumper - Scratch(es) - repair according to calculation



**Damage 5:** Front bumper: Front bumper - Scratch(es) - repair according to calculation



**Damage 5:** Front bumper: Front bumper - Scratch(es) - repair according to calculation



**Damage 5:** Front bumper: Front bumper - Scratch(es) - repair according to calculation



**Damage 5:** Front bumper: Front bumper - Scratch(es) - repair according to calculation



**Damage 6:** Vehicle glazing: Windscreen - Stone chips - repair according to calculation



**Damage 6:** Vehicle glazing: Windscreen - Stone chips - repair according to calculation