BMW X2

Vehicle information

Brand:	**BMW**	License plate:	**2CQE224**
Gearbox:		Body color:	
Model:	**X2**	LEVEL:	**WBAYN910905V72854**
Fuel type:		Power:	**92 kW**
Version:	**1.5 XDRIVE25E PHEV 162KW)**	First registration	**14/10/2022**
Mileage:	**90463 km**	Number of doors:	

Summary of damages

Back	1
RIGHT	5
LEFT	4
Interior	2
Roof & other	1

Commercial photos

































Equipment corresponding to the VIN according to the manufacturer's information

Center armrest	Airbag	Alarm	Rain sensor
Distance control	Battery current	Power steering	Electrical operation of windows
GPS	Alloy wheels	Electrically adjustable mirrors	Adjustable lumbar support
Phone	Central locking	Leather steering wheel	Multifunction steering wheel
Sports steering wheel			

Options according to the inspector

GPS	**Yes**

Damages

Left rear wing
repaired,
acceptable
condition.



Front right wing
repaired,
acceptable
condition.




Fast charging cable
missing
- Replace
rear



Bodywork
Damaged -
Acceptable.
Roof & other















Dirty **Interior**


- Clean

Interior










Interior - Acceptable
Wear and Tear









Alloy wheel, right rear, scratch
(es)
, left front - Repair and paint (complete),
right side








Alloy wheel, **left-hand side.**
Acceptable
.




Alloy wheel AVD
Scratch(es)
LI - Repair and paint (complete)
Right







Broken **front left door seal**
-
Replace




Right rear door
repaired,
acceptable
condition.




Porte ARG
Réparé
Acceptable
Gauche



Porte AVD
Réparé
Acceptable
Droite



Pneus

Avant Gauche

Eté

225/55/17/97/W

Goodyear

2,0 mm

Avant Droite

Eté

225/55/17/97/W

Goodyear

2,0 mm

Arrière Gauche

Eté

225/55/17/97/W

Goodyear

5,0 mm

Arrière Droite

Eté

225/55/17/97/W

Goodyear

5,0 mm

Contrôles

Catégorie	**Vehicule particulier**	Certificat d'immatriculation partie domicile	**Oui**
Certificat d'immatriculation partie véhicule	**Oui**	Certificat de Conformité	**Oui**
Compresseur	**P/A**	Kit réparation	**P/A**
Nbr cable de charge (220V)	**1**	Nbr cable de charge (charge rapide)	**0**
Nbre clés total	**2**	Niveau de charge	**10**
Réinitialisation des paramètres d'usine	**Non, ce n’est pas possible**	Runflat	**P/A**
Type de carnet d'entretien	**Entretien digital**		

Détails du NIV

ABS (antiblocage des freins)	Accoudoir central arrière avec 2 porte-boissons	Accoudoir central AV
Actionnement automatique du hayon	Active Guard	Affichage de la pression de gonflage
Airbag conducteur	Airbag passager	Airbags tête avant et arrière
Antidémarrage électronique (EWS III)	Assistant de détection de somnolence	Attention Assist
Avertisseur acoustique pour piétons	Bac de rangement à gauche/droite du coffre	Batterie haute tension garantie 6 ans 100.000 km
BMW TeleServices	Boulons antivol	Bouton start/stop
Brake Energy Regeneration	Câble de charge rapide+câble standard	Calandre décorative+barreaux Schwarz hochglänz.
Caméra de recul	CBC (cornering brake control)	Climatisation à réglage électronique 2 zones
Climatiseur indépendant	Colonne de direction réglable en hauteur et en longueur	Combiné d'instruments Black Panel écran coul.2.7''
Compartiment sous le fond du coffre	Connected eDrives Services	ConnectedDrive Services (BMW Online) via SIM
Connexion USB	Control Display avec écran couleur 6.5''	Cruise Control avec fonction freinage
DAB-tuner	DBC (contrôle dynamique de freinage)	Démarrage sans clé
Désactivation airbag passager	Deux sorties échappement gauche/droite chromées	Direction assistée
Dossier arrière rabattable 40:20:40	Driving Experience Control incl. ECO PRO	DSC - Contrôle dynamique de la stabilité
DTC (Contrôle Dynamique de Traction)	Extension de garantie BMW jusqu'à 3 ans	Feux arrière en LED avec iconic design 3D
Feux stop adaptatifs	Filet au dos des sièges avant	Filet multi-usage
Filtre à particules Otto (OPF)	Fixation Isofix sièges enfants AR	Fonction Auto start/stop
Frein de stationnement électrique avec Autohold	Gicleurs de lave-glace chauffants	GPS Plus 8.8'' Head-Up alarm (if Business Pack)
Head-Up Display	iDrive with 8 programmable shortcut keys	iDrive Controller on center console
Inserts Oxidesilber dark matt+Schwarz high-gloss	Intelligent Emergency Call - eCall	Grid fabric interior
Central locking switch	JAV double spokes 564 7.5Jx17''+225/55	Bluetooth hands-free kit with USB connection
Mirror kit: electrically folding mirrors + anti-glare control.	Safety kit (triangle, first-aid kit, fire extinguisher, jacket)	LED Headlight with extended functions
Electric windows in the rear	Electric windows in the front	Dutch ship's literature
BMW logo on the C-pillars	Media: Pro.color radio 6.5''+6HP+USB+AUX+Bluet.	On-board computer
Park Distance Control (PDC) at the rear	Front and rear Park Distance Control (PDC)	Metallic paint
Solid color paint Black	Performance Control	Personal Profile
Cup holder in the center console (2)	12V socket in the rear center console	Power outlet (12V) in luggage compartment
Power outlet in the center console	Headlight reminder	Auto-dimming interior rearview mirror.
Electric and heated exterior mirrors	Electrically folding exterior mirrors	Retaining strap on the side wall of the trunk
Rain sensor and light sensor	Servotronic	Stainless steel trunk loading sill
Shift Point Display	Lumbar support for driver and passenger	Speed Limit Assist
Speed Limit Info	Alarm system with remote control	Navigation Plus system with Head-Up Display
Velvet carpeting at the front and rear	Third stop light	Central locking with remote control
German language version	Dutch language version	Heat-insulating windows tinted green
Leather steering wheel	Multifunction steering wheel	Sports steering wheel

Information on the content and scope of the inspection report:

- The evaluation is based on the sales standards specified by the client.
- Acceptable wear and tear according to sales standards is not always documented in this condition report.
- The specified repair methods and/or resulting repair times were determined taking into account modern industrial repair methods.
- The reseller must assess individual repair costs.
- The inspection was carried out without dismantling. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.