TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48257266
Order No. / Reference: 27188983
Inspection date: 22 Oct 2026

Manufacturer: Volkswagen	Model: Caravelle T6.1 Lang Comfortline
VIN: WV2ZZZ7HZMH130463	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Caravelle T6.1 Lang Comfortline	
Vehicle Identification number	WV2ZZZ7HZMH130463
Mileage (Read)	71,516 km
First registration	17 Aug 2021
Number of holders	1
Next periodical technical inspection	08/2026
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Pure Grey
Doors / Seats	4 / 8
Upholstery type	Artificial leather
Colour of upholstery	Grey

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	
Last service on / at	12/2025 at 61,933 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GC379250
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / BTX 31123		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,080 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 106T	All-season tyres on Steel rim with wheel cover	Continental	6mm / 6mm
2)	215/65 R16 106T	All-season tyres on Steel rim with wheel cover	Continental	6mm / 6mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage and stowage boxes
- Airbag: Side and curtain airbags including center airbag
- Exterior mirrors, left and right convex
- Reinforced battery (70 Ah/ 420 A)
- Side turn signals
- third brake light
- Tachometer
- Chassis: 16" chassis with 16" brake system
- Window in passenger/cargo compartment: rear left window, fixed
- Electric windows, front
- Transmission: 6-speed transmission
- Tailgate with window cutout
- Tailgate closing mechanism with unlocking function from inside
- Child safety lock, electrically operated
- Air conditioning in the driver's cab with electronic control
- Headrests: Whiplash headrests, height-adjustable at the front, height- and tilt-adjustable at the rear (7)
- Multifunction display "Plus" with fatigue detection
- Non-smoking version
- "Composition Audio" radio with TFT display (monochrome)
- Wheels/Tires: Tire pressure monitoring system
- Wheels/Tire Accessories: Wheel covers for 16" wheels
- Sliding door in the passenger/cargo area: Without sliding door on the left, in the cargo/passenger area
- Keys for locking system: 2 remote control flip keys
- electromechanical power steering
- dimmable interior safety mirror
- Seats in the 3rd row: 3-seater bench, foldable and rollable
- Seat configuration - 3. Seat settings: Height adjustment for left and right single seat in the driver's cab
- Seat configuration - 5. Armrests: Armrests for both seats in the driver's cab
- Start-stop system
- Power outlets: 2 12-volt sockets in the dashboard
- Daytime running light
- Inside step, in the driver's cab and passenger compartment
- Lashing eyes for securing cargo
- Green thermal insulation glazing
- Approval with up to 9 seats
- Airbag for driver and front passenger
- Electrically adjustable and heated exterior mirrors
- Exterior mirror housings and door handles in body color
- Hill Start Assist
- Floor coverings: Carpet in the driver's cab
- Three-phase generator 180 A
- Electronic Stability Program
- Chassis: Suspension and damping, standard
- Window: Side window in the passenger/cargo compartment, rear right, permanently installed
- Total weight: Permissible total weight 3080 kg
- Rear window with heat-insulating glazing, heated, and rear window wiper/washer system
- Interior lighting with LED technology in the cargo/passenger compartment
- ISOFIX and Top Tether child seat anchorages in the 2nd row of seats
- Fuel-powered auxiliary heater
- Paint finish: Solid
- Multi-collision brake
- Particulate filter: Soot particle filter for diesel engines
- Radio accessories: Digital radio reception DAB+
- Wheels/Tires: Steel wheels 6.5 J x 16 in 20-hole design
- Wheels: Tire Mobility Set
- Sliding door in the passenger/cargo compartment: sliding door on the right
- Crosswind assist
- Seat belts: Three-point automatic seat belts
- Seats 2nd row: 2-seater bench on the left, folding backrest with armrest on the aisle side
- Seat configuration - 4. Lumbar support: Lumbar support, left and right, manually adjustable for individual use.
- Sunshades on the side windows in the passenger compartment
- Power outlets: 12-volt socket(s)
- Bumpers in body color
- Telephone: Mobile phone interface
- Underride guard
- First aid kit, warning triangle and high-visibility vest
- Electronic immobilizer
- Central locking with remote control and interior operation

Extra equipment

- Floor coverings, rubber flooring in the driver's cab and passenger compartment (including loading sill protection, rear)
- Headrests: Whiplash headrests with synthetic leather cover, front and rear, height adjustable
- Loading sill protector (inside) in plastic and loading sill protector on the bumper in black
- Wheels/Tires: 4 all-season tires 215/65 R 16 C 106/104 T, optimized for rolling resistance
- Seat configuration - 3. Seat settings: Height adjustment for the left single seat in the driver's cab
- Floor coverings: 2 rubber floor mats in titanium black
- Braking systems: Electronic Stability Program, ABS, ASR (with deactivation button), EDS (Hill Start Assist, Brake Assist)
- Fuel tank with 80 l tank capacity
- ParkPilot in the front and rear areas
- Upholstery: Faux leather (seat covers in faux leather, "Mesh" design)
- Seats 1st row: Double passenger seat on the right (with lockable compartment in the seat base)
- Seat configuration - 4. Lumbar support: Lumbar support (manually adjustable) for single seat in the driver's cab, left.

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Boot lid / rear door	Boot lid (Zuziehhilfe) - Missing - Replace
2	Side panel - rear left side	Side panel - dent(s) - Smooth repair work
3	Misc.	Main inspection - Due - Perform
4	Rear bumper	Rear bumper - Scratch(es) - Paint
5	Door - front right side	Door - Dent / paintcoat damage - Repair and paint
6	Bonnet	Bonnet - Corrosion - Repair and paint

Missing parts

Description
Documents - Log book
Equipment - Tirefit complete

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Servicerestlauf nicht anzeigbar

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Misc.




Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Damage 1: Boot lid / rear door: Boot lid (Zuziehhilfe) - Missing - Replace



Damage 2: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 2: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 3: Misc.: Main inspection - Due - Perform



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 5: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 5: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 5: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 5: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 6: Bonnet: Bonnet - Corrosion - Repair and paint



Damage 6: Bonnet: Bonnet - Corrosion - Repair and paint



Damage 6: Bonnet: Bonnet - Corrosion - Repair and paint