ARVAL
BNP PARIBAS GROUP

2DJN197

INSPECTION REPORT

End of contract

GENERAL INFO

File	325370
License plate	2DJN197
Vehicle identification number	VF3MRHNSUPS041801
Dossier	2022 364 126
Make	Peugeot 5008 1.2PTech 96kW Act
Mileage	84996
First registration	30/03/2023
client availability date	16/10/2026
inspectionDate	20/10/2026










CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	




2-DJN-197
KEURING
BELCAR

DAMAGES

Damages	Type	Acceptable
92	Rocker Panel Left // Painting	N
102	Door Rear Left // Smart Repair Large	N
134	Bumper Rear // Repair & Painting	N
146	Back Side / Reflector L / Replace	N
222	Side View Mirror Right // Painting	N
228	Side View Mirror Right / Direction Indicator / Replace	N
18	Bumper Front / Spoiler / Replace	Y
196	Door Rear Right // Polish	Y
201	Rocker Panel Right // Smart Repair Medium	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
631	Rear Left Door Interior Coating // Repair	Y
634	Rear Left Door Interior Coating // Replace Completely	Y
860	Interior Cleaning // Small	N

Damage Pictures





Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Rocker Panel Right // Smart Repair Medium-dent




Door Rear Right // Polish-scratch






Bumper Front / Spoiler / Replace-scratch




Rear Left Door Interior Coating // Repair-scratch

Rear Left Door Interior Coating // Replace Completely-scratch





Interior Cleaning // Small-stain






Door Rear Left // Smart Repair Large-scratch + dent





Rocker Panel Left // Painting-scratch + dent




Back Side / Reflector L / Replace-bad position





Bumper Rear // Repair & Painting-dent




Side View Mirror Right // Painting-scratch




Side View Mirror Right / Direction Indicator / Replace-scratch