DEKRA

DEKRA Automotive Solutions


Condition Report

Vehicle details

VIN	VSSZZZKJ1 SR515982	Mileage	72 324 km	Engine (Fuel) Type	Petrol
Licence Plate	2GEE934	Registration date	13/11/2024	Engine size	999
Brand	SEAT	Fuel level	-	Transmission	Automatic
Model	Arona-2017	Car type	PC	Gears	-
Body Type	SUV CrossOver	Number of seats	-	Condition of the car	Unknown
Doors	5	Exterior Color	Blanc		

Inspection Details

Inspection date	28/10/2026	Inspection loc.	AVIS Own Risk - Parc AVIS	Fleet owner	AVIS Own Risk Belgique




Other technical information

Spare wheel kit	✔
Rear parcel shelf	✔

Tyres

Goodyear 205/55/17 V Summer 3.0 mm

Goodyear 205/55/17 V Summer 3.0 mm






Goodyear 205/55/17 V Summer 5.0 mm

Goodyear 205/55/17 V Summer 5.0 mm

Damages

1



Part	Service
Position	-
Damages	Missing
Severity	-
Repair mode	Replace
Net cost (Excluding VAT)	100.00€

motor lampje

2



Part	Fabric seat
Position	Front left
Damages	Burnt
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	136.00€

x2, ovb

3



Part	Spoiler
Position	Front
Damages	Broken
Severity	-
Repair mode	Replace
Net cost (Excluding VAT)	192.71€

4



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	90.00€

DEKRA

DEKRA Automotive Solutions

Condition Report

5



Part	Alloy wheel 17"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Smart Repair
Net cost (Excluding VAT)	165.00€

6



Part	Fabric seat
Position	Front right
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning
Net cost (Excluding VAT)	-

7



Part	Tailgate / Boot door
Position	Back
Damages	Dented
Severity	-
Repair mode	For info
Net cost (Excluding VAT)	-

x2

8



Part	Bumper
Position	Back
Damages	Stone impact
Severity	-
Repair mode	For info
Net cost (Excluding VAT)	-

Summary Inspection

Net Price (Exclusing VAT)	683.71€