TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48536920
Order No. / Reference: 27258690
Inspection date: 4 Nov 2026

Manufacturer: Ford	Model: Transit Custom 300 L1H2 LKW VA Trend
VIN: WF0YXXTTGYMK34042	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Transit Custom 300 L1H2 LKW VA Trend	
Vehicle Identification number	WF0YXXTTGYMK34042
Mileage (Read)	42,694 km
First registration	6 May 2022
Number of holders	1
Next periodical technical inspection	05/2028
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,995 ccm / 4
Power	125 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Polar-Silber Metallic
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	40,000 km
Last service on / at	08/2026 at 42,509 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GH384106
Previous damage / Accident	None detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8566 / BMV 05915		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,200 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 109T	Winter tyres on Steel rim with wheel cover	Michelin	5mm / 5mm
2)	215/65 R16 109T	Winter tyres on Steel rim with wheel cover	Goodyear	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	215/65 R16 109T	All-season tyres on Steel	Goodyear	8 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 1 battery
- Anti-lock braking system with electronic brake force distribution (EBD)
- roof, high
- Double-leaf rear door with 180° opening angle (without window)
- Electronic Stability Program (ESP) with Traction Control System (TCS)
- FordPass Connect
- Generator, 240 A
- Cruise control including imitation leather steering wheel
- Lockable glove compartment with lid
- Front air conditioning
- Cargo area lighting with activatable switch-off delay
- Emergency brake assist including emergency brake light
- Front and rear parking pilot system including fog lights
- Wheel trims
- Headlights: Halogen projector headlights
- Sliding door: Sliding door, right
- Mud flaps front and rear
- Half-height side wall cladding
- Seat belts
- Start-stop system
- Power outlet: 12-volt connection
- Immobiliser
- Central locking with remote control
- Driver's side airbag
- Exterior mirrors, electrically adjustable and heated
- On-board computer
- Headliner in driver's cab
- Tachometer
- Third brake light
- Front electric windows
- Ford Easy Fuel
- Warranty: 2-year Ford new car warranty including Ford Assistance mobility guarantee
- Transmission: 6-speed transmission
- Interior lighting with delay circuit
- Fuel tank 70 l
- Steering column, adjustable in height and reach
- Package: Style-Color Package
- Particulate filter: diesel particulate filter
- Wheels/Tires: Spare wheel, steel wheel
- Sliding door entry light automatically illuminates when the door is opened
- Side protection strips
- Power steering
- Seats: Seat package 13 - partition (load-through flap), without window (Custom Truck Trend)
- Lashing eyes 8
- Heat-insulating glazing, lightly tinted
- Auxiliary heater, electric

Extra equipment

- Battery: AGM deep-cycle high-performance battery (2 batteries (80 Ah), deep dischargeable - standard battery is replaced by AGM)
- Radio: Audio System 24: Ford audio system including Ford SYNC 3 with AppLink, DAB/DAB+, navigation system. (Radio (FM/AM) 8" touchscreen multifunction display (20.32 cm), 4 speakers, FordPass Connect Wi-Fi hotspot, integrated control panel and audio remote control on the steering wheel, Ford SYNC 3 with touchscreen (hands-free system with voice control, SMS readout/sending function, Bluetooth, Emergency Assistance...), AppLink (advanced voice control, privacy mode, Android Auto and Apple CarPlay support, capacitive touchscreen technology,...), dynamic navigation, lane guidance, road map for Western Europe)
- Airbag (passenger side)
- Cargo area floor: Vinyl floor covering omitted
- HACCP floor + cooling
- LED lights in the cargo area
- Paint finish: Metallic
- Reversing camera (reversing camera with image transmission of the rear driving path in the multifunction display and coupling aid)
- Tire Pressure Monitoring System (TPMS)
- Towing device (fixed, 13-pin socket - incl. trailer stability control (TSC))
- Voltage converter (230 V/150 Watt (socket))
- Wheels: All-season tires (suitable for winter use)

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Boot lid / rear door	Rear door - left side - dent(s) - Smooth repair work
2	Electronic systems	Rear view camera - Electrical fault - Perform diagnosis
3	Body	B-pillar - right side - Scratch(es) - Smart repair
4	Body	B-pillar - left side - Scratch(es) - Smart repair
5	Boot lid / rear door	Rear door - right side - Dent / paintcoat damage - Smart repair
6	Door - front right side	Door (teilweise) - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Door - front right side	Brightware - lower - Scratch(es) - No deduction
2	Sliding door, right	Brightware - Scratch(es) - No deduction
3	Roof	Roof - dent(s) - No deduction
4	Side panel - rear left side	Side panel - Scratch(es) - Cover / polish
5	Door - front left side	Door edge - Scratch(es) - Cover / polish

The vehicle shows signs of wear and tear commensurate with its age and use.

Repainting

No.	Repainting
1	Side panel - rear left side, Side panel - rear right side

Paint coat thickness measurement

Side panel - rear left side	175 µm	Side panel - rear right side	301 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Instrument cluster



Figure 7: Instrument panel

Figure 8: Interior 360° view (Online Link)



Figure 9: Cargo area




Figure 10: VIN



Figure 11: Mounted tyres




Figure 12: Documents




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Damage 1: Boot lid / rear door: Rear door - left side - dent(s) - Smooth repair work



Damage 1: Boot lid / rear door: Rear door - left side - dent(s) - Smooth repair work



Damage 2: Electronic systems: Rear view camera - Electrical fault - Perform diagnosis




Damage 2: Electronic systems: Rear view camera - Electrical fault - Perform diagnosis



Damage 3: Body: B-pillar - right side - Scratch(es) - Smart repair




Damage 3: Body: B-pillar - right side - Scratch(es) - Smart repair



Damage 4: Body: B-pillar - left side - Scratch(es) - Smart repair



Damage 4: Body: B-pillar - left side - Scratch(es) - Smart repair



Damage 5: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Smart repair



Damage 5: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Smart repair



Damage 5: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Smart repair



Damage 5: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Smart repair



Damage 6: Door - front right side: Door (teilweise) - Dent / paintcoat damage - Repair and paint



Damage 6: Door - front right side: Door (teilweise) - Dent / paintcoat damage - Repair and paint



Damage 6: Door - front right side: Door (teilweise) - Dent / paintcoat damage - Repair and paint



Damage 6: Door - front right side: Door (teilweise) - Dent / paintcoat damage - Repair and paint



Damage 6: Door - front right side: Door (teilweise) - Dent / paintcoat damage - Repair and paint



Wear and tear 1: Door - front right side: Brightware - lower - Scratch(es) - No deduction



Wear and tear 1: Door - front right side: Brightware - lower - Scratch(es) - No deduction




Wear and tear 2: Sliding door, right: Brightware - Scratch(es) - No deduction




Wear and tear 2: Sliding door, right: Brightware - Scratch(es) - No deduction




Wear and tear 3: Roof: Roof - dent(s) - No deduction



Wear and tear 3: Roof: Roof - dent(s) - No deduction



Wear and tear 4: Side panel - rear left side: Side panel - Scratch(es) - Cover / polish



Wear and tear 4: Side panel - rear left side: Side panel - Scratch(es) - Cover / polish



Wear and tear 4: Side panel - rear left side: Side panel - Scratch(es) - Cover / polish



Wear and tear 5: Door - front left side: Door edge - Scratch(es) - Cover / polish



Wear and tear 5: Door - front left side: Door edge - Scratch(es) - Cover / polish



Repainting 1: Side panel - rear left side, Side panel - rear right side



Repainting 1: Side panel - rear left side, Side panel - rear right side



Repainting 1: Side panel - rear left side, Side panel - rear right side



Repainting 1: Side panel - rear left side, Side panel - rear right side