BMW

VIN: WBA11BL0X0CJ09439



Description

Registration number 2BCV059	**First registration date** 05/10/2021	**Odometer** 145150 km
Color 475 Saphirschwarz	**Model year** -	**Upholstery** -
Number of doors 4	**Number of seats** -	**Generation** -
Engine displacement 1995	**Max power** 110 KW	

Statement details



Inspection loc PARC HÖDLMAYR TONGEREN	**Statement date** 21/10/2026	**Inspection approval date** 22/10/2026

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction
001	Personal Data / -	Non Compliant	Carry out
	 		
002	Rim / Front Right Material : Aluminium alloy / Rim/Tyre diameter : 17 " / Surface : Painted	Scratched	Repair

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.





003	Windscreen / -	Sticker	Removal



004	Door / Front Left	Scratched	Acceptable





005	Wing / Back Left	Dent	Acceptable



006	Bumper / Back Painted : Yes	Scratched	Painting




007	Wing / Back Right	Dent	Repair





008	Door handles / Front Right	Scratched	Acceptable

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



009	Bumper / Front Painted : Yes	Dent	Repair







010	Rear (wing) lamp glass / Back Right [1]	Non Compliant	Check





[1] Controle op schade, niet zeker of dit origineel is Andere kant is zo niet

Loose Items

- [x] Triangle
- [x] Conformity certificate
- [x] Towing hook
- [x] First aid kit
- [x] Registration certificate
- [x] Safety vest
- [x] Registration certificate owner
- [x] Spare Key

Main set of tyres


Front Left	VREDESTEIN	225/55/17 Winter	4 mm
Front Right	VREDESTEIN	225/55/17 Winter	4 mm
Back Left	VREDESTEIN	225/55/17 Winter	4 mm
Back Right	VREDESTEIN	225/55/17 Winter	4 mm

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Comments

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left


Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat



Front passenger compartment


Front right


Odometer


Navigation


Spare Tyre




Vin


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Other




Other




Other



Other



Personal Data / - / Non Compliant



Personal Data / - / Non Compliant



Rim / Front Right / Scratched



Rim / Front Right / Scratched



Rim / Front Right / Scratched



Windscreen / - / Sticker



Door / Front Left / Scratched




Wing / Back Left / Dent



Bumper / Back / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Bumper / Back / Scratched



Bumper / Back / Scratched



Wing / Back Right / Dent



Wing / Back Right / Dent



Wing / Back Right / Dent



Door handles / Front Right / Scratched



Bumper / Front / Dent




Bumper / Front / Dent




Bumper / Front / Dent



Bumper / Front / Dent



Bumper / Front / Dent



Rear (wing) lamp glass / Back Right / Non Compliant



Rear (wing) lamp glass / Back Right / Non Compliant



Rear (wing) lamp glass / Back Right / Non Compliant

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.