TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48414368
Order No. / Reference: 27182097
Inspection date: 28 Oct 2026

Manufacturer: Ford	Model: Transit 350 L3H2 Lkw VA Trend
VIN: WF0EXXTTRENT86269	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Transit 350 L3H2 Lkw VA Trend	
Vehicle Identification number	WF0EXXTTRENT86269
Mileage (Read)	112,486 km
First registration	4 Sept 2022
Number of holders	2
Fuel type	Diesel
Engine displacement / Cylinder	1,995 ccm / 4
Power	125 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Frost-Weiß
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	30,000 km
Last service on / at	12/2025 at 103,147 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GK814657
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8566 / BNI 09193		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,500 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 115R	Winter tyres on Steel rim with wheel cover	Michelin	3mm / 3mm
2)	235/65 R16 115R	Winter tyres on Steel rim with wheel cover	Michelin	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 115R	Summer tyres on Steel	Continental	6mm / 6mm
2)	235/65 R16 115R	Summer tyres on Steel	Continental	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 04/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Driver's side airbag
- Exterior mirrors, electrically adjustable and heated
- Battery: Battery life, programming of battery life to 10 minutes
- Tachometer
- Front electric windows
- Warranty: 2-year Ford new car warranty including Ford Assistance mobility guarantee
- Lockable glove compartment with lid
- Front air conditioning
- Paint finish: Solid color paint
- Steering wheel: Faux leather steering wheel
- MyKey key system
- Emergency call assistant
- Wheels: Wheel trims
- Wheels: Steel wheels 6.5 J x 16 with 235/65 R 16 tires
- Sliding door entry light automatically illuminates when the door is opened
- Rear mud flaps
- Power steering
- Start-stop system
- recirculation mode
- Immobiliser
- Central locking with remote control
- Front overhead storage compartment
- Anti-lock braking system with electronic brake force distribution (EBD) incl.
- On-board computer
- roof, middle
- Third brake light
- Ford Easy Fuel
- Generator, high-performance version
- Transmission: 6-speed transmission
- Interior lighting with delay circuit
- Fuel tank 70 l
- Cargo area lighting
- Steering column, adjustable in height and reach
- Fog light
- Particulate filter: diesel particulate filter
- Wheels: Tire repair kit
- Headlight low beam: Halogen headlights with daytime running lights
- Sliding door: Sliding door, right
- Side protection strips
- Seat belts
- Rear bumper with integrated step
- Lashing eyes
- Heat-insulating glazing, lightly tinted
- Second key with remote control

Extra equipment

- 2 batteries
- Airbag (passenger side)
- Cargo area floor: Vinyl floor covering "Easy Clean"
- Central locking with remote control (also includes a second key, foldable, with remote control)
- Deletion: Digital tachograph (including deletion of the second battery)
- Exterior mirrors, electrically adjustable, heated and foldable
- Navigation system (dynamic and cloud-based navigation with road map for Western Europe - including automatic climate control - Ford audio system with 12" multifunction display and Ford SYNC 4 - Bluetooth, hands-free system with voice control - music playback with voice control - integration of storage media (USB, MP3 player) - FordPass Connect including Wi-Fi hotspot, control of selected functions with the FordPass app - Emergency call assistant - Ford Power-Up - AppLink, Android Auto, Apple CarPlay - touchscreen)
- Partition wall (metal) with window
- Seat covers for driver and passenger side
- Side wall cladding up to the roof
- Voltage converter (230 V (socket))
- Double-wing rear doors with a 256° opening angle, (without windows) (without rear windows, with holding magnets)
- Headlight dipped beam: with static cornering light (supplement to headlight dipped beam)
- Package: Technology Package 10 (Heated windscreen, rain-sensing wipers - Front and rear parking sensors, active emergency braking assist (camera-based) - Lane Keeping Assist with Driver Alert and High Beam Assist; additionally with Lane Departure Warning - Automatic Headlights with Day/Night Sensor - Cruise Control - Rearview Camera with image transmission of the rear view on the multifunction display - LED Downlights - Fog Lights - Ford Audio System with 4" multifunction display)
- Seats: Seat Package 14 (Driver's seat, 4-way adjustable (forward/backward, backrest, seat cushion tilt, height) - Single passenger seat, 4-way adjustable (forward/backward, backrest, seat cushion tilt, height) - Height-adjustable headrests - Heated driver's seat - Heated passenger seat - Interior armrest for driver - Interior armrest for single passenger seat - Manual lumbar support (driver's seat) - Manual lumbar support (passenger seat) - Seat upholstery: fabric)
- Speed limiter 130 km/h (not switchable)
- subsequent installations

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - front left side	Door seal - Missing - Replace
2	Equipment	Tirefit filler - Expired - Replace
3	Side panel - rear right side	Side panel (unterhalb) - Scratch(es) - Paint
4	Side panel - rear left side	Side panel - Dent / paintcoat damage - Repair and paint
5	Sliding door, right	Sliding door - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Wheel / tyres	Tyre - front (3mm) - Does not meet the leasing specifications - No deduction
2	Body	Body - Scratch(es) - No deduction
3	Body	Body - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer, from 20 Feb 2025	4.524,19 €
2	Rear, Side - left, Side right, Provided by user / customer, from 16 Aug 2023	13.361,16 €

Repainting

No.	Repainting
1	Boot lid / rear door, Bonnet, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Boot lid / rear door	310 µm	Bonnet	241 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)




Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.



Damage 1: Door - front left side: Door seal - Missing - Replace



Damage 2: Equipment: Tirefit filler - Expired - Replace




Damage 3: Side panel - rear right side: Side panel (unterhalb) - Scratch(es) - Paint



Damage 3: Side panel - rear right side: Side panel (unterhalb) - Scratch(es) - Paint



Damage 4: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 4: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 4: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 4: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 5: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 5: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 5: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Wear and tear 1: Wheel / tyres: Tyre - front (3mm) - Does not meet the leasing specifications - No deduction



Wear and tear 1: Wheel / tyres: Tyre - front (3mm) - Does not meet the leasing specifications - No deduction



Repainting 1: Boot lid / rear door, Bonnet



Repainting 1: Boot lid / rear door, Bonnet