ARVAL
BNP PARIBAS GROUP

2BTN911

INSPECTION REPORT

End of contract

GENERAL INFO

File	323165
License plate	2BTN911
Vehicle identification number	VF1RFB00368392921
Dossier	2021 130 012
Make	Renault Mégane GT dCi 115 Corp
Mileage	58373
First registration	17/03/2022
client availability date	13/10/2026
inspectionDate	20/10/2026











CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	




B
2-BTN-911

DAMAGES

Damages	Type	Acceptable
134	Bumper Rear // Repair & Painting	N
148	Back Side / Reflector R / Replace	N
186	Wing Rear Right // Polish	Y
187	Wing Rear Right / Trim / Replace	Y
15	Bumper Front // Replace & Painting	N
31	Front Bonnet // Smart Repair Small	Y
66	Wing Front Left // Polish	Y
80	Door Front Left // Smart Repair Small	Y
106	Door Rear Left // Polish	Y
159	Rear Bonnet / Rear Window / Replace	N
161	Roof // Smart Repair Medium	Y
196	Door Rear Right // Polish	Y
210	Door Front Right // Smart Repair Small	Y
544	Interior / Floor Covering / Replace	N
774	Interior / Side Cover rear Seat / Replace	N

Damage Pictures





Door Rear Right // Polish-scratch




Wing Front Left // Polish-scratch




Door Front Left // Smart Repair Small-scratch




Door Rear Left // Polish-scratch






Rear Bonnet / Rear Window / Replace-scratch

Front Bonnet // Smart Repair Small-dent












Bumper Front // Replace & Painting-cracked




Interior / Floor Covering / Replace-tear

Roof // Smart Repair Medium-dent




Door Front Right // Smart Repair Small-scratch




Interior / Side Cover rear Seat / Replace-scratch




Back Side / Reflector R / Replace-dent





Bumper Rear // Repair & Painting-scratch + dent






Wing Rear Right // Polish-scratch




Wing Rear Right / Trim / Replace-scratch